

**TRANS EUROKARS PTE LTD****ESTIMATE COST OF REPAIRS**

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Lien Cheong Jin Gerard LTPI (WIP : 63750 ADDRESS Blk 11 Farrer Park Road #17-11 Singapore 210011 TEL : 97875521		EXCESS : DATE: 2-Mar-20	
VEH NO :	SGA6488Z	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6CW1071F0121966	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG	21-Jul-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB		\$ 961.20
2	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A		\$ 10.80
3	GROMMET, REAR BUMPER	2	MC235-50-ES1		\$ 9.40
4	GROMMET, REAR BUMPER	2	M9991-00-501		\$ 6.00
5	FASTENER, REAR BUMPER	2	MGD7A-50-EA1		\$ 6.40
6	FASTENER, REAR BUMPER	2	MB45A-56-146A		\$ 6.00
7	RIVET, REAR BUMPER	4	MBN8F-50-355		\$ 22.80
TOTAL PARTS					\$ 1,022.60
TOTAL PARTS COST					\$ 1,022.60
Labour Description					
1	MZ-BR-REAR01	TO REPLACE REAR BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 600.00
2	MZ-SP-SREAR1	TO RESPRAY REAR BUMPER.			\$ 630.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.			NETT \$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.			NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 2,510.00
TOTAL PARTS	\$ -	\$ 1,022.60
TOTAL	\$ -	\$ 3,532.60
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING

TRANS EUROKARS PTE LTD

Authorised Signature