



666

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

✉ zoomautowerks@gmail.com

Car Number: SJK8420S

Model : HONDA Fit

Damaged Area: (LH Side Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Date: 18/03/2020

No of Authorized
Labor
4900 /
5 days.**Parts / Material :**

1	Front Bumper		Quantity n/c gram	\$	580.50	X
2	Front Bumper Side Retainer		11	\$	48.10	X
3	Front Bumper Reinforcement		11	\$	354.50	X
4	Front Bumper Lower Spoiler		11	\$	214.30	X
5	Front Bumper Clips		11	\$	60.00	X
6	Front Fender LH	386.60	DO/Bent	\$	496.60	✓
7	Front Fender Inner Shield LH		11	\$	194.30	X
8	Front Fender Inner Shield Clips		11	\$	60.00	X
9	Front Fender Quarter Glass C/W Moulding LH		11	\$	79.20	X
10	Front Fender Lamp LH		11	\$	68.40	X
11	Front Headlamp LH		11	\$	1,159.00	X
12	Front Headlamp Bracket LH		11	\$	93.40	X
13	Front Suspension LH		DO	\$	438.00	X
14	Front Knuckle Arm LH	355.20	Bent	\$	479.00	✓
15	Front Knuckle Hub LH		Bent	\$	214.70	✓
16	Front Hub Bearing	145.50	new	\$	162.20	✓
17	Front Suspension Linkage LH		11	\$	101.10	X
18	Front Lower Arm LH		11	\$	427.90	X
19	Front ABS Sensor LH		11	\$	246.80	X
20	Front Door LH	781.90	DO/Bent	\$	1,210.30	✓
21	Front Door Hinge Top LH		11	\$	109.80	X
22	Front Door Hinge Lower LH		11	\$	106.70	X
23	Front Door Inner Trimboard LH	366.10	DO/cut	\$	797.40	✓
24	Front Door Inner Trimboard Clips	45.00	new	\$	60.00	✓
25	Front Door Power Window Linkage LH		Bent	\$	246.70	✓
26	Front Door Power Window Motor LH	355.20	shock/bent	\$	467.90	✓
27	Front Door Inner Lock Assy LH		11	\$	394.10	X
28	Front Door Weather Strip LH	90.50	new	\$	149.80	✓
29	Front Door Pillar Outer LH		2	\$	946.80	X
30	Wing Mirror Motor Assy LH		11	\$	694.40	X
31	Centre Door Pillar Outer LH		2	\$	926.80	X
32	Rear Door LH	755.20	DO/Bent	\$	1,440.50	✓
33	Rear Door Hinge Top LH		11	\$	117.20	X
34	Rear Door Hinge Lower LH		11	\$	114.40	X
35	Rear Door Inner Trimboard LH		11	\$	784.40	X
36	Rear Door Inner Trimboard Clips		11	\$	60.00	X
37	Rear Door Power Window Linkage LH		11	\$	231.40	X
38	Rear Door Power Window Motor LH		11	\$	463.50	X

- 39 Rear Door Inner Lock Assy LH
40 Rear Door Weather Strip LH 98.50
41 Rocker panel LH
42 Rocker Garnish Clips
43 Rear Fender LH

17	\$	342.20	X
18	\$	178.00	✓
19	\$	382.50	✓
20	\$	60.00	X
21		Repair	X
Parts :		\$	15,762.80
Less Parts 20% :		\$	3,152.56
Total Parts :		\$	12,610.24

Special Net Items :

- Brake Oil
Front Door visor NLS
Rear Door visor NLS
Front Sport Rim LH
Rear Sport Rim LH
Front Tyre LH

22	\$	80.00	X
23	\$	150.00	40
24	\$	150.00	40
25	\$	550.00	300
26	\$	550.00	X
27	\$	210.00	X
Total S/N Parts :		\$	1,690.00

Labour :

- To Remove, Repair & Renew Affected Accident Areas
To Putty, Spray Paint on Affected Accident Areas
To Check & Re-Connect all electrical wiring
To Conduct Wheel Alignment
To Renew, Balance & Replace Front LH Tyre
To Remove & Install Front Door Components LH
To Remove & Install Rear Door Components LH
To Remove & Install Rear Fender Interior Garnish, Seat, Carpets to facilitate Repairs
To Remove & Install Front LH Undercarriage
To Rust Proof Affected Areas

	\$	1,400.00	800
	\$	1,600.00	1080
	\$	50.00	20
	\$	180.00	60
	\$	80.00	X
	\$	180.00	60
	\$	180.00	60
	\$	200.00	80
	\$	250.00	120
	\$	150.00	100
Total Labour :		\$	4,270.00

TOTAL PARTS :	\$	12,610.24
TOTAL SPECIAL NET ITEM :	\$	1,690.00
TOTAL LABOUR :	\$	4,270.00
TOTAL REPAIR COST :	\$	18,570.24

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

P-4231-90
202
P-3385-52
S.N-380.00
L-2380.00
6145.52
4916.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: