

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKG 2088 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To renew lhs 1/4 glass to facilitate fender renewal.	S/N \$ 300.00 ✓	
3	To install 1/4 glass solar film.	S/N \$ 400.00 ✓ X NN	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 3,860.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKG 2088 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dismantle rear bumper, rear lid and lhs sill panel trim. Cut out and weld lhs rear fender. To renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	7,200.00 <i>(5 days)</i> \$ 2500	3000
7	To respray rear bumper, lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	5,500.00 <i>(5.5)</i> \$ 3025	
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00 X	NN
9	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 17,032.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 2088 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>repair</i>	\$ 2,385.00	
2	REAR BUMPER FIXING PARTS <i>7</i> X SVC	\$ 156.00	
3	REAR BUMPER SECURING STRIP <i>7</i> - X SVC	\$ 210.00	
4	TRIM MOLDING <i>X</i> SVC	\$ 958.00	
5	REAR LIGHT REFLECTOR - LH <i>X</i> SVC	\$ 39.00	
6	LED TAIL LIGHT - LH <i>scr</i>	\$ 1,076.00	\$ 860.80
7	TAIL LIGHT TRIM - LH <i>re</i>	\$ 28.00	\$ 22.16
8	REAR BUMPER GUIDE SECTION - LH CRA <i>/</i>	\$ 41.00	\$ 32.80
9	REAR BUMPER GUIDE SECTION - LH / RH <i>X</i> SVC 2	\$ 42.00	
10	SIDE PANEL - LH <i>bt</i>	\$ 2,354.00	\$ 1,883.20
11	SIDE WINDOW - LH <i>re</i>	\$ 676.00	\$ 540.40
12	SILL PANEL ATTACHMENT PARTS <i>re</i>	\$ 123.00	\$ 98.00
13	SILL PANEL ADHESIVE TAPES <i>re</i>	\$ 200.00	\$ 159.60
14	WHEEL HOUSING LINER - LH <i>X</i> SVC	\$ 259.00	
15	WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i> SVC	\$ 86.00	
16	REAR ALUMINIUM RIM - LH <i>X</i> SVC	\$ 964.00	
17	1/4 GLASS SEALANT <i>re</i>	S/N \$ 100.00 <i>/</i>	
18	ACRYLIC SEALANT <i>re</i>	S/N \$ 180.00 <i>/</i>	
19	CAVITY WAX <i>re</i>	S/N \$ 140.00 <i>/</i>	
20	STONE CHIP <i>re</i>	S/N \$ 180.00 <i>/</i>	
21	METAL FILLER POWDER <i>re</i>	S/N \$ 280.00 <i>/</i>	
22	SUNDRIES <i>7</i> , NEC <i>/</i>	\$ 400.00	\$ 11.44

TOTAL SPARE PARTS CHARGES

\$ 10,877.00

TOTAL LABOUR CHARGES

: \$ 17,032.00

GRAND TOTAL

\$ 27,909.00

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.