

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLR 2282C
Vehicle Model : TOYOTA CHR HYBRID
Accident Date : 14.03.2020
Original Reg Date : 03.08.2017

Date : 17.03.2020
Chassis : ZYX102056249
TP Ins. AIG

ESTIMATE

1	1 pc	Tailgate			1,260.10	bt
2	1 pc	Tailgate Emblem Badge			62.70	rec
3	1 pc	Tailgate Emblem Hybrid			59.10	rec
4	1 pc	Tailgate Emblem CHR			59.10	rec
5	1 pc	Tailgate Lamp LH			298.50	x
6	1 pc	Tailgate Lamp Sealer			38.00	x
7	1 set	Tailgate Lamp Clips			25.00	x
8	1 set	Tailgate Inner Trims Clips			40.00	x
9	1 pc	Tailgate Inner Lock		373	448.30	bt
10	1 pc	Tailgate Lock Catch			56.20	x nn
11	1 pc	Tailgate Weatherstrip			321.70	del
12	1 pc	Rear Bumper			916.40	del
13	1 pc	Rear Bumper Lower Skirt		397.60	592.70	cut
14	2 pcs	Rear Bumper Side Retainer	72.10	R+Xnn	44.20	LH-de
15	2 pcs	Rear Bumper Attachment Retainer	56.00	R+Xnn	12.00	LH-de
16	1 set	Rear Bumper Clip			40.00	rec
17	1 pc	Rear Bumper Reflector LH			56.20	x nn
18	1 pc	Rear Bumper Reflector Cover LH			92.70	cut
19	1 pc	Rear Bumper Reinforcement			451.70	bt
20	1 pc	Taillamp LH			521.80	x
21	1 pc	Taillamps Inner Sealer			38.00	x nn
22	1 set	Taillamp Clips			25.00	x
23	1 pc	End Panel			724.10	bt
24	1 pc	End Panel Top Trim		266.60	327.10	de
25	1 set	End Panel Top Trim Clip			30.00	rec
26	1 pc	Rear Key Antena			116.40	3ve
27	1 pc	Rear Fender Wheel Arch Protector LH			237.10	de
28	1 pc	Rear Exhaust Silencer			593.00	del
29	2 pcs	Rear Exhaust Mountings	38.00		76.00	x An
30	1 pc	Rear Exhaust Gasket			46.20	rec
31	1 pc	Rear Exhaust Heat Plate			126.20	bt

7,935.50

Less 25% 1,983.88
C/D 5,951.63

6301.80

25% - 4726.35

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle NO : SLR 2282C

B/F

5,951.63

Special Nett

1	1 set	Body Panel Joint Sealant		120.00	4000
2	1 set	Reverse Sensor	200	250.00	1000
3	1 pc	Rear Number Plate with Holder		50.00	2000
4	1 set	Reverse Camera		450.00	1000

285

Labour charge

Panel Beating	800	1,200.00
Spray painting	800	1,200.00
Check Wiring	30	50.00
Anti rust	30	90.00
Remove and install tailgate parts.	60	90.00
Remove and install rear windscreen.	120	140.00
Remove and install reverse sensor	30	90.00
Remove and install carpet and seat	60	120.00
Remove and install rear camera	60	120.00

1990

9,921.63

Less 20% 1,984.33

Lump sum 7,937.30

4726.35

285

1990

7001.35

4/5\$5600

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 9749 5749

Wp

Lumpsum

Reamy After repair

17/3/2020 800pm

6-7 days

Tanpin @ Montson