

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004204/KBA3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900095547

Claimant
Vehicle No : SMQ2442B **Insured Vehicle No :** SDJ2133L

Date of Loss: 17/03/2020 Nature of Claim: TP Claim No: 3517801413SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ2442B		
Make & Model:	KIA NIRO HYBRID, 1.6 (A)	Engine No:	G4LEKS567872
Reg. Date:	04/11/2019 (Man. Year: 2019)	Chassis No:	KNACB81CVL5341563
Colour:	Metallic Dark Blue	Odometer:	43042 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	649.00	454.30	194.70	30.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	675.27	473.94	201.33	29.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,324.27	928.24	396.03	29.91
Approved Total (Overridden) (S\$)		740.00		
(S\$)	1,324.27	740.00	584.27	44.12
+ GST 7.00/7.00% (S\$)	92.70	51.80	40.90	44.12
Nett Amount (S\$)	1,416.97	791.80	625.17	44.12
+ Car Rental (3.0 x S\$84.95/day) (S\$)		254.85		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,054.10		

INSPECTION

Date of Assignment: 18/03/2020

Date Inspected: 18/03/2020 Inspected At:

Esteem Performance Pte Ltd
5033 Ang Mo Kio Industrial Park 2,
#01-259
Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/R DOOR (NPA)	Repair	0.00 F	*- FL
2	1		*L/R LOWER DOOR HINGE (NPA)	Repair	0.00 F	*- FL
3	1		*L/R LWR DOOR PROTECT	Dented	203.40 F	*203.40 FL
4	1		*L/R STONE PROTECTION	Necessary	50.00 F	*50.00 FL
5	1		*L/R UPPER DOOR HINGE (NPA)	Repair	0.00 F	*- FL
6	1		*L/R UPP WING MLDG	Dented	50.00 F	*50.00 FL
7	1		*L/R WHEELHOUSE COVER	Dented	345.60 F	*345.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	649.00	649.00
- List Item Discount on L Items 0.00/30.00% (\$\$)	0.00	194.70
Total Parts (\$\$)	649.00	454.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	47.0 WU X 50.00 SGD/H	New	235.00	85.00
2	LABOUR COST 66.0 WU X 50.00 SGD/H	New	330.00	300.00
3	MATERIAL COST	New	110.27	88.94
Gross Labour Cost (\$\$)			675.27	473.94

Report was unsubmitted during this print-out.

< END OF ESTIMATES >