

**ESTIMATE TO REPAIR**

VEHICLE NO. : SLU 6579 E  
 MAKE : HONDA  
 MODEL : VEZEL 1.5X CVT  
 YEAR : 2017  
 CHASSIS NO : RU11230301

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 18-Mar-20  
 DATE OF ACCIDENT : 11-Mar-20  
 THIRD PARTY REF : SLK 8853 C  
 THIRD PARTY REF : SOMPO INSURANCE SINGAPORE PTE. LTD.

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$ 463.70
2 pcs	rear bumper retainer		\$ 17.50		\$ 35.00
1 pc	rear end panel				\$ 411.90
1 pc	rear end panel garnish				\$ 92.80
1 pc	tail gate				\$ 1,050.00
1 pc	tail gate rubber				\$ 92.80
1 pc	tail gate lock				\$ 157.00
1 pc	tail gate VEZEL emblem				\$ 43.00
1 pc	rear windscreen moulding				\$ 120.00
1 pc	rear buzzer assy snert				\$ 75.50
	Less 20%				\$ 2,541.70
					\$ 508.34
					\$ 2,033.36
1 pc	rear bumper sensor	S.Nett			\$ 200.00
1 tube	rear windscreen sealant	S.Nett			\$ 40.00
	To putty & spray paint.				\$ 800.00
	To transfer tail gate fitting.				\$ 80.00
	To remove & refix.rear windscreen glass.				\$ 100.00
	To anti-rust.				\$ 80.00
	Labour charges.				\$ 500.00
TG/VL	TOTAL				\$ 3,833.36