



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20004210/Kyd3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 03-11-2020



Code : UOI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKM 7637T
Policy No.	DHOM110161741801	Coverage (\$)	0.00
Claim No.	M11D09372002	Excess (\$)	3,000.00
Assign From	JOSEPHINE WONG	Assign Date	18/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS RX270 (A)	c.c	2672
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTJZA11A602035936	Colour	METALLIC PEARL WHITE
Odometer	266673	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R19	CONTINENTAL	8 mm
L/H Front Tyre	235/55 R19	CONTINENTAL	8 mm
R/H Rear Tyre	235/55 R19	KUMHO	8 mm
L/H Rear Tyre	235/55 R19	KUMHO	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/02/2020	Inspection Date	24/03/2020
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

- A)THE MARKET VALUE IS S\$85,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------