

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III20004211/APA3Q2**Date:** 27/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	GBA8744E	Insured Vehicle No :	SHA2981E
Date of Loss:	17/03/2020	Nature of Claim:	TP
		Claim No:	MCT20030278

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA8744E	Engine No:	FE5236
Make & Model:	ISUZU TFR86HDR, 2.5 D (M)	Chassis No:	MPATFR86H7H586450
Reg. Date:	03/03/2008 (Man. Year: 2007)	Odometer:	206255 km
Colour:	Silver		
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,940.10	1,679.31	4,260.79	71.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	700.00	500.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,140.10	2,379.31	4,760.79	66.68
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	7,140.10	1,900.00	5,240.10	73.39
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,227.45		
Global Sum Settlement (S\$)		2,200.00		

INSPECTION

Date of Assignment:	18/06/2020	F-1 AUTOCLINIC PTE LTD (HQ)
Date Inspected:	18/06/2020 Inspected At:	25 KAKI BUKIT ROAD 4 SYNERGY @ KB, #05-26
Estimated Period of Repair:	3.0 days	Singapore 417800

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Jan 2022)	
Parts:	N/A	ISUZU TFR86HDR 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA8744E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Repair	1,150.00 F	*- FL
2	1		*BOOT LID LOWER PANEL	Repair	325.10 F	*- FL
3	1		*BOOT LID LOGO	Necessary	150.00 FS	*80.00 FS
4	1		*BOOT LID 70KM LOGO	Necessary	25.00 FS	*15.00 FS
5	1		*REAR LOWER STEP PANEL	Repair	256.10 F	*- FL
6	2		*TAIL LAMP -LH	Not Necessary	255.10 F	*- FL
7	2		*REAR BUMPER BRACKET	Bent	230.40 F	*230.40 FL
8	1		*REAR BUMPER	Distorted	1,550.10 F	*1,550.10 FL
9	1		*REAR BUMPER SIDE REFLECTOR	N/S Missing	96.20 F	*48.10 FL
10	1		*REAR FENDER LH	Not Necessary	1,852.10 F	*- FL
11	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,940.10	1,953.60
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	274.29
Total Parts (\$\$)	5,940.10	1,679.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING CHARGES	New	600.00	400.00
Gross Labour Cost (S\$)			1,200.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >