

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
HP: 96583371 TEL: (65) 67022915 FAX: 67022916

Adm
Indm

TAI BEE CONSTRUCTION PTE LTD
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

17th JUNE 2020

TNPATFR86H7HS86450

Accident date: 17th MARCH 2020

Estimated repair costs for vehicle no: 004925J Isuzu TFR86HDR2.5M 2008 (COE TIL MARCH 2023)

S/n	Qty	Items	U/price	Amount
1	1	tail gate		\$1,150.00
2	1	boot lid lower panel	1828.60	\$325.10
3	1	boot lid logo		\$150.00
4	1	Boot lid 70 km logo	1554.31	\$25.00
5	1	rear lower step panel		\$256.10
6	2	tail lamp -LH		\$255.10
7	2	Rear Bumper Bracket	\$115.20	\$230.40
8	1	Rear bumper		\$1,550.10
9	2	Rear Bumper Side Reflector	\$48.10	\$96.20
10	1	rear fender -LH		\$1,852.10
11	1	Rear Number Plate		\$50.00
			Subtotal :-	\$5,940.10

Labour Charges

Panel beating

Spray painting charges

700

Total:-

\$600.00 300

\$600.00 400

\$1,200.00

\$7,140.10

whl 237931

L/S 1-SK

03 Days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: