



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006317
INV Date 14/09/2020
Reference CC4/FCI20004215/Aba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKJ 929M
Insured Veh. SHA 8721A
Claim No. D20001517MFSH
Policy No. D-20094921MFSH
Accident Date 15/03/2020
Inspection Date 19/03/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20004215/Aba3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-09-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8721A	Veh. Inspected	SKJ 929M
Policy No.	D-20094921MFSH	Coverage (\$)	0.00
Claim No.	D20001517MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	19/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	AGH300236378	Colour	WHITE
Odometer	10083	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	TOYO	6 mm
L/H Front Tyre	235/50 R18	TOYO	6 mm
R/H Rear Tyre	235/50 R18	TOYO	6 mm
L/H Rear Tyre	235/50 R18	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/03/2020	Inspection Date	19/03/2020
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 929M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR -RIGHT	DENTED	2,500.00	1,680.40
1	REAR DOOR -RIGHT	DENTED	2,900.00	2,130.70
1	SIDE SKIRT -REAR RIGHT	MISSING	540.00	540.00
	LESS 25% DISCOUNT		-1,485.00	-1,087.78
			4,455.00	3,263.32
	<u>LABOUR</u>			
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA.		1,200.00	700.00
	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.		900.00	400.00
	ANTI RUST TREATMENT.	NOT NECESSARY	120.00	-
			2,220.00	1,100.00
	GRAND TOTAL		6,675.00	4,363.32
	RECOMMENDED COST OF REPAIRS			4,363.32

Report Ref No. CC4/FCI20004215/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKJ 929M

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKJ 929M

RE-INSPECTION

