



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLE9843G	MODEL : LEGACY 2.5I-S AWD CVT
REF NO:INS/IC/CHI/0079/2020	YEAR: 10-AUG-2016
ENGINE NO: FB25Y250796	CHASSIS NO: JF1BN9KC2GG011167
DOA: 04/03/2020	TOA: 2120HRS
TYPE OF CLAIM: OD	INS COMPANY:AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER & FRONT PANEL . 250	\$1000.00 750
2.	RESPRAY FRONT BUMPER & FRONT PANEL 200	\$800.00 400
3.	DISMENTLE & REFIX UNDERCARRAIGE TO FACILITATE REPAIRS ✓	\$684.00
4.	REMOVE & REFIX EXHAUST	\$114.00 ✓
5.	REMOVE & REFIX AIR CON CONDENSER & RADIATOR TO FACILITATE REPAIR	\$171.00 ✓
6.	MECHANICAL REPAIRS- ALTERNATOR,COMPRESSOR,STEERING PUMP	\$171.00 X M
7.	FAULT DIAGNOSTIC	\$235.00 ✓
8.	SUNDRIES	\$100.00 20
9.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$125.00 ✓
10.		
Total Labour		\$3400.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Guo Qiang - 82880282
HP / EMAIL:	82880282 Guo Qiang@lkkauto.com
BEFORE PAINT:	before paint photos.
DAYS GIVEN:	6 Days.

Not Authorised.

19/3/2020

Excess: TBA

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Estimate

Date 03 / 17 / 2020

001 / 002

Name	QUOTATION FOR SLE9843G	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	B15
		Body Model	BN9BK6C
		Vin-Code	JF1BN9KC2GG011167

Part Number	Part Code Name	Part Code	Q'ty	Price
57702AL100	BUMPER FACE-FRONT / CAA	FIG-590 57704	1	594.00
57711AL0119P	BACK BEAM COMPLETE-FRONT X NN	FIG-590 57711	1	342.40
57705AL050	ENERGY ABSORBER-FRONT BUMPER CA CAA	FIG-590 57705	1	57.60
57705AL071	ENERGY ABSORBER-FRONT BUMPER X NN	FIG-590 57705F	1	35.10
57707AL050	BRACKET-BUMPER, FRONT LOWER X NN	FIG-590 57707AE	1	57.60
57735AL010	SEAL-FRONT BUMPER X NN	FIG-590 57735A	1	27.00
57705AL040	ENERGY ABSORBER-UPPER X NN	FIG-590 57705B	1	18.00
57707AL060	BRACKET-FRONT BUMPER CORNER, RI GHT X NN	FIG-590 57707AF	1	32.40
57707AL070	BRACKET-FRONT BUMPER CORNER, LE FT / CC	FIG-590 57707AG	1	32.40
57707AL081	BRACKET-FRONT BUMPER SIDE, RIGH T X	FIG-590 57707F	1	18.00
57707AL091	BRACKET-FRONT BUMPER SIDE, LEFT X	FIG-590 57707G	1	18.00
57731AL270	COVER-FOG LIGHT, RIGHT X	FIG-590 84953N	1	50.40
57731AL280	COVER-FOG LIGHT, LEFT / BR LENS	FIG-590 849530	1	50.40
57731AL180	COVER-INTAKE, FRONT X MISC.	FIG-590 57731M	1	50.40
91121AL010	FRONT GRILLE ASSEMBLY X NN	FIG-911 91121	1	576.00
91165AL012	BRACKET-GRILL X NN	FIG-911 91165J	1	42.20
Page-Total				2,001.90

Memo

Grand Total
8,068.30

Estimate

Date 03 / 17 / 2020

002 / 002

Name	STATION FOR SLE9843G	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	B15
		Body Model	BN9BK6C
		Vin Code	JF1BN9KC2GG011167

Part Number	Part Code Name	Part Code	Qty	Price
93013AL000	ORNAMENT / SCR	FIG-919 91174	1	72.00
86636AL060W6	COVER ASSEMBLY-LAMP WASHER NOZ ZIE, LEFT	FIG-877 866360A	1	54.00
86636AL021	NOZZLE LAMP WASHER, LEFT / MIS	FIG-877 866360	1	90.00
44200AL000	EXHAUST PIPE ASSEMBLY REAR X Repair	FIG-440 44200	1	756.00
44300AL140	MUFFLER ASSEMBLY-LEFT - DD	FIG-440 44300B	1	540.00
44011S0000	GASKET A / Acc.	FIG-440 44011A	1	7.20
44370AL000	TAIL PIPE CUTTER X NN	FIG-440 44371	1	86.40
44620AD840	CONVERTER COMPLETE-FRONT X NN	FIG-440 44110D	1	2,520.00
44620AD900	CONVERTER COMPLETE-FRONT X NN	FIG-440 44110E	1	1,105.20
56410AL050	UNDER COVER-FRONT / MIS	FIG-572 56410	1	162.00
84501AJ060	FOG LIGHT ASSEMBLY-FRONT LH-RH X NN	FIG-845 84501B	2	544.00
53029AL1009P R	FRAME COMPLETE-RADIATOR PANEL, LOWER X	FIG-505 53060	1 R	64.80
53029AL1109P R	FRAME COMPLETE-RADIATOR, LOWER X/DT	FIG-505 51231G	1 R	64.80
	Number plate - SCR	Page-Total		6,066.40
	under cover - X2	Sub-Total		8,068.30
		Total		8,068.30
		Tax		0.00
		Grand Total		8,068.30

Memo

Grand Total
8,068.30

Blank area for additional notes or signatures.

Tel



Motor Image Enterprises Pte Ltd
 19 Loring 8 Tosa Payoh
 Singapore 319755
 Tel (65) 6703 8101/8102
 Fax (65) 6753 5535
 www.motorimage.net
 Co Reg No. 198102937K

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SLE-9843 G

Surveyor: _____

DESCRIPTION	PART NO	AMOUNT
1 UNIT - ABSY. ACTIVE GRILL ✓ BR	S2811A L000	\$ 2475.20
2 Radiator complete ✓ BT	45119AL060	\$ 810.00
3 Hose - radiator inlet / } Part	45161AJ170	\$ 36.00
4 Hose - radiator outlet / }	45161AJ190	\$ 36.00
5 Condenser ASSEMBLY / BT	73210AL000	\$ 756.00
6 Frame complete - cradle - BT	50527AL020	\$ 1080.00
7		
8 LAMP. ASSEMBLY. Y. HEAD. RIGHT ✓ BR	84002AL000	\$ 1,870
9 LAMP. ASSEMBLY. Y. HEAD. LEFT ✓ BR	84002AL010	\$ 1,870
10 CONSOLE ASSEMBLY. Y. HEAD LAMP W/BR / MIS	86636AL060UR6	\$ 54.00
11 HOSE. ASSEMBLY. Y. HEAD LAMP W/BR ✓ BR	86655AL040	\$ 105.00
12 MUD. GUARD. FRONT RIGHT / } TV	59110AL060	\$ 108.00
13 MUD. GUARD FRONT. LEFT / }	59110AL050	\$ 108.00
14 PANEL. COMPLETE RADIATOR / BNC	53029AL12R.P	\$ 601.20

16 Radiator packing / Re x 2

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Eno Rimp
 19/06/2020

Acknowledged by Repairer
 Signature:
 Date:



Motor Image Enterprises Pte L
 19 Lorong 8 Toa Payoh
 Singapore 319255
 Tel (65) 6703 8101/8102
 Fax (65) 6253 5535
 www.motorimage.net
 Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SLE 9843 G

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1 conduct 4-wheel Alignment ✓ \$ 171.00

2 remove & refit wire harness ✓ \$ 228.00

3 _____

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

4 _____

5 _____

Acknowledged by Repairer
 Signature: _____
 Date: _____

6 _____

7 _____

8 _____

9 _____