

REPAIR ESTIMATE*

DATE: 18. Mar. 2020

MODEL : i40

DOA: 17. Mar. 2020

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover <i>Cha</i>			\$1,052.20
1	Front Bumper Side Bracket – LH <i>xun</i>			\$24.60
1	Front Bumper Grille – LH <i>xun</i>			\$93.60
1	Headlamp – LH scr <i>scr cut</i>			\$1,388.00
1	Headlamp Support Panel <i>xun</i>			\$907.40
1	Front Fender – LH <i>x(R)</i>			\$663.00
1	Front Fender Shield – LH <i>xun</i>			\$174.90
1	Front Wheel Cover – LH <i>scr cut</i>			\$107.10
SUB TOTAL				\$4,410.80
LESS 20%				\$882.16
DISCOUNTED TOTAL				\$3,528.64
Labour Charge				
1	Panel Beating			\$600.00
1	Spray Painting Charge			\$500.00
1	Tuff Kote			\$50.00
1	Wiring Charge			\$50.00
1	Front Wheel Alignment			\$80.00
TOTAL LABOUR				\$1,280.00
ESTIMATE TOTAL				\$4,808.64

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Handwritten notes:

29/3/2020

Ram (LKR)

18/03/2020 1315

Rameson@telkomsat.com

826 22778

2nd repair photo

(3 repair keys)

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305388386

STOMER

COMFORT TRANSPORTATION PTE LTD

7010045

/MS

STOMER NO.

DRESS

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R)

(P)

(O)

ACCOUNT CARD NO.

REGN NO.:

SHD3637C

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

17.03.2020 16:40

YR OF MANU

29.09.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU093679

COMPLETION DATE/TIME:

Accident Date: 17.03.2020

NATURE: 3P 17.03.2020

JOB DESCRIPTION

TAKE PHOTOGRAPH
BEFORE / AFTER
SPRAY PAINTING


S/NO

LABOR CODE

DESCRIPTION

CHINA - Left Frnt

LKK/



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.:

SHD3637C

LARRY

Vehicle No.:

SHD3637C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard