



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



| | | | |
|--|----------------------------|---|------------------------|
| INDIA INTERNATIONAL INSURANCE P/L | | NAME : MR. VINCENT TAN SWEE CHIEW | WIP : 34823 |
| 64 CECIL STREET | | ADDRESS : | EXCESS : |
| #04-#05 IOB BUILDING | | | DATE: 18-Mar-20 |
| SINGAPORE 049711 | | | |
| ATTN. : MOTOR CLAIMS | | TEL : 98178610 | |
| FAX : | | | |
| VEH NO : SFG9086K | DATE IN : | CONTACT PERSON : JOBI THOMAS 6331 0682 | |
| CHASSIS NO : WMWXU52080TH94273 | MILEAGE : | TYPE OF CLAIM : THIRD PARTY CLAIM | |
| MODEL : MINI COOPER F55 | DATE REG.: 2-Jul-18 | POLICY NO. : | |

NATURE OF WORKS

| S/NO | Parts Description | | REVISED | PRICES |
|-------------------------|--------------------------|---|---------|-------------|
| | QTY | | | |
| 1 | REAR RIM LH / CM | 1 | | \$ 825.17 |
| 2 | REAR RIM CAP LH / CM | 1 | | \$ 34.38 |
| 3 | REAR DOOR ARCH LH / CM | 1 | | \$ 106.99 |
| 4 | REAR FENDER ARCH LH / CM | 1 | | \$ 142.68 |
| 5 | ARCH CLIP / MC | 8 | | \$ 17.68 |
| TOTAL PARTS | | | | \$ 1,126.90 |
| | | | | \$ - |
| TOTAL PARTS COST | | | | \$ 1,126.90 |

Labour Description

| | | | | |
|---|---|--|------|---------------|
| 1 | TO REPAIR REAR BUMPER, REAR DOOR LH & FRONT DOOR LH AND ALL AREAS AFFECTED BY THE ACCIDENT. 840 | | 1260 | \$ 1,900.00 |
| 2 | TO RESPRAY REAR BUMPER, REAR DOOR LH AND FRONT DOOR LH. 800 | | 2400 | \$ 2,600.00 |
| 3 | TO CARRY-OUT BODY CAVITY PRESERVATION. | | | \$ 250.00 150 |
| 4 | TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING. | | NETT | \$ 120.00 ✓ |
| 5 | TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. | | NETT | \$ 560.00 ✓ |
| 6 | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. | | | \$ 250.00 150 |
| 7 | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. | | | \$ 350.00 250 |
| 8 | SUNDRIES. | | NETT | \$ 50.00 20 |

| | | |
|--------------------|------|-------------|
| TOTAL LABOUR | \$ - | \$ 6,080.00 |
| TOTAL PARTS | \$ - | \$ 1,126.90 |
| TOTAL | \$ - | \$ 7,206.90 |
| LESS EXCESS | \$ - | \$ - |
| TOTAL AFTER EXCESS | \$ - | \$ - |

| | | |
|--------------------|-------------|-------------|
| GST 7% | \$ - | \$ - |
| GRAND TOTAL | \$ - | \$ - |

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

19/3/20, 2:31pm
 Steve with RL
 5 days
 P/P
 My Bol My

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: