

FWD 3



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM: SMG 8662 X
MAKE & MODEL: HONDA FIT
MILEAGE:
TYRE:
CHASSIS NUM: 6C5

Not Ah
her
2/5/2004
SL
19/3/2

ATTN:	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING	1	391.00
	2	REAR TAILGATE	1	1264.00
	3	REAR TAILGATE WIPER ARM	1	266.00
	4	REAR TAILGATE WIPER MOTOR	1	396.00
	5	REAR TAILGATE WIPER MOTOR COVER	1	213.00
	6	REAR TAILGATE CHROME HANDLE	1	451.00
	7	REAR TAILGATE CHROME HANDLE LOGO	1	103.00
	8	REAR TAILGATE CHROME HANDLE LICENSE PLATE LAMP L+R	2	228.00
	9	REAR TAILGATE OPENER	1	361.00
	10	REAR TAILGATE LOCK	1	652.00
	11	REAR TAILGATE INNER TRIM TOP	1	312.00
	12	REAR TAILGATE INNER TRIM BTM	1	596.00
	13	REAR TAILGATE WEATHERSTRIP	1	324.00
	14	REAR TAILGATE LAMP L+R	2	966.00
	15	REAR TAILLAMP	2	1854.00
	16	REAR TAILLAMP PANEL	1	984.00
	17	REAR BUMPER	1	1061.00
	18	REAR BUMPER RETAINER L+R	2	268.00
	19	REAR BUMPER REFLECTOR L+R	2	382.00
	20	REAR BUMPER BRACKET L+R	2	242.00
	21	REAR BUMPER REINFORCEMENT BAR	1	518.00
	22	REAR BUMPER SPONGE	1	302.00
	23	REAR FENDER L+R	2	3638.00
	24	REAR FENDER COWLING L+R	2	424.00
	25	REAR FENDER INNER TRIM BTM L+R	2	2118.00
	26	REAR FENDER INNER TRIM TOP L+R	2	1682.00
	27	REAR END PANEL	1	1229.00
	28	REAR END PANEL TOP GARNISH	1	481.00
	29	REAR FLOOR PANEL	1	1951.00
	30	REAR FLOOR PANEL TOP BOARD	1	781.00
	31	REAR BATTERY	1	26,421.00
	32	REAR BATTERY COVER	1	357.00
	33	REAR BATTERY CASING	1	468.00
	34	REAR BATTERY MOUNTING	1	310.00
	35	REAR EXHAUST PIPE	1	1193.00
	36	REAR EXHAUST MOUNTING	1	104.00
	37	REAR EXHAUST GASKET	1	261.00
	38	REAR EXHAUST HEAT SHIELD	1	322.00

4/5/5000

DESCRIPTION - PARTS

rear

68.50

306500

880.40

11 X

11 X

11 X

11 X

11 X

11 X

11 X

7m

109.40

11 X

De

341.80

7m

148.20

11 X

cre

325 x 2 = 610

2 X

00

548.10

54

35 x 2 = 70

Pa

s. de sponge cre

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

11 X

P: \$11,381.00		SUBTOTAL	\$ -
-20% = \$9104.80		LESS 20%	\$ -
		PARTS TOTAL	\$ -
SPECIAL NETT		QTY	PRICE
1	REAR NUMBER PLATE 17X	1	\$ 120.00 X
2	REVERSE SENSOR Stuck 200	2	\$ 300.00 200
3	REVERSE CAM 17X	1	\$ 1,200.00 X
4	REAR END PANEL SEALANT Re 50	1	\$ 120.00 50
5	SPARE WHEEL PANEL SEALANT 17X	1	\$ 120.00 X
6	REAR BUMPER CLIPS Re 50	10	\$ 120.00 50
7	REAR FENDER COWLING CLIPS 17X	10	\$ 120.00 X
8	REAR FENDER INNER TRIM CLIPS 17X	10	\$ 120.00 X
9	BOOTLID INNER TRIM CLIPS 17X	10	\$ 120.00 X
10	REAR END PANEL TOP GARNISH CLIPS n 17X	10	\$ 120.00 X
s/n = \$300			
SPECIAL NETT TOTAL			\$ 2,460.00
LABOUR		QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN 600	1	\$ 2,500.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 900	1	\$ 2,500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 60	1	\$ 120.00
4	TO RNR REAR WINDSCREEN 120	1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM 60	1	\$ 120.00
6	TO RNR REAR LUGGAGE COMPARTMENT 60	1	\$ 400.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION. 50	1	\$ 300.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS 17X	1	\$ 250.00
9	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION 20	1	\$ 250.00
10	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE. 17X	1	\$ 800.00
11	TO DO WATER LEAK TEST. 17X	1	\$ 120.00
13	TO RNR FUEL TANK TO ASSIST WORK LOAD 17X	1	\$ 120.00
14	TO RNR BATTERY AND PERFORM SAFETY TEST 300	1	\$ 2,500.00
LABOUR TOTAL			\$10,380.00
GRAND TOTAL COST			\$12,840.00
Total: \$11,294.80			
-20% = \$9050			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE 2 OF 2

P-4767-30

20%

P-3813-84

S.W-300.00

L-2190.0

6303.84