

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9788K**AAD2003-092**

Not Notarised
11/10/20

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 MAR 2020

SHD 9788K

VF1ABL15AUC277267

RENAULT

LATITUDE

17.3.2020

AIG

14/04/2014

PART		LIST	
1	DOOR PANEL FRT LH	\$	2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	274.50 X
1	DOOR HINGE LOWER LH	\$	300.55 X
1	DOOR CHECK FRT LH	\$	90.90 X
1	DOOR REGULATOR FRT LH	\$	758.10 ?
1	DOOR REGULATOR MOTOR FRT LH	\$	501.40 ?
1	DOOR REGULATOR GUIDE FRT LH	\$	69.00 X
1	DOOR WHEATHESTRIIP FRT LH	\$	316.00 X
1	DOOR SEAL FRONT LH	\$	69.60
1	DOOR SEAL FRONT LH	\$	63.10
1	DOOR SEAL LOWER FRT LH	\$	93.90
1	DOOR MOULDING FRT LH	\$	100.50
1	DOOR FINISHER FRT LH	\$	258.90
1	DOOR FINISHER CLIP KIT FRT LH	\$	94.00
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	332.00
1	DOOR HANDLE OUTER FRONT LH	\$	169.50
1	DOOR HANDLE CAP FRONT LH	\$	17.30
1	DOOR HANDLE MODULE FRT LH L70Y	\$	133.40
1	DOOR LOCK FRT LH	\$	453.80
1	DOOR MIRROR ASSY LH	\$	727.90
1	DOOR HARNESS WIRE LH	\$	2,670.00
1	ROCKER PANEL INNER GARNISH LH	\$	466.51
1	ROCKER PANEL INNER LH	\$	1,024.79
1	ROCKER PANEL OUTER LH	\$	1,184.99
1	FENDER PANEL FRT LH	\$	414.40
1	WHEELARCH FRT LH	\$	112.30
1	FENDER BRACKET LOWER LH	\$	11.80
1	FENDER INSULATOR LH	\$	65.50

X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9788K**AAD2003-092**

1 FENDER BRACKET FRT LH	\$	38.90	}	X
1 BUMPER COVER FRT	\$	747.20		
1 BUMPER RETAINER FRT LH	\$	101.40		
1 AIR CLEANER BOX	\$	464.20		
1 AIR CLEANER HOSE	\$	175.85		
1 AIR CLEANER LOWER	\$	271.26	}	
1 DOOR PANEL REAR LH	\$	758.70		
1 DOOR GUIDE REAR LH	\$	136.40	}	X
1 DOOR HINGE UPPER REAR LH L70Y	\$	180.70		
1 DOOR HINGE LOWER REAR LH L70Y	\$	169.90		
1 DOOR CHECK REAR LH	\$	114.90		
1 DOOR REGULATOR REAR LH L70Y	\$	657.10		
1 DOOR REGULATOR MOTOR REAR LH L70Y	\$	450.60		
1 DOOR HANDLE OUTER REAR LH L70Y	\$	42.10		
1 DOOR HANDLE CAP REAR LH L70Y	\$	57.90		
1 DOOR HANDLE MODULE REAR LH L70Y	\$	133.40		
1 DOOR SEAL REAR LH	\$	119.40		
1 DOOR WHEATHERSTRIP REAR LH	\$	240.50		
1 DOOR GLASS RUNNER SEAL REAR LH	\$	116.10		
1 DOOR FINISHER REAR LH	\$	230.30		
1 DOOR WAIST SEAL OUTER REAR LH	\$	169.60		
1 DOOR MOULDING BLACK REAR LH	\$	100.50		
1 DOOR LOCK REAR LH L70Y	\$	468.20		
1 FENDER PANEL REAR LH	\$	1,933.20		
1 FENDER PANEL INNER TRIM REAR LH	\$	671.45		
1 WHEELARCH REAR LH	\$	181.60		
1 AIR VENT	\$	59.40		
1 TAILLAMP LH	\$	401.40		
1 TAILLAMP PANEL LH	\$	401.40		
1 BUMPER COVER REAR	\$	561.70		
1 BUMPER LOWER REAR	\$	411.90		
1 BUMPER BRACKET SIDE LH REAR	\$	80.80		
1 BUMPER RETAINER LH REAR	\$	54.20		
1 BUMPER REFLECTOR LH	\$	16.60		
1 BUMPER BEAM REAR	\$	547.80		
1 BUMPER BEAM BRACKET LH REAR	\$	114.50		
TOTAL	\$	25,000.35		

Trans-cab Auto Services Pte Ltd

AAD2003-092

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9788K

10%	\$	2,500.04
	\$	22,500.32

Special Nett

1	FRONT DOOR STICKER 'Trans-Cab'	\$	na	80.00	60sn
1	FRONT DOOR STICKER 'Classic'	\$	na	80.00	15sn
1	REAR DOOR STICKER '6555-3333'	\$	na	100.00	60sn
1	LH SIDE RENAULT TYRE 215/60/16	\$	sn	330.00	} X
1	LH SIDE RENAULT TYRE RIM	\$	sn	380.00	
1	WHEELARCH CLIP FRT LH	\$	na	30.50	
1	REAR WINDSCREEN MOULDING	\$	na	160.00	
2	WINDSCREEN SEALANT	\$	na	120.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	sn	100.00	
1	DOOR CHECK BOLT	\$	sn	10.20	
1	DOOR CHECK NUT	\$	sn	10.20	
1	DOOR GUIDE SCREW	\$	sn	10.85	
1	DOOR HINGE BOLT	\$	sn	12.60	
1	DOOR HINGE NUT LH	\$	sn	7.20	
1	DOOR SEAL CLIP LH	\$	na	4.90	
1	DOOR MOULDING CLIP	\$	na	5.90	
1	BUMPER CLIP FRT	\$	na	66.00	
1SET	BUMPER RETAINER FRONT LH	\$	na	35.00	
1	TAILLAMP CLIP LH	\$	na	5.00	
1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
1SET	PARKING AID	\$	sn	700.00	
1SET	REAR BUMPER CLIP	\$	na	66.00	
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	
1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	
1	Rear Bumper Protector	\$	sn	100.00	
TOTAL		\$		2,595.35	

TOTAL PARTS	\$	25,095.67
--------------------	----	------------------

LABOUR

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9788K**AAD2003-092**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	5001
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To rust-proofing of the affected areas.	\$	170.00	601
Putty and spray painting of the affected portion.	\$	7,500.00	8801
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	170.00	801
To transfer of Front door fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	170.00	601
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

Trans-cab Auto Services Pte Ltd**AAD2003-092**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9788K

To transfer of rear bumper fittings, attachment and perform
water seepage test.

\$ *nn* 170.00 X

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 X

TOTAL \$ 17,850.00

Over All Total \$ 42,945.67

LUMP SUM (REPAIR DAY)***25* DAYS***3 day,*