



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685502
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 17/03/2020

User ID : wngbangklien

Section A - Accident Details

Registration Number	SHB144M
Case Reference Number	TAX/03/20/2045
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	MOHD SHARIFF BIN OMAR
Type of Accident	Side Swipe
Accident Date and Time	14/3/2020 2:30 PM
Accident Reported Date and Time	16/3/2020 9:51 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106162
Special Instruction to ARC, if any	LEFT HAND FRONT PORTION
Prepared Date and Time	16/3/2020 1:41 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$5,802.76	\$39.67
Total Other Cost	\$700.00	\$0.00
TOTAL COST	\$8,114.76	\$639.67
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	16/03/2020 2:12 PM	17/03/2020 3:27 PM
Signature		
Remarks		P/P, Before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685532
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/03/2020

User ID : angbangklien

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$700.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given
		81220470 20	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given
		81185476 91	UNIT, HEADLAMP, LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given
		53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
Total					\$6,987.44		\$39.67		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

Section A - Accident Details

Registration Number	SHB144M
Case Reference Number	TAX/03/20/2045
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	MOHD SHARIFF BIN OMAR
Type of Accident	Side Swipe
Accident Date and Time	14/3/2020 2:30 PM
Accident Reported Date and Time	16/3/2020 9:51 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106162
Special Instruction to ARC, if any	LEFT HAND FRONT PORTION
Prepared Date and Time	16/3/2020 1:41 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$5,802.76	\$39.68
Total Other Cost	\$700.00	\$0.00
TOTAL COST	\$8,114.76	\$639.68 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	16/03/2020 2:12 PM	17/03/2020 3:27 PM
Signature		
Remarks		P/P, Before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2003-0542	Invoice Number	
Quotation Date	31.03.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$700.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given
		81220470 20	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given
		81185476 91	UNIT, HEADLAMP, LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given
		53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
Total					\$6,987.44		\$39.68		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

39.68 ✓
 + 200.00 ✓
 + 400.00 ✓

 639.68 ✓

2 days

Nec