

## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Se	vices Pte Ltd
60 Woodlands Industria	I Rark E4, Singapore 757705
EAX Number : 636855	02

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 17/03/2020 User ID : angbangkien

	Section	A - Accident Detail	S	
Registration Number	SHB144M			
Case Reference Number	TAX/03/20/2045	5		
Registration Date	28/11/2017			
Company Type	SMRT Taxis Pte	e Ltd		
Make	TOYOTA			
Model	PRIUS4			
Name of Driver	MOHD SHARIF	F BIN OMAR		
Type of Accident	Side Swipe			
Accident Date and Time	14/3/2020 2:30	PM		
Accident Reported Date and Time	16/3/2020 9:51	AM		
Is Surveyor Required?	Yes	11611175		
Survey by	7 9			
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number	24106162			
Special Instruction to ARC,if any	LEFT HAND FR	RONT PORTION		
Prepared Date and Time	16/3/2020 1:41	PM		
Chassis Number				
Mileage				
Work Shop		7 11/2		
Repair Completion Date and Time				
11700	Cartier D. C.			
Summary of Repair Estimates	Section B - Sui	mmary of Repair Es	timates	
Summary of Repair Estimates	Quotation from A	ADC	1	
The second second	Quotation nom?	ARC	Adjusted by Surveyor, if appli	icable
Total Labour Cost	\$676.00	ARC	\$200.00	icable
		ARC		icable
Total Spray Cost	\$676.00	ARC	\$200.00	icable
Total Spray Cost Total Spare Part Cost	\$676.00 \$936.00	arc .	\$200.00 \$400.00	icable
Total Spray Cost Total Spare Part Cost Total Other Cost	\$676.00 \$936.00 \$5,802.76	arc	\$200.00 \$400.00 \$39.67	icable
Fotal Spray Cost  Fotal Spare Part Cost  Fotal Other Cost  FOTAL COST	\$676.00 \$936.00 \$5,802.76 \$700.00	and	\$200.00 \$400.00 \$39.67 \$0.00	icable
Total Spray Cost  Total Spare Part Cost  Total Other Cost  FOTAL COST  Lump Sum Total	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76	o local v	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67	icable
Total Spray Cost Total Spare Part Cost Total Other Cost FOTAL COST Lump Sum Total Number of Repair Days	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00	o locatily	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00	icable
Total Spray Cost Total Spare Part Cost Total Other Cost  FOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00	Getti 1	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0	icable
Total Labour Cost  Total Spray Cost  Total Spray Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok	Getti 1	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK)	icable
Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok	Getti 1	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK)	icable
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok	Getti 1	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK)	icable
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok	Getti 1	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK) 17/03/2020 3:27 PM	icable
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok	Getti 1	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK)	icable
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok	Getti 1	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK) 17/03/2020 3:27 PM	icable
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok	Getti 1	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK) 17/03/2020 3:27 PM	icable
Fotal Spray Cost Fotal Spare Part Cost Fotal Other Cost FOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok 16/03/2020 2:12 F	PM PM	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK) 17/03/2020 3:27 PM	icable
Fotal Spray Cost Fotal Spare Part Cost Fotal Other Cost FOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok	PM PM	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK) 17/03/2020 3:27 PM	icable
Fotal Spray Cost Fotal Spare Part Cost Fotal Other Cost FOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature Remarks	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok 16/03/2020 2:12 F	on and Accident Inv	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK) 17/03/2020 3:27 PM	icable
Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature	\$676.00 \$936.00 \$5,802.76 \$700.00 \$8,114.76 \$0.00 5.0 Tuck Foo Kok 16/03/2020 2:12 F	PM PM	\$200.00 \$400.00 \$39.67 \$0.00 \$639.67 \$0.00 2.0 Sun Pin (LKK) 17/03/2020 3:27 PM	icable



Page 2 of 2

## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone No. mber: 68662623

Accident Reporting Number : 68662672

Date Generated: 17/03/2020

OREARN FRONT EN PORTION   \$676.00   \$200.00    27art 2 - Spray Painting & Panel Beating Related Works    27art 2 - Spray Painting & Panel Beating Related Works    27art 2 - Spray Painting & Panel Beating Related Works    27art 2 - Spray Painting & Panel Beating Related Works    27art 2 - Spray Painting & Panel Beating Related Works    27art 2 - Spray Painting & Panel Beating    27art 3 - Spray Painting & Panel Beating    27art 3 - Spray Painting & Panel Beating    27art 3 - Other Costs - Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art 3 - Other Costs - Accident and Accident Repair Related Expense    27art	Common			- C(6)	Sect	ion D - Det	ails of Repair I	Estimates				
SPECIAL PROPERTION	September   Portion   September	Part 1 - Labo	ur Works	500		7						1
Second   S	Total Labour	Job Scope	341	7777		Quotation	Quotation from AR			Adjusted by Surveyor, if applicable		
Part 2 - Spray Painting & Panel Beating Related Works	Part 2 - Spray Painting & Panel Beating Related Works	TO REPAIR FE	RONT LH PORT	TION		\$676.00				\$200.00		
	Quotation from ARC	Total Labour	417	-		\$676.00			7)			
TO REPSRAY FRONT BUMPER	TO REPSRAY FRONT BUMPER	Part 2 - Spra	y Painting & I	Panel Beating Rel	ated Works	-		i.				Ħ
S78.00	S278.00	Job Scope	ob Scope Quotation from ARC Adjusted by Surveyor, if applicable									
S78.00	S278.00	TO REPSRAY	FRONT BUMP	ER	707	\$378.00	\$378.00			\$200.00		-
Statistics   Sta	Standard											A
Sample   S	Sample	TO RESPRAY	RIM							No. Control		-
Adjusted by Surveyor, If applicable   Surv		Total Spray Pa	ainting & Panel	l Beating		\$936.00		3		7.000 D		1 11
Adjusted by Surveyor, If applicable   Surv	Adjusted by Surveyor, If applicable	Part 3 - Other	Costs - Acci	ident and Accider	nt Repair Related Expen	se		1000				10.10
S0.00	S0.00   S0.0						otation from ARC			Adjusted by Surveyor, if applicable		3
TO APPLY RUST-PROOFING ON AFFECTED AREA   \$100.00   \$0.00	TO APPLY RUST-PROOFING ON AFFECTED AREA   \$100.00   \$0.00   \$0.00	TO CHECK WII	RING AND SYS	STEM FUNCTION		\$80.00				\$0.00		1
TO DO WHEEL ALIGNMENT / TYRE BALANCING	TO DO WHEEL ALIGNMENT / TYRE BALANCING	TO APPLY RUS	ST-PROOFING	ON AFFECTED AR	EA	E. CO. C. T. T. C.				N. 1711.00.10.		1
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)   \$120.00   \$120.00   \$50.00	SECOND   S	TO DO WHEEL	L ALIGNMENT /	TYRE BALANCING		\$120.00						-
TO REMOVE AND REFIT WIRE HARDESS   \$120.00   \$0.00   \$0.00   \$0.00	TO REMOVE AND REFIT WIRE HARDESS   \$120.00   \$0.00	TO REMOVE A	ND REFIT TYP	RE RIM (SPRAYING	PURPOSE)					PARTITION AND ADDRESS OF THE PARTITION ADDRESS OF THE PARTITION AND ADDRES		A 19
Stock Number	Stock Number   Portion   Stock Number   Part Name   Quantity   List Price (\$)   Discount (%)   Final Price (\$)   Estimator Approved   Surveyor Approved	TO REMOVE A	ND REFIT WIR	RE HARDESS		\$120.00	-	-				-
Second   S	Second   S	O REPLACE S	SUNDRY PART	S		\$100.00	eris .					
Part A - Spare Parts / Material Usage Part Number   Portion   Stock Number   Part Name   Quantity   List Price (\$)   Discount (%)   Final Price (\$)   Estimator Approved   Surveyor Approved	Part 4 - Spare Parts / Material Usage Part Number	D WASH AND VACUUM			\$60.00							
Portion   Stock Number   Part Name   Quantity   List Price (\$)   Discount (%)   Final Price (\$)   Estimator Approved   Surveyor Approved	Part Number   Portion   Stock Number   Part Name   Quantity   List Price (\$)   Discount (%)   Final Price (\$)   Estimator Approved   Surveyor Approved	Total Other Co	sts			\$700.00				\$0.00		
Portion   Stock Number   Part Name   Quantity   List Price (\$)   Discount (%)   Final Price (\$)   Estimator Approved   Surveyor Approved	Part Number   Portion   Stock Number   Part Name   Quantity   List Price (\$)   Discount (%)   Final Price (\$)   Estimator Approved   Surveyor Approved	Part 4 - Spare	Parts / Mater	rial Usage		-	_				- 1	
52161160 10   CLIPS PIECE, FRT & RR   0.00   \$1.50   0.00   \$0.00   Replace   Not Given   \$50.00   Replace   Replace   Replace   Replace   Replace   Replace   Replace   Replace   Replace   \$60.00   Replace   Replace   \$60.00   Replace   Replace   \$60.00   Replace   \$60.00   Replace   Replace   \$60.00	52161160 10   CLIPS PIECE, FRT & RR   0.00   \$1.50   0.00   \$0.00   Replace   Not Given   SVC				Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
BUMPER   SUPPORT, FR BUMPER   0.00   \$82.30   0.00   \$0.00   Replace   Not Given   SVC	BUMPER   SUPPORT, FR BUMPER   0.00   \$82.30   0.00   \$0.00   Replace   Not Given   SVC			52119479 62	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair	XR
LH 52115470 50 SUPPORT, FR BUMPER 0.00 \$76.90 0.00 \$0.00 Replace Not Given 5VC 81220470 20 LAMP ASSY, FOG, LH 0.00 \$910.20 0.00 \$0.00 Replace Not Given 5VC 81185476 91 UNIT, HEADLAMP, LH 0.00 \$2,558.90 0.00 \$0.00 Replace Not Given 53802471 00 FENDER SUB-ASSY, FR 1.00 \$933.10 100.00 \$0.00 Replace Repair R 75374471 40 EMBLEM, SIDE PANEL ( 1.00 \$52.90 25.00 \$39.67 Replace Replace 10.00 \$10.00 Replace Replace 10.00 \$10.00 Replace Replace 10.00 \$10.00 \$10.00 Replace Not Given 50.00 Repl	LH  52115470 50 SUPPORT, FR BUMPER 0.00 \$76.90 0.00 \$0.00 Replace Not Given  81220470 20 LAMP ASSY, FOG, LH 0.00 \$910.20 0.00 \$0.00 Replace Not Given  81185476 91 UNIT, HEADLAMP, LH 0.00 \$2.558.90 0.00 Replace Not Given  53802471 00 FENDER SUB-ASSY, FR 1.00 \$933.10 100.00 \$0.00 Replace Repair  75374471 40 EMBLEM, SIDE PANEL ( 1.00 \$52.90 25.00 \$39.67 Replace Replace Not Given  53876471 10 LINER, FR FENDER, LH 0.00 \$194.30 0.00 \$0.00 Replace Not Given  TYRE 0.00 \$126.74 0.00 \$0.00 Replace Not Given  576.90 Not Given			52161160 10		0.00	\$1.50	0.00	\$0.00	Replace	Not Given	
RH  81220470 20 LAMP ASSY, FOG, LH 0.00 \$910.20 0.00 \$0.00 Replace Not Given \$5\times \$5\time	RH			52116470 50		0.00	\$82.30	0.00	\$0.00	Replace	Not Given	X svc
S1185476 91 UNIT, HEADLAMP, LH   0.00   \$2,558.90   0.00   \$0.00   Replace   Not Given   53802471 00   FENDER SUB-ASSY, FR   1.00   \$933.10   100.00   \$0.00   Replace   Repair   R	81185476 91			52115470 50		0.00	\$76.90	0.00	\$0.00	Replace	Not Given	× svc
81185476 91	S1185476 91	77	100	81220470 20	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given	25.00
53802471 00   FENDER SUB-ASSY, FR   1.00   \$933.10   100.00   \$0.00   Replace   Repair   R	53802471 00   FENDER SUB-ASSY, FR   1.00   \$933.10   100.00   \$0.00   Replace   Repair   R	(c) II		81185476 91	UNIT, HEADLAMP , LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given	
HYBRID)   S000   S000   Replace   Not Given   SVC	HYBRID   10.00   194.30   0.00   0.0		Ya.	53802471 00		1.00	\$933.10	100.00	\$0.00	Replace	Repair	48 110
TYRE 0.00 \$126.74 0.00 \$0.00 Replace Not Given \$5.00	TYRE 0.00 \$126.74 0.00 \$0.00 Replace Not Given \$5.00 Question of the control of t	3 170		75374471 40	EMBLEM, SIDE PANEL ( HYBRID)	1.00	\$52.90	25.00	\$39.67	Replace	Replace	DE/NE
TYRE 0.00 \$126.74 0.00 \$0.00 Replace Not Given	TYRE 0.00 \$126.74 0.00 \$0.00 Replace Not Given \$500 Solution	100	1103	53876471 10		0.00		0.00	\$0.00	Replace	Not Given	X SVC
	42611474 50 WHEEL, DISC 0.00 \$1,555.10 0.00 \$0.00 Replace Not Given				554.55	2000		0.00	\$0.00	Replace	Not Given	11 14 10
The state of the s			(3)	42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	77 177
	555.01	otal	2.5				\$6,987.44		\$39.67		- 19	
[otal		Total	19	81185476 91 53802471 00 75374471 40 53876471 10	LAMP ASSY, FOG, LH UNIT, HEADLAMP, LH FENDER SUB-ASSY, FR, LH EMBLEM, SIDE PANEL ( HYBRID) LINER, FR FENDER, LH TYRE	0.00 1.00 1.00 6.00 0.00	\$2,558.90 \$933.10 \$52.90 \$194.30 \$126.74 \$1,555.10	0.00 100.00 25.00 0.00	\$0.00 \$0.00 \$39.67 \$0.00 \$0.00 \$0.00	Replace Replace Replace Replace Replace	Not Given Repair Replace Not Given Not Given Not Given	AXXXXXXX
156 987 AA 1 1630 67			1				\$6,987.44		\$39.67		13	1.15
		Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Added Spare Parts / Material Usage After Surveyor Signed off	Part Number Portion Stock Number Part Name Quantity List Price \$ Discount (%) Final Price (\$) ARC Check Surveyor Check	Total	14 14				_					41.5
Added Spare Parts / Material Usage After Surveyor Signed off  Part Number   Portion   Stock Number   Part Name   Quantity   List Price \$   Discount (%)   Final Price (\$)   ARC Check   Surveyor Check	Gallinity Clair File 3 Discoulit (%) Filial File (3) ARC Check Surveyor Check		To ston	Mary 1				the Repa	irer of the f	ollowing:		
Added Spare Parts / Material Usage After Surveyor Signed off  Part Number Portion Stock Number Part Name Quantity List Price \$ Discount (%) Final Price (\$) ARC Check Surveyor Check  Total LKK Auto Consultants hence notify the Repairer of the following:	LKK Auto Consultants hence notify the Repairer of the following:								To resurvey before/after spray painting To display damaged part(s) during resurvey			

 Parts prices are subject to confirmation Third party survey is on a "Without Projudice" be

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

No illegal modification(s) is allowed

Acknowledged by Repairer

Signature: Date: