


SKETCH PLAN



Vehicle A - PC8853Y
Vehicle B - 6B D5 334X
Vehicle C - GBL 3205S

[illegible]

/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature:
Name: *[Signature]*
INRI/FIN No: *[Signature]*



**SINGAPORE
POLICE FORCE**



T/20200318/2030

1 of 4

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20200318/2030

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/03/2020 10:49	Vide Report No.:	Station Diary No.: 34
--------------------------------------------	------------------	--------------------------

Informant's Particulars

Name of Informant: MOHD ASRI BIN MOHD SAID			Address: APT BLK 785A WOODLANDS RISE #05-152 SINGAPORE 731785		
ID Type / ID No.: NRIC NO / S1778064F			Contact No.: Home/Office: Mobile: 90210151		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 53	Date of Birth: 26/09/1966	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: Operational Executive			Driving Licence Information: Class: 3,4 Date of Expiry:		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/03/2020 20:00	Type of Location:
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY BKE towards SLE before the exit to Mandai Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC3205S	Lorry				Slightly Damaged	0
GBD5339X	Lorry				Slightly Damaged	1
PC8853Y	Van				Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20200318/2030

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

2 of 4

Report No. T/20200318/2030

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	SHAI HAN KONG	ID No.	S1191253B
Related Vehicle	GBC3205S (Lorry)	Contact No.	96461670
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	ISLAM MOHAMMAD JAHIRUL	ID No.	G2370752M
Related Vehicle	GBD5339X (Lorry)	Contact No.	83014771
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MOHD ASRI BIN MOHD SAID	ID No.	S1778064F
Related Vehicle	PC8853Y (Van)	Contact No.	90210151
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	17/03/2020	Date Discharge	18/03/2020
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 17/03/2020 at about 8pm, I was driving my company van (PC 8853Y) along BKE towards SLE before the exit of Mandai Road. As there was a jam along BKE, all the vehicles were travelling slowly. Suddenly, one lorry(GBD 5339X) hit onto the rear of my van. The impact caused my van to move forward and hit onto the front lorry (GBS 3205S).. All of us alighted from our vehicles to exchange particulars. We did not call police as it was a minor accident. After we drove off. I felt uneasy. On the same day at 8.57 pm, I sought treatment at KTPH and given 3 days MC for whip lash.



**SINGAPORE
POLICE FORCE**



T/20200318/2030

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

4 of 4

Report No. T/20200318/2030

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

SI QUEK CHAW YUEN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

18/03/2020 10:49

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Classification Of Case:

Authentication Stamp

NP168

Signature:

Singapore Police Force



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE		
DATE	:	19/3/2020
ACC DATE	:	17/03/2020
POLICY NO	:	D-19094600MFBP/2
SHEET NO. 1 OF 2 SHEET		

Attention: Motor Claim Department

RE : VEHICLE NO : PC8853Y (POH TIONG CHOON LOGISTICS LIMITED)

S/NO	QTY	DESCRIPTION	UNIT PRICE S\$	AMOUNT S\$
1	1	BONNET <i>bt</i>		757.00
2	1	BONNET BADGE <i>neu</i>		78.50
3	2	BONNET HINGE <i>neu RH-bt (1pc)</i>	98.00	196.00
4	1	BONNET LOCK <i>X</i>		175.00
5	1	BONNET STAND <i>X</i>		68.00
6	2	BONNET SIDE STOPPER <i>neu</i>	10.00	20.00
7	2	FRONT CORNER PANEL <i>repair RH (1pc)</i>	527.00	1,054.00
8	1	FRONT GRILLE BASE <i>cm</i>		457.00
9	1	FRONT GRILLE OUTER TOP <i>cm</i>		217.00
10	1	FRONT GRILLE OUTER BOTTOM <i>cm</i>		320.00
11	1	FRONT BUMPER <i>cm</i>		859.00
12	2	FRONT BUMPER SIDE RETAINER <i>X</i>	200.00	400.00
13	10	FRONT BUMPER CLIPS <i>neu</i>	5.00	50.00
14	1	FRONT BUMPER CENTER GRILLE <i>de-bt</i>		275.00
15	1	FRONT BUMPER REINFORCEMENT TOP <i>bt-repair</i>		379.00
16	1	FRONT BUMPER REINFORCEMENT LOWER <i>repair</i>		569.00
17	2	FRONT BUMPER REINFORCEMENT SIDE BRACKET <i>?</i>	130.00	260.00
18	2	FRONT BUMPER REINFORCEMENT INNER SIDE PANEL <i>bt</i>	278.00	556.00
19	2	HEADLAMP <i>cm</i>	958.00	1,916.00
20	1	FRONT FIRE WALL <i>repair</i>		970.00
21	1	RADIATOR SPARE TANK <i>cm</i>		217.00
22	1	WIPER TANK <i>de</i>		179.00
23	1	INTERCOOLER		1,289.00
24	1	INTERCOOLER SIDE COVER RH <i>X</i>		110.00
25	1	INTERCOOLER SIDE COVER LH <i>X</i>		139.00
26	1	SUPPORT PANEL <i>bt</i>		569.00
27	1	BRAKE MASTER PUMP <i>X</i>		781.00
28	1	BRAKE BOOSTER PUMP <i>?</i>		951.00
29	1	AIR CONDENSER <i>bt</i>		651.00
30	1	RADIATOR <i>bt</i>		1,120.00
31	1	TAILGATE <i>bt</i>		1,700.00
32	1	TAILGATE TOP THIRD BRAKE LAMP <i>X</i>		270.00
33	1	TAILGATE WINDSCREEN <i>bro</i>		790.00
34	1	TAILGATE INNER SEAL <i>neu</i>		50.00
35	1	TAILGATE WIPER MOTOR <i>X</i>		659.00
36	1	TAILGATE WIPER ARM <i>X</i>		120.00
37	1	TAILGATE BLADE <i>neu-neu</i>		69.00
38	1	TAILGATE BADGE <i>neu</i>		89.00
39	1	TAILGATE STICKER (TOYOTA) <i>neu</i>		69.00
40	1	TAILGATE STICKER (HIACE) <i>neu</i>		50.00
41	1	TAILGATE OUTER GARNISH		327.00
42	1	TAILGATE OUTER HANDLE <i>X</i>		120.00
43	2	TAILGATE NUMBER PLATE LAMP <i>X</i>	89.00	178.00
44	2	TAILGATE SIDE STOPPER (MALE) <i>neu X</i>	80.00	160.00
45	2	TAILGATE SIDE STOPPER (FEMALE) <i>neu RH (cut) (1pc)</i>	80.00	160.00
46	2	TAILGATE HINGE <i>X</i>	80.00	160.00
47	2	TAILGATE ABSORBER <i>X</i>	310.00	620.00
48	1	TAILGATE INNER LOCK <i>bt</i>		420.00
49	1	TAILGATE AUTO LOCK ACTUATOR <i>?</i>		272.00
50	1	TAILGATE LOCK MECHANISM <i>?</i>		321.00
51	1	TAILGATE LOCK CATCH <i>X</i>		46.00
52	1	TAILGATE WEATHERSTRIP <i>neu</i>		289.00
53	1	TAILGATE INNER TRIM BOARD <i>de</i>		572.00
54	1	TAILGATE INNER HANDLE <i>X</i>		42.00
55	1	TAILGATE HANDLE BASE <i>de</i>		121.00
56	2	TAILAMP <i>cm (RH) (1pc)</i>	472.00	944.00
57	2	TAILAMP PANEL OUTER (TOP) <i>X</i>	190.00	380.00
58	2	TAILAMP PANEL OUTER (LOWER) <i>RH-bt (1pc)</i>	272.00	544.00
59	2	TAILAMP PANEL INNER <i>RH-bt (1pc)</i>	372.00	744.00
60	2	TAILAMP BOTTOM SIDE COVER <i>RH-cut (1pc)</i>	130.00	260.00
61	2	TAILAMP BOTTOM SIDE RETAINER <i>RH-cm (1pc)</i>	60.00	120.00
62	1	END PANEL (OUTER) <i>bt</i>		679.00
63	1	END PANEL (INNER) <i>bt</i>		972.00
64	1	END PANEL TOP PLATE <i>bt</i>		210.00
65	1	REAR FLOOR PANEL <i>repair</i>		2,120.00
66	1	FLOOR PANEL TOP CLUTCH <i>slu cm price?</i>		870.00
67	1	REAR BUMPER <i>de</i>		690.00
68	1	REAR BUMPER SIDE RETAINER <i>neu RH (1pc)</i>	120.00	240.00
69	1	REAR FENDER RH <i>bt</i>		3,210.00
70	1	REAR FENDER INNER PANEL RH <i>repair</i>		779.00
71	2	REAR FENDER GLASS INNER SEAL <i>neu</i>	50.00	100.00
72	1	REAR EXHAUST SILENSER <i>bt-photo</i>		1,690.00
73	2	REAR EXHAUST MOUNTING <i>ne</i>	40.00	80.00
74	1	REAR EXHAUST GASKET <i>ne</i>		52.00



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE

DATE : 19/3/2020
ACC DATE : 17/03/2020
POLICY NO : D-19094600MFBP/2
SHEET NO. 1 OF 2 SHEET

Attention: Motor Claim Department

RE : VEHICLE NO : PC8853Y (POH TIONG CHOON LOGISTICS LIMITED)

S/NO.	QTY	DESCRIPTION	UNIT PRICE	AMOUNT S\$
		SPECIAL NET		
1	3	REAR WINDSCREEN SEALANT <i>new price</i>	210.00	\$ 630.00 <i>80</i>
2	1	REAR WINDSCREEN SOLAR FILM		\$ 250.00 <i>?</i>
4	1	WATER PROOF SEALANT <i>new price</i>		\$ 120.00 <i>60</i>
5	1	REVERSE SENSOR <i>new</i>		\$ 350.00 <i>220</i>
6	1	LAST ROW PASSENGER SEAT <i>repair</i>		\$ 2,500.00 <i>300</i>
7	1	REAR NUMBER PLATE WITH COVER <i>55</i>		\$ 50.00 <i>35</i>
8	1	FRONT NUMBER PLATE WITH COVER <i>55</i>		\$ 50.00 <i>35</i>
9	1	RADIATOR COOLANT <i>new</i>		\$ 60.00 <i>2</i>
				\$ 4,010.00

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1		To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	3,000.00 <i>2000</i>
2		To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	3,000.00 <i>1800</i>
3		Remove & Refit Rear Windscreen	150.00 <i>120</i>
4		Remove & Refit Tailgate	90.00 <i>60</i>
5		Remove & Refit Carpet , Seat and Interior	350.00 <i>200</i>
6		Remove & Refit Exhaust	150.00 <i>80</i>
7		Remove & Refit Aircond System	300.00 <i>150</i>
8		Remove & Refit Reverse Sensor	150.00 <i>60</i>
			\$ 7,190.00
		GRAND TOTAL :	\$ 41,552.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resu
Hp 90010068
17 days
4/5
19/03/2020 @ 17/10
Resu after repair