

Vfix Auto Pte Ltd
26 Chua Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE	
DATE	19/3/2020
ACC DATE	17/03/2020
POLICY NO	D-19094600MFBP/2
SHEET NO. 1 OF 2 SHEET	

Attention: Motor Claim Department

RE : VEHICLE NO : PC8853Y (POH TIONG CHOON LOGISTICS LIMITED)

S/NO	QTY	DESCRIPTION	UNIT PRICE S\$	AMOUNT S\$
1	1	BONNET bt		757.00
2	1	BONNET BADGE new		78.50 66
3	2	BONNET HINGE new RH-bt (1pc)	@54 98.00	196.00 54
4	1	BONNET LOCK X SVC		175.00 x
5	1	BONNET STAND X SVC		68.00 x
6	2	BONNET SIDE STOPPER new	10.00	20.00
7	2	FRONT CORNER PANEL repair RH (1pc) X	527.00	1,054.00 Repair x
8	1	FRONT GRILLE BASE new		457.00 326
9	1	FRONT GRILLE OUTER TOP new		217.00 155
10	1	FRONT GRILLE OUTER BOTTOM new		320.00 210
11	1	FRONT BUMPER new		859.00 499
12	2	FRONT BUMPER SIDE RETAINER X SVC	200.00	400.00 x
13	10	FRONT BUMPER CLIPS new	5.00	50.00
14	1	FRONT BUMPER CENTER GRILLE new		275.00 186
15	1	FRONT BUMPER REINFORCEMENT TOP bt		379.00
16	1	FRONT BUMPER REINFORCEMENT LOWER repair		569.00 repair x
17	2	FRONT BUMPER REINFORCEMENT SIDE BRACKET ? bt	@50 130.00	260.00 100
18	2	FRONT BUMPER REINFORCEMENT INNER SIDE PANEL bt	278.00	556.00
19	2	HEADLAMP new	@750 958.00	1,916.00 1500
20	1	FRONT FIRE WALL repair		970.00 x
21	1	RADIATOR SPARE TANK new		217.00
22	1	WIPER TANK new		179.00
23	1	INTERCOOLER ? bt		1,289.00
24	1	INTERCOOLER SIDE COVER RH X SVC		110.00 x
25	1	INTERCOOLER SIDE COVER LH X SVC		139.00 x
26	1	SUPPORT PANEL new		569.00 450
27	1	BRAKE MASTER PUMP X SVC		781.00 x
28	1	BRAKE BOOSTER PUMP ? bt		951.00
29	1	AIR CONDENSER bt		651.00
30	1	RADIATOR bt		1,120.00
31	1	TAILGATE bt		1,700.00
32	1	TAILGATE TOP THIRD BRAKE LAMP X SVC		270.00 x
33	1	TAILGATE WINDSCREEN new		790.00
34	1	TAILGATE INNER SEAL new		50.00
35	1	TAILGATE WIPER MOTOR X SVC		659.00 x
36	1	TAILGATE WIPER ARM X SVC		120.00 x
37	1	TAILGATE BLADE new		69.00 55
38	1	TAILGATE BADGE new		89.00 75
39	1	TAILGATE STICKER (TOYOTA) new		69.00 30
40	1	TAILGATE STICKER (HIACE) new		50.00 20
41	1	TAILGATE OUTER GARNISH X SVC		327.00 x
42	1	TAILGATE OUTER HANDLE X SVC		120.00 x
43	2	TAILGATE NUMBER PLATE LAMP X SVC	89.00	178.00 x
44	2	TAILGATE SIDE STOPPER (MALE) new SVC	80.00	160.00 x
45	2	TAILGATE SIDE STOPPER (FEMALE) new RH (cut) (1pc)	@49 80.00	160.00 49
46	2	TAILGATE HINGE X SVC	80.00	160.00 x
47	2	TAILGATE ABSORBER X SVC	310.00	620.00 x
48	1	TAILGATE INNER LOCK bt		420.00 320
49	1	TAILGATE AUTO LOCK ACTUATOR ? X SVC		272.00 x
50	1	TAILGATE LOCK MECHANISM ? X SVC		321.00 x
51	1	TAILGATE LOCK CATCH X SVC		46.00 x
52	1	TAILGATE WEATHERSTRIP new		289.00
53	1	TAILGATE INNER TRIM BOARD new		572.00 485
54	1	TAILGATE INNER HANDLE X SVC		42.00 x
55	1	TAILGATE HANDLE BASE new		121.00
56	2	TAILAMP new (RH) (1pc)	@388 472.00	944.00 388
57	2	TAILAMP PANEL OUTER (TOP) X SVC	190.00	380.00 x
58	2	TAILAMP PANEL OUTER (LOWER) RH-bt (1pc)	@272.00	544.00 272
59	2	TAILAMP PANEL INNER RH-bt (1pc)	@175 372.00	744.00 175
60	2	TAILAMP BOTTOM SIDE COVER RH-cut (1pc)	@91 130.00	260.00 91
61	2	TAILAMP BOTTOM SIDE RETAINER RH-cut (1pc)	@ 60.00	120.00 60
62	1	END PANEL (OUTER) bt		679.00 486
63	1	END PANEL (INNER) bt		972.00 585
64	1	END PANEL TOP PLATE bt		210.00
65	1	REAR FLOOR PANEL repair		2,120.00 x
66	1	FLOOR PANEL TOP CLUTCH new S/N price? (carpet) S/N		870.00 300
67	1	REAR BUMPER new		690.00 469
68	2	REAR BUMPER SIDE RETAINER new RH (1pc)	@120.00	240.00 120
69	1	REAR FENDER RH bt	@1889	3,210.00 1889
70	1	REAR FENDER INNER PANEL RH repair		779.00 x
71	2	REAR FENDER GLASS INNER SEAL new	50.00	100.00
72	1	REAR EXHAUST SILENSER X repair (labour - 100) LOCAL REPAIR/BT	40.00	1,690.00 x
73	2	REAR EXHAUST MOUNTING X SVC		80.00 x
74	1	REAR EXHAUST GASKET X SVC		52.00 x

18,544

25%

13,908


S/N - 300

labour - 100

20%

\$ 37,940.50

\$ 30,352.40



Vfix Auto Pte Ltd
26 Chio Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68626669
UEN / GST REG No.: 201830761R

ESTIMATE

DATE : 19/3/2020
ACC DATE : 17/03/2020
POLICY NO : D-19094600MFBP/2
SHEET NO. 1 OF 2 SHEET

Attention: Motor Claim Department

RE : VEHICLE NO : PC8853Y (POH TIONG CHOON LOGISTICS LIMITED)

S/NO.	QTY	DESCRIPTION	UNIT PRICE	AMOUNT S\$
		SPECIAL NET		
1	3	REAR WINDSCREEN SEALANT <i>new price nec</i>	210.00	\$ 630.00 <i>80</i>
2	1	REAR WINDSCREEN SOLAR FILM		\$ 250.00 <i>200</i>
4	1	WATER PROOF SEALANT		\$ 120.00 <i>60</i>
5	1	REVERSE SENSOR <i>new</i>	970	\$ 350.00 <i>220</i>
6	1	LAST ROW PASSENGER SEAT <i>repair LOCAL REPAIR/SCR</i>		\$ 2,500.00 <i>300</i>
7	1	REAR NUMBER PLATE WITH COVER <i>bt</i>		\$ 50.00 <i>35</i>
8	1	FRONT NUMBER PLATE WITH COVER <i>bt</i>		\$ 50.00 <i>35</i>
9	1	RADIATOR COOLANT <i>new</i>		\$ 40.00 <i>35</i>
				\$ 4,010.00

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1		To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	3,000.00 <i>2000</i>
2		To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	3,000.00 <i>1800</i>
3		Remove & Refit Rear Windscreen	150.00 <i>120</i>
4		Remove & Refit Tailgate	90.00 <i>60</i>
5		Remove & Refit Carpet, Seat and Interior	350.00 <i>200</i>
6		Remove & Refit Exhaust	150.00 <i>80</i>
7		Remove & Refit Aircond System	300.00 <i>150</i>
8		Remove & Refit Reverse Sensor	150.00 <i>60</i>
			\$ 7,190.00
		GRAND TOTAL	\$ 41,552.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

13,908
300
100
970
4470

19748
20%
15798

L/S - 15,800

17 DAYS

Rasm

Htp 90010068

17 days

4/5

19/03/2020 @ 17/10

Rasm after repair