

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 22 Jul 2020

Preliminary Advice

Insured Vehicle No : GBD5339X

TP Vehicle No : PC8853Y

Make : TOYOTA HIACE

Date of Inspection : 19/03/2020

Inspection At : Vfix Auto Pte Ltd (HQ)
26 Chia Ping Road
Singapore 619977

Accident Date : 17/03/2020

Assignment Date : 19/03/2020

Est. Duration of Repair : 17 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front o/s & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	41,552.40
Revised Amount	:S\$	19,748.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	19,748.00

Lump Sum Repair :S\$ 15,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP