

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33279

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0304/2020/NS
Date : 19-Mar-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no : SMF 4881 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Kester Andrew Lim Tan
Address : 10 Lakeshore View
Singapore 098152
Telephone : (HP) +65 91822086
Type of Claim : Third Party Claims
Policy No. : GA531333/1
Vehicle No : **SLM 69 S**
Model Code : Audi S4 Sedan 3.0 TFSI QU
Model / Year : 9/3/2017
Engine No : CWG 003119
Chassis No : WAUZZZF47HA095266
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Mar-20
Place of Accident : Allanbrooke Road Towards Sentosa Cove

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLM 69 S

S/n	Nature of Jobs		Estimated Charges	Survivor's Recommendations
1	To carry out first measurement test on car o-liner	S/N \$	800.00	X
2	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	✓
3	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	X
4	To install solar film for rear windscreen.	S/N \$	400.00	X
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	?
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	?
SUB TOTAL LABOUR CHARGES		:	<u>\$ 4,960.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLM 69 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
7	To place vehicle on car o-liner.	S/N \$ 2,400.00	X
8	To install rear lid top spoiler.	S/N \$ 480.00	✓
9	To dismantle and renew rear bumper and rear lid. Cut out and weld rhs rear fender and rear end panelling. Re-organise crash management components. Reinstall all parts removed.	\$ 7,700.00	2000 (Ry's End Panel) 2500 (End Panel Ryshad)
10	To respray rear bumper, rear lid, hinges, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel end panelling and spare wheel housing. To carry out stone chip treatment and joint sealer works.	\$ 6,350.00	2750.
11	To re-align rhs rear exhaust silencer to position.	S/N \$ 280.00	?
12	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 22,362.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 69 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER <i>rehd</i>	\$ 2,687.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 69.00	+
3	REAR BUMPER SECURING STRIP ?	\$ 210.00	?
4	REAR BUMPER TRIM <i>at</i>	\$ 275.00	✓
5	REAR BUMPER TRIM - LH / RH ?	2 \$ 76.00	?
6	REAR LIGHT REFLECTOR - LH / RH <i>new</i>	2 \$ 78.00	+
7	REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2 TBC	+
8	REAR BUMPER CARRIER ?	\$ 955.00	?
9	REAR BUMPER CARRIER SEAL ?	2 \$ 26.00	?
10	REAR BUMPER GUIDE SECTION - LH	\$ 41.00	+
11	REAR BUMPER GUIDE SECTION - RH	\$ 43.00	+
12	REAR BUMPER GUIDE SECTION - LH / RH <i>2 new</i>	2 \$ 42.00	+
13	TAILGATE OPENING SENSOR LINE <i>new</i>	\$ 194.00	+
14	BOOT LID CONTROL UNIT	\$ 396.00	+
15	REAR LID <i>Dented</i>	\$ 2,496.00	✓
16	REAR LID HINGE - LH / RH <i>new</i>	2 \$ 432.00	+
17	REAR LID LOCK	\$ 217.00	+
18	REAR LID LOCK STRIKER <i>2 new</i>	\$ 31.00	+
19	REAR LID FLAP GASKET	\$ 193.00	+
20	PACKING ADHESIVE <i>new</i>	\$ 18.00	✓
SUB TOTAL SPARE PARTS		: \$ 8,479.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 69 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	AUDI EMBLEM <i>2 new</i>	\$ 117.00	✓
22	S4 INSCRIPTION	\$ 117.00	✓
23	REAR LID SPOILER <i>Not new</i>	TBC	✗
24	LED TAIL LIGHT - LH / RH OUTER <i>cut</i>	2 \$ 1,918.00	✓
25	TAIL LIGHT TRIM - LH / RH OUTER <i>cut</i>	2 \$ 56.00	✓
26	LED TAIL LIGHT - LH / RH INNER <i>cut</i>	2 \$ 1,918.00	✓
27	TAIL LIGHT TRIM - LH / RH INNER <i>cut</i>	2 \$ 56.00	✓
28	REAR CROSS PANEL ?	\$ 245.00	?
29	CROSS PANEL REINFORCEMENT ?	\$ 475.00	?
30	REAR CROSS PANEL TRIM ?	\$ 156.00	?
31	SIDE PANEL -RH <i>Regis</i>	\$ 2,518.00	✗
32	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 86.00	✗
33	REAR SIDE PANEL REINFORCEMENT - RH <i>Regis</i>	\$ 194.00	✗
34	SIDE PANEL SUPPORT - RH <i>new</i>	\$ 92.00	✗
35	REAR WINDSCREEN <i>2</i>	\$ 1,085.00	✗
36	SIDE WINDOW - RH <i>new</i>	\$ 579.00	✗
37	PRIMER	2 \$ 37.00	✗
38	EXHAUST SILENCER BRACKET ?	\$ 40.00	?
39	REAR BUMPER LOWER DIFFUSAL <i>cracked</i>	\$ 2,180.00	✓
40	EXHAUST TIP ?	\$ 4,680.00	?
SUB TOTAL SPARE PARTS		: \$ 16,549.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 69 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	ACRYLIC SEALANT ?	S/N \$ 180.00 ?	
42	CAVITY WAX ?	S/N \$ 140.00 ?	
43	STONE CHIP ?	S/N \$ 180.00 ?	
44	METAL FILLER POWDER ?	S/N \$ 280.00 ?	
45	REAR WINDSCREEN SEALANT <i>new</i>	S/N \$ 200.00 <i>+</i>	
46	1/4 GLASS SEALANT <i>new</i>	S/N \$ 100.00 <i>+</i>	
47	REAR NO PLATE <i>new</i>	S/N \$ 60.00 <i>+</i>	
48	SUNDRIES ?	\$ 600.00 ?	
TOTAL SPARE PARTS		: \$ 26,768.00	
TOTAL LABOUR CHARGES		: \$ 22,362.00	
GRAND TOTAL		: \$ 49,130.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 24/03/2011
Authorised Date :
Excess Cost :
Liability :
Remarks : Xire Authorised, 05 Days (End Panel Reps)
08 Days. (End Panel Replanned)

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 62501198 / Fax : +65 62501081

E-mail : sales@maximusracing.com

Company Registration No. : 200507694R

Sold To: Mr Kester Lim - 91822086

Car make and model: **Audi S4**Vehicle Registration No.: **SLM 69 S //**

Tax Invoice No: M-18-16352

Date: 06/08/2018

Terms: Cash

Mileage:

S: Daphne

GST Reg No. 20-057694-R



Item	Description	Qty	Unit Price	Total Price
1	Milltek Audi S4 - 3.0 T V6 B9 - (Sports Diff Models) <i>LTA Compliant</i> <i>Cat-Back Resonated with Quad JET-100 Carbon Trims</i> System Number: SSXAU721	1set		\$ 4,680.00
Paid - \$3,503.20 - 06/08/2018 - Fund Transfer				
E. & O.E.				
Sub-Total				\$ 4,680.00
Add GST 7%				\$ 327.60
Grand Total:				\$ 5,007.60

Please Visit our website @ www.MaximusRacing.com**TERMS & CONDITIONS:**

Some products are made exclusively for off-road use, we do not accept any claims/liabilities from their usage.

Do not use the product except in specified car types. We reserve the rights to dispose of goods/parts unclaimed after 3 months.

Maximus Racing Pte Ltd will not accept any claims and/or responsibility arising therefrom.**Any Deposit paid are strictly non-refundable!!**

Payment by CHEQUES should be crossed and made payable to MAXIMUS RACING PTE LTD

Goods or Parts sold are not returnable nor refundable!

We reserve the rights to charge 1.5% interest per month on all overdue accounts.

Received and agreed to all above charges and sales terms.

Authorised By:

Receiver's Signature

INVOICE//INV20201874



Division Euro Kit

15 Kaki Bukit Road 4 #01-36
Singapore 417808

Email sales@dek.com.sg
UEN 53387741E
Phone No +65 9138 0338
Website www.facebook.com/DivisionEuroKit



CUSTOMER

Kester (Audi S4 B9)

Invoice No INV20201874
Date 08/01/2020
Term Due on Receipt
Due On 08/01/2020

#	ITEM	QTY	RATE (S\$)	TOTAL (S\$)
1	Audi S4 B9 Karbel Carbon Fiber Rear Diffuser	1	2,180.0000	2,180.00
SUB TOTAL				S\$ 2,180.00
GRAND TOTAL				S\$ 2,180.00