

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33279

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0304/2020/NS
Date : 19-Mar-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no : SMF 4881 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

*We took 28 days 1 PH 6 Sundays
Pls refer to Allan for details
jb 16 Jan 21*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Kester Andrew Lim Tan
Address : 10 Lakeshore View
Singapore 098152
Telephone : (HP) +65 91822086
Type of Claim : Third Party Claims
Policy No. : GA531333/1
Vehicle No : **SLM 69 S**
Model Code : Audi S4 Sedan 3.0 TFSI QU
Model / Year : 9/3/2017
Engine No : CWG 003119
Chassis No : WAUZZZF47HA095266
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Mar-20
Place of Accident : Allanbrooke Road Towards Sentosa Cove

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLM 69 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To carry out first measurement test on car o-liner	S/N \$ 800.00	
2	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
3	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00	
4	To install solar film for rear windscreen.	S/N \$ 400.00	
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00	\$ 1,400.00
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	
SUB TOTAL LABOUR CHARGES		: \$ 4,960.00	\$ 1,760.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLM 69 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
			\$ 1,760.00
7	To place vehicle on car o-liner.	S/N \$ 2,400.00	
8	To install rear lid top spoiler.	S/N \$ 480.00	\$ 480.00
9	To dismantle and renew rear bumper and rear lid. Cut out and weld rhs rear fender and rear end panelling. Re-organise crash management components. Reinstall all parts removed.	\$ 7,700.00	\$ 3,000.00
10	To respray rear bumper, rear lid, hinges, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel end panelling and spare wheel housing. To carry out stone chip treatment and joint sealer works. <i>(Both end panel replaced)</i>	\$ 6,350.00	\$ 2,750.00
11	To re-align rhs rear exhaust silencer to position.	S/N \$ 280.00	\$ 280.00
12	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
13	Added labour -	\$ 1,800.00	\$ 1,200.00
	TOTAL LABOUR CHARGES	: \$ 22,362.00	\$ 9,662.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 69 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,687.00	\$ 2,149.60
2	REAR BUMPER FIXING PARTS	\$ 69.00	
3	REAR BUMPER SECURING STRIP	\$ 210.00	
4	REAR BUMPER TRIM	\$ 275.00	\$ 219.60
5	REAR BUMPER TRIM - LH / RH	2 \$ 76.00	
6	REAR LIGHT REFLECTOR - LH / RH	2 \$ 78.00	\$ 61.28
7	REAR PARKING AID SENSOR - INNER / OUTER	2 TBC	
8	REAR BUMPER CARRIER	\$ 955.00	\$ 675.60
9	REAR BUMPER CARRIER SEAL	2 \$ 26.00	\$ 20.80
10	REAR BUMPER GUIDE SECTION - LH	\$ 41.00	
11	REAR BUMPER GUIDE SECTION - RH	\$ 43.00	
12	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 42.00	\$ 33.12
13	TAILGATE OPENING SENSOR LINE	\$ 194.00	
14	BOOT LID CONTROL UNIT	\$ 396.00	
15	REAR LID	\$ 2,496.00	\$ 1,996.80
16	REAR LID HINGE - LH / RH	2 \$ 432.00	
17	REAR LID LOCK	\$ 217.00	
18	REAR LID LOCK STRIKER	\$ 31.00	
19	REAR LID FLAP GASKET	\$ 193.00	
20	PACKING ADHESIVE	\$ 18.00	\$ 14.24
SUB TOTAL SPARE PARTS		: \$ 8,479.00	\$ 5,171.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 69 S

		<u>Damaged Parts & Prices</u>		
S/N	Parts Description		S/Nett	Remarks
		<i>c/f</i>		\$ 5,171.04
21	AUDI EMBLEM	\$	117.00	\$ 93.20
22	S4 INSCRIPTION	\$	117.00	\$ 93.20
23	REAR LID SPOILER		TBC	
24	LED TAIL LIGHT - LH / RH OUTER	2 \$	1,918.00	\$ 1,534.40
25	TAIL LIGHT TRIM - LH / RH OUTER	2 \$	56.00	\$ 44.32
26	LED TAIL LIGHT - LH / RH INNER	2 \$	1,918.00	\$ 1,534.40
27	TAIL LIGHT TRIM - LH / RH INNER	2 \$	56.00	\$ 44.32
28	REAR CROSS PANEL	\$	245.00	\$ 195.60
29	CROSS PANEL REINFORCEMENT	\$	475.00	\$ 380.00
30	REAR CROSS PANEL TRIM	\$	156.00	
31	SIDE PANEL -RH	\$	2,518.00	
32	WHEEL HOUAING LINER ATTACHMENT PARTS	\$	86.00	
33	REAR SIDE PANEL REINFORCEMENT - RH	\$	194.00	\$ 154.80
34	SIDE PANEL SUPPORT - RH	\$	92.00	
35	REAR WINDSCREEN	\$	1,085.00	
36	SIDE WINDOW - RH	\$	579.00	
37	PRIMER	2 \$	37.00	
38	EXHAUST SILENCER BRACKET	\$	40.00	
39	REAR BUMPER LOWER DIFFUSAL	\$	2,180.00	\$ 2,180.00
40	EXHAUST TIP	\$	4,680.00	
SUB TOTAL SPARE PARTS		:	\$ 16,549.00	\$ 11,425.28

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SLM 69 S

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0304/2020/NS 27-Mar-20 Glory Tan 1 of 1 SLM 69 S Audi S4 Sedan 3.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Labours</u> 1	To put vehicle on cellete bench for repair.	\$ 1,800.00	\$ 1,200.00
TOTAL		\$ 1,800.00	\$ 1,200.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant