

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2020		02 Apr 2020 12:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: WRICK PTE LTD , Co. Reg. No.: 0									
Vehicle Reg. No.: GBK1285G		Date of Loss: 16/03/2020 18:00 - :59 [2 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM20D201343C01		Policy/Cover Note No.: DMCVSNW00002211900 (Comprehensive)							
		Excess: S\$350.00							
Repairer: Tan Chong Motor Sales Pte Ltd (HQ) 911 BUKIT TIMAH ROAD, 589623 Bukit Timah - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 14/04/2020]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
CHINA_TAIPIING (08/04/2020): Alert - Adj Mandate Approved (S\$0.00) - GBK1285G - Claim Handler: Irene Tay Hui ...									
ALL ASSOCIATED TASKS ☐									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBK1285G (SNM20D201343C01)

OD

Mar 16 2020 6:00PM

[WRICK PTE LTD]

Tan Chong Motor Sales Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/20 13:28	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/20 13:31	General View	 Load JPG	✓
2	02/04/20 13:31	General View	 Load JPG	✓
3	02/04/20 13:31	General View	 Load JPG	✓
4	02/04/20 13:31	General View	 Load JPG	✓
5	02/04/20 13:31	General View	 Load JPG	✓
6	02/04/20 13:31	General View	 Load JPG	✓
7	02/04/20 13:31	General View	 Load JPG	✓
8	02/04/20 13:31	General View	 Load JPG	✓
9	02/04/20 13:31	General View	 Load JPG	✓
10	02/04/20 13:31	General View	 Load JPG	✓
11	02/04/20 13:31	General View	 Load JPG	✓
12	02/04/20 13:31	General View	 Load JPG	✓
13	02/04/20 13:31	General View	 Load JPG	✓
14	02/04/20 13:31	General View	 Load JPG	✓
15	02/04/20 13:31	General View	 Load JPG	✓
16	02/04/20 13:31	General View	 Load JPG	✓
17	02/04/20 13:31	General View	 Load JPG	✓
18	02/04/20 13:31	General View	 Load JPG	✓
19	02/04/20 13:31	General View	 Load JPG	✓
20	02/04/20 13:31	General View	 Load JPG	✓
21	02/04/20 13:31	General View	 Load JPG	✓
22	02/04/20 13:31	General View	 Load JPG	✓
23	02/04/20 13:31	General View	 Load JPG	✓
24	02/04/20 13:31	General View	 Load JPG	✓
25	02/04/20 13:31	General View	 Load JPG	✓
26	02/04/20 13:31	General View	 Load JPG	✓
27	02/04/20 13:31	General View	 Load JPG	✓
28	02/04/20 13:31	General View	 Load JPG	✓
29	02/04/20 13:31	General View	 Load JPG	✓
30	02/04/20 13:31	General View	 Load JPG	✓
31	02/04/20 13:31	General View	 Load JPG	✓
32	02/04/20 13:31	General View	 Load JPG	✓
33	02/04/20 13:31	General View	 Load JPG	✓
34	02/04/20 13:31	General View	 Load JPG	✓
35	02/04/20 13:31	General View	 Load JPG	✓
36	02/04/20 13:31	General View	 Load JPG	✓
37	02/04/20 13:31	General View	 Load JPG	✓
38	02/04/20 13:31	General View	 Load JPG	✓

Assessment Reports				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
39	02/04/20 13:31	General View		Load JPG	☒
40	02/04/20 13:31	General View		Load JPG	☒
41	02/04/20 13:31	General View		Load JPG	☒
42	02/04/20 13:31	General View		Load JPG	☒
43	02/04/20 13:31	General View		Load JPG	☒
44	02/04/20 13:31	General View		Load JPG	☒
45	02/04/20 13:31	General View		Load JPG	☒
46	02/04/20 13:31	General View		Load JPG	☒
47	02/04/20 13:31	General View		Load JPG	☒
48	02/04/20 13:31	General View		Load JPG	☒
49	02/04/20 13:31	General View		Load JPG	☒
50	02/04/20 13:31	General View		Load JPG	☒
51	02/04/20 13:31	General View		Load JPG	☒
52	02/04/20 13:31	General View		Load JPG	☒
53	02/04/20 13:31	General View		Load JPG	☒
54	02/04/20 13:31	General View		Load JPG	☒
55	02/04/20 13:31	General View		Load JPG	☒
56	02/04/20 13:31	General View		Load JPG	☒
Documentation				1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/04/20 13:29	GBK 1285G GIA.pdf		Load PDF	
2	02/04/20 13:29	TOTAL LOSS LETTER.pdf		Load PDF	
3	02/04/20 13:29	DRIVING & CI .pdf		Load PDF	
4	16/04/20 11:38	LTA REBATE		Load PDF	
5	16/04/20 13:03	LETTER		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20004263/ESD3S2**Date:** 16/04/2020**REFERENCE**

Insured/Claimant: WRICK PTE LTD Policy No: DMCVSNW00002211900
Date of Loss: 16/03/2020 Nature of Claim: OD Claim No: SNM20D201343C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK1285G**
Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KE628D721782
Reg. Date: 31/12/2019 (Man. Year: 2019) Chassis No: VSKYBAM20Z0181087
Colour: Silver Odometer: 4301 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/04/2020

Date Inspected: 20/03/2020

Inspected At:

Tan Chong Motor Sales Pte Ltd (HQ)
913 BUKIT TIMAH ROAD
Singapore 589623

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$ 57,000.00
OMV :	\$ 20,548.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$ 23,200.00
COE Rebate (2) :	\$ 22,701.00
Total Rebate (1) + (2) = :	\$ 22,701.00

The total amount incurred will be Market Value \$ 57,000.00 minus Total Rebate \$ 22,701.00 = \$ 34,299.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Apr 2020)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK1285G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >