

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUTO	O & GENERAL IN:	SURANCE (S) PL	Ref : CS/AGI20004265/h	CS/AGI20004265/Ksd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 08-04-2020		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJH 7157A	Veh. Inspected	SMG 7163B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10005967	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	19/03/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	GP72002106	Colour	METALLIC PEARL WHITE	
	Odometer	116171	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA	7 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA	7 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/03/2020	Inspection Date	20/03/2020	
	Survey held at KUM CHEW MOTOR WORKSHOP				
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: