Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| | Notified | Est Submitted | Adj Assigned | Adj Rpt | | [Au] St | ubmitted | Ins Auth'ed | | Pending for Survey Report Cancel Case | |
|-----------------------------------|---------------------------|------------------|--------------------------------------|----------------------------|-----------------------|---------|--------------------------------------------------------------------------------------------|------------------|-----------------|---------------------------------------|------------|
| Main | 9 Mar 2020 Edit Reg | | 19 Mar 2020 00:00 Edit Adj Rpt | S\$0.00 Edit Es | timates | S\$0.0 | Ppt | | | | |
| M | lain | R | eference | | laim Deta | ails | | Documer | nts | \supset | Show All |
| CLAIM SUE | FOLDER DE | TAILS | | | | [| Created I | by adjuster] | and the same of | Line Tennin | |
| nsured: | FULCO LE | ASING PTE LTD, | Co. Reg. No.: 20 | 1021308G | | | | | | | |
| Main Claimant: | | ¥ | | | | | | | | | |
| /ehicle Reg. No.: | GBC445 | GBC4459U | | | Date of L | | 04/03/2020 00:00 - :59 [94 Months and 4 Days From LTA Reg Date (Man Yr)] | | | | |
| Claim Type: | Policy/Cover Note No.: 09 | | | 0999993928 (Comprehensive) | | | | | | | |
| /ehicle Reg. No. (Insured): | GBG3009 | x | | | Policy No (Claiman | | | | | | |
| | | | | | Excess: | | | | | | |
| Repairer: | A-Tec Aut | omotive Pte Ltd | (Kaki Bukit) 8 Ka | ki Bukit Ave | 4, #04-2 | 0 Prem | ier, 41587 | 5 Kaki Bukit - T | Tel: | | |
| Handling Insurer: | AIG Asia | Pacific Insuranc | e Pte. Ltd. (Expre | ess) - Tel: 6 | 5-6419-30 |)00 [| [Handled b | y MdNoor, No | rsiah] | Norsiah.Mdl | Noor@aig.c |
| Adjuster: | 30/03/20 | | Ltd (HQ) - Tel: 62 | 256-3561 | . [Handled | by PAI | RASURAM | SHANMUGAM | 1] [F | inal Rpt | due |
| ASSOCIATI | ED MAIL RE | CEIVED | | | | | | \ | /iew All | Compo | se Case Ma |
| There are no | mail for this | case. | | | | | | | | | |
| ALL ASSO | CIATED TAS | ks⊟ | | | | Mic | ew All S | earch Tasks | Croate | e New Task | Complet |

No results.

Page 1 of 1 Merimen e-Claims

Claim Documents

*GBC4459U (7858459055SG) [GBG3009X] TP

Mar 4 2020 12:00AM [FULCO LEASING PTE LTD] A-Tec Automotive Pte Ltd

| Up | oload Documents U | oload Photos Compose New Letter Upload Video Upload A | Nudio | View in Brows | er 🗸 |
|-----|-------------------|-------------------------------------------------------------|-------|---------------|----------|
| Vid | eo | | 1 per | page 🔻 | ✓ |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | Thumbnail | Print |
| 1 | 20/03/20 18:54 | Video - Accident | 0 | Load MP4 | |
| | - | | | | |
| Dod | cumentation | | 1 per | page 🔻 | ✓ |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 20/03/20 14:46 | GIA REPORT | 0 | Load PDF | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | Thumbnail | Print |
| 1 | 20/03/20 18:53 | OI GIA REPORT | 0 | Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| | | | ^ |
| | | | ~ |
| Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties. | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG20004267/FVD3E2

Date:

25/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999993928

Claimant Vehicle

GBC4459U

Insured Vehicle No:

GBG3009X

Date of Loss:

04/03/2020

Nature of Claim:

TP

Claim No: 7858459055SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

GBC4459U

Make & Model:

NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR

Engine No:

K9KF276D126495

151431 km

Reg. Date:

30/04/2012 (Man. Year: 2011)

Chassis No: Odometer:

VSKYBAM20U0031172

Colour: **Engine Capacity:** White

EURO 5 (M)

1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Rear Tyre Size:

175/70 R14C

Front Tyre Size: Front Left Side:

Goodyear 6 mm

175/70 R14C

Rear Left Side:

Goodyear 7 mm

Front Right Side:

Goodvear 6 mm

Rear Right Side:

Goodyear 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment:

19/03/2020

Date Inspected:

19/03/2020 Inspected At:

A-Tec Automotive Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #04-20 Premier

Singapore 415875

Estimated Period of Repair:

3.0 days

Adjuster: PARASURAM SHANMUGAM Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty Part No | . Particulars | Condition | Repairer's | Amount |
|-------|---------------|------------------------------|----------------------------|------------|--------|
| 1 | 1 | *FRT BUMPER | Cut / Scratched / Deformed | 0.00 F | *-F |
| 2 | 1 | *FRT BUMPER CLIP | Necessary | 0.00 F | *- F |
| 3 | 1 | *FRT BUMPER SPONGE | Cracked | 0.00 F | *- F |
| 4 | 1 | *FRT BUMPER SIDE RETAINER LH | Necessary | 0.00 F | *- F |
| 5 | 1 | *FRT LH BUMPER FOG LAMP | Cut | 0.00 F | *- F |
| F=Fra | anchise part. | | Total Parts (S\$) | 0.00 | 0.00 |

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >