

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 34419

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0345/2020/NS
Date : 30-Mar-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SDQ 3118 M

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chee Wing Tuck Samuel
Address : 32 Dover Rise
#09-09
Singapore 138686
Telephone : (HP) +65 84996733
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SMS 4285 P**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : 26/2/2020
Engine No : CVK 087930
Chassis No : WAUZZZF4XKA116523
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Mar-20
Place of Accident : B1 Carpark Gleneagles Hospital

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMS 4285 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	500
3	To respray front bumper and lhs front fender.	\$ 2,000.00	1100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 5,122.00</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMS 4285 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,068.00	× R
2	FRONT BUMPER FIXING PARTS	\$ 553.00	× NN
3	FRONT BUMPER AIR GUIDE - LH	\$ 59.00	× NN
4	FRONT BUMPER SECURING STRIP	2 \$ 67.00	× NN
5	FRONT FENDER - LH	\$ 722.00	× R
6	FRONT FENDER CLOSING ELEMENT - LH	\$ 47.00	× NN
7	FRONT FENDER BRACKET - LH	\$ 33.00	× NN
8	FENDER LEDGE COVER - LH OUTER	\$ 29.00	× NN
9	FENDER LEDGE COVER	\$ 21.00	× NN
10	LED HEADLIGHT - LH	\$ 7,321.00	× NN
11	FRONT BUMPER GUIDE SECTION - LH	2 \$ 34.00	? × NN
12	SUNDRIES	\$ 200.00	? × NN
TOTAL SPARE PARTS		: \$ 11,154.00	
TOTAL LABOUR CHARGES		: \$ 5,122.00	
GRAND TOTAL		: \$ 16,276.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Steve (LKK)
Surveyed Date : 25/03/20
Authorised Date : Without Prejudice
Excess Cost : P/P
Liability : Resurvey Before Spray
Remarks : 4 Repair Days

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant