

LEE HONG & CO MOTOR SERVICE

Blk 9 Sin Ming Road
#01-36 Sin Ming Industrial Estate
Singapore 575644.

T. (65) 6458 8460
F. (65) 6455 5379
E. leehong36@rocketmail.com

Date	13-Jul-2016	Ref.:	TP Claim
------	-------------	-------	----------

Owner Particulars			
Name	Lim Hock Poh	Mobile No.	96787322
# Nos	S1299355B	Date of Birth	19/6/1958
Address	Blk 341 Clementi Avenue 5		
	#07-160		
	Singapore 120341		

Vehicle Particulars	
Number	SGE 6916J
Model	MITSUBISHI LANCER 1.6 A
Engine	4G18HB7742
Chassis	JMYSTCS3A6U006984
Year	23-Mar-06

Accident Details	
Date	12 July, 2016
Time	14.30 Hrs
Place	Junction of Tuas West Road And Tuas Link 4

Insured With	
Insurance	AXA insurance Singapore Pte Ltd
Policy No.	VA1/GA093684
Expiry	22 March, 2017

Driver Particulars		
Name	As Above	Mobile No.
Nric Nos.		Date of Birth
Address		

Parts & Labour Costs			
List Prices			\$ 9,868.25
Nett Prices			\$ -
Special Nett Prices			\$ 1,325.10
Labour Charges			\$ 4,190.00
Total			\$ 15,383.35

Estimate Cost Of Repairs		Vehicle #	SGE 6916J
QTY	DESCRIPTIONS	UNITS	AMOUNTS
	NETT		
1 pce	Rear bumper		\$ ✓ 731.00
1 pce	Rear bumper reinforcement		\$ ✓ 268.00
2 pcs	Rear bumper side retainers	\$ 39.00	\$ ✓ 78.00
1 pce	Rear bumper spoiler		\$ ✓ 653.00
2 pcs	Rear Lamps	\$ 398.00	\$ ✓ 796.00
1 pce	Boot lid		\$ ✓ 582.00
2 pcs	Boot lid hinges	\$ 88.00	\$ X 176.00
1 pce	Boot lid top lock		\$ ✓ 58.00
1 pce	boot lid bottom lock		\$ ✓ 18.00
1 pce	Boot lid rubber		\$ ✓ 139.00
1 pce	Boot lid 'Lancer' name plate		\$ ✓ 25.20
1 pce	Boot lid Badge		\$ ✓ 38.00
1 pce	Boot lid 'GLX' emblem		\$ ✓ 25.00
1 pce	Boot lid 'Ralli-Art' name plate		\$ ✓ 73.40
1 pce	Boot lid licence plate garnish		\$ ✓ 100.00
2 pcs	Licence plate lamps	\$ 48.00	\$ X 96.00
1 pce	Rear panel		\$ ✓ 398.00
2 pcs	Pear lamp panels	\$ 67.00	\$ ✓ 134.00
1 pce	Rear panel top garnish		\$ ✓ 140.00
1 pce	Rear panel inner trim cover		\$ X 141.00
2 pcs	Rear fenders	\$ 621.00	\$ ✓ 1,242.00
2 pcs	Rear fender reinforcement plates	\$ 141.00	\$ X 282.00
2 pcs	Rear fender inner trim covers	\$ ✓ 212.00	\$ X 424.00
1 pce	Boot floor panel		\$ X 659.00
1 pce	Spare tyre hardboard		\$ ✓ 141.00
1 pce	Rear exhaust pipe		\$ T 459.00
1 pce	Rear exhaust centre pipe		\$ X 491.00
3 pcs	Rear exhaust pipe mountings	\$ 28.00	\$ ✓ 56.00
1 pce	Rear windscreen moulding		\$ ✓ 28.00
1 pce	Rear windscreen inner rubber beading		\$ ✓ 38.10
2 pcs	Front seat sliding rail	✓ \$ 710.00	\$ ✓ 1,420.00
2 pcs	Front seat reclining gear	✓ \$ 850.00	\$ ✓ 1,700.00
			\$ 11,609.70
		Less 10%	\$ 1,741.46
			\$ 9,868.25
	S NETT		
1 pce	Boot lid Spoiler		\$ 850.00
1 pce	Rear exhaust chrome pipe		\$ — 67.00
1 pce	Rear number plates		\$ ✓ 50.00
1 set	Reverse sensors		\$ 240.00
1 pce	Rear windscreen sealant		\$ ✓ 80.00
1 pce	Rear windscreen inner rubber beading		\$ X 38.10

def
bt
dis
res.
over
bt
R
bt
bt
dis
ne
ne
ne
dis
bt
bt
dis
dis
R
R
bt
ne
ne
200
200 / 200

600
bt
bt
200
40

	Labour			
	Towing Charges		\$ 80.00	60
	To remove damaged lamps and necessary wirings to enable necessary repairs, check, Replace damaged lamps and refit.		\$ 50.00	30
	To remove both front seats, repair seat frame, check, replace sliding rail and reclining gear assy., refit same.		\$ 240.00	X 120
	To remove rear seats and backrest, rear parcel tray, garnishes and necessary interior upholstery to enable repair and replace of parts, refit same., including cleaning and vacuum up interior compartment.		\$ 220.00	120
	To remove rear windscreen glass assy., to Enable necessary repairs, check, refit glass Assy. (Bonded type windscreen glass)		\$ 150.00	120
	To check wheel alignment – computerize.		\$ 80.00	X
	To check and re-align body structure on chassis alignment sysyems.		\$ 350.00	✓ 200
	To remove rear exhaust pipe and silencer assy., Check, replace same with mounting and refit.		\$ 180.00	80
	To remove damaged parts, jack and cut out damaged body panels, jack out, straighten up damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and realign whichever parts necessary.	NA Authored US Repw. After PWA Photo 466477 89 weeks 15/7/2016	\$ 1,200.00	1100
	To spray painting replacement parts and repaint damaged sections with welded portions in and outside, including putty.		\$ 1,400.00	1200
	To perform a computerise systems checking after removing of necessary wirings and Electrical fittings to enable necessary diagnosing and re-setting to specifications		\$ 120.00	X
	To rust proofing damaged portions and replacement parts		\$ 120.00	100
			\$ 15,383.35	

15,963.83#