

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

18 MAR 2020

ESTIMATE

Estimate No. : b1 54843 Estimated : 18/03/2020 Prepared By : Inthiran A/L Thurasamy		Page No. : 1 of 5
ESTIMATE REPAIR FOR - HAOFENG Choa Chu Kang Road Singapore 689106		- ACCOUNT - 303 MS First Capital Insurance Limited 6 Raffles Quay #21-00 Singapore 048580

Y. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
573B	WBA6V12020ED05730	28/03/2019	216i GT	0

DESCRIPTION

To replace front bumper, rear bumper and attachments.

Painting front bumper and rear bumper.

To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

Sundries.

VALUE

1700 2,580.00

1868 2,076.00

250 295.00

150 171.00

₹ 80.00

Total Labour 1: 5,178.00

DESCRIPTION

IMPACT ABSORBER TOP ~~X~~ svc

FRT BUMPER PRIMED PANEL (PMA) ~~de~~

REAR BUMPER CARRIER ~~bt~~

SUPPORT ~~✓~~ cra

REAR BUMPER TOWING FLAP EYE PRIMED ~~X~~ nn

REAR BUMPER TRIM STRIP (BLACK) ~~se~~

REAR BUMPER PANEL PRIMED (LINES PDC) ~~de~~

FRT LH GRILLE (SPORT) ~~cr~~

FRT RH GRILLE (SPORT) ~~cr~~

PLAQUE 82MM ~~re~~

QTY	PRIC	VALUE
1	49.30	49.30
1	897.25	897.25
1	460.40	460.40
1	45.55	45.55
1	43.05	43.05
1	72.20	72.20
1	1,045.45	1,045.45
1	112.65	112.65
1	112.65	112.65
1	71.60	71.60

Total Parts : 2,910.10



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 54843**
Date Estimated : **18/03/2020**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK573B	WBA6V12020ED05730	28/03/2019	216i GT	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/06/2020 @ 1050 Excess S\$ _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 90010568 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes Part Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

Labour 1	:	5,178.00
Parts	:	2,910.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	566.17
Grand Total	:	8,654.27