

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO 42 SUNGEI KADUT ST 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
 SHD 5264G -

*Not Authorized* Andrea  
*61 Sing & 1750h*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD 5264G - Andrea**  
**JTDGJ20WX805001962\***  
**TOYOTA**  
**WISH 2.0 BI-FUEL**  
**22.07.2013**  
**AXA**

		PART		LIST
1	1	Front Bumper	\$	<i>R</i> 585.36 ✓
2	1	Front Bumper Retainer RH	\$	<i>Sm</i> 74.50 X
3	1	Front Fender RH	\$	<i>As</i> 837.60 ✓
4	1	Front Fender Liner	\$	<i>CM</i> 369.14 ✓
5	1	Front side rocker panel garnish RH	\$	<i>Sm</i> 614.28 X
6	1	Front Door RH	\$	<i>R</i> 1,554.00 X
7	1	Front Side View Mirror RH	\$	<i>Sm</i> 874.43 X
			TOTAL	\$ 4,909.31
			<i>10%</i>	\$ 490.93
			<i>25%</i>	\$ 4,418.38

*100 100*  
*90 75*

### Specical Nett

1 Set	Front Bumper Fastener Clip	\$	<i>nn</i> 20.00 X
1	CNG Sticker	\$	<i>nn</i> 15.00 ✓
4	Front Fender Liner Clip RH	\$	<i>nn</i> 30.00 ✓
1	Front Tyre	\$	<i>Lot</i> 180.00 <i>70 liter</i>
1	Front Tyre Rim	\$	<i>lip</i> <i>RV</i> 120.00 <i>50 liter</i>

TOTAL \$ 365.00

**TOTAL PARTS \$ 4,783.38**

Panel Beating, Knocking And Straightening  
 The Necessary Portion, Remove And  
 Renewal Of Parts, Adjust And Realign The  
 same

\$ 2,240.00 *4001*

Labour charge to mount and dismount  
 vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO 42 SUNGEI KADUT ST 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
 SHD 5264G -

**LKK Auto Consultants** here  
**the Repairer of the following:**  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

**Andrea**

To apply paint protection system (PPS)  
 maintain and enhancement

Acknowledged by Repairer

Signature:

\$

380.00 X

Date:

To check ABS brake efficiency, final  
 checking and testing.

\$

380.00 X

To dismantle and refit front end  
 suspension, undercarriage parts, final  
 checking and testing.

\$

380.00 X

To pull and jack out chassis frame and  
 correct it to symmetrical position with the  
 aid of hydraulic pneumatic jack.

\$

380.00 X

To transfer of door fittings, attachment and  
 perform water seepage test.

\$

170.00 X

To Rust-Proofing Of The Affected Areas.

\$

220.00 30%

To Remove And Refit Interior Fittings,  
 Trimings, Garnish, Fittings And Other, To  
 Enable Repair.

\$

380.00 X

Putty And Spray Painting Of The Affected  
 Portion.

\$

2,160.00 54%

To Check Electrical Lighting Concerned.

\$

120.00 15%

To Transfer Of Fender Fittings,  
 Attachments And Perform Water Seepage  
 Test.

\$

170.00 X

To transfer of door fittings, attachment and  
 perform water seepage test.

\$

170.00 X

To check steering geometry and computer  
 wheel alignment

\$

220.00 60%

To transfer of tire, rim and on wheel  
 balancing.

\$

170.00 20%

TRANS-CAB AUTO SERVICES PTE LTD  
NO 42 SUNGEI KADUT ST 1 SINGAPORE 729346  
TEL NO.6287 6666 FAX NO.6366 8862  
CO/GST REG NO.201019626G  
SHD 5264G -

Andrea

TOTAL \$ 7,920.00

Over All Total \$ 12,703.38

REPAIR DAYS

~~6~~ DAYS

3 days