

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 54847**  
Date Estimated : **19/03/2020**  
Prepared By : **Han Kwan Yong**

### - ESTIMATE REPAIR FOR -

**Huang HongLiang**  
**52 Bukit Batok Street 31**  
**#23-12**

**Singapore 659443**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

| REGN. NO.       | CHASSIS NO.              | REGN. DATE        | MODEL          | MILEAGE  |
|-----------------|--------------------------|-------------------|----------------|----------|
| <b>SJQ9878S</b> | <b>WBA2B32060V926372</b> | <b>14/05/2018</b> | <b>216d AT</b> | <b>0</b> |

| DESCRIPTION                                                                                                                                            | ORIGINAL PRICE | DISC. % | NETT     |
|--------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|---------|----------|
| To replace front right door and attachments, front right fender including make good the front bumper and knock out dented area caused by the accident. | 2,125.00       |         | 2,125.00 |
| To respray front bumper, front right fender and front right door.                                                                                      | 2,527.00       |         | 2,527.00 |
| To carry out body cavity preservation (2X)                                                                                                             | 200.00         |         | 200.00   |
| To check steering geometry and conduct wheel alignment in accordance with BMW specification (1X)                                                       | 451.00         |         | 451.00   |
| To replace front right wheel rim including balancing. (1x).                                                                                            | 80.00          |         | 80.00    |
| To check electrical wiring systems at the front section for proper function.                                                                           | 150.00         |         | 150.00   |
| Sundries.                                                                                                                                              | 80.00          |         | 80.00    |

| DESCRIPTION                    | UNIT PRICE | QTY  | DISC. % | NETT     |
|--------------------------------|------------|------|---------|----------|
| ALLOY RIM 7JX16 DOUBLE SPK 473 | 757.00     | 1.00 |         | 757.00   |
| FRT RH FENDER                  | 627.15     | 1.00 |         | 627.15   |
| FRT RH DOOR                    | 1,136.90   | 1.00 |         | 1,136.90 |
| # RIVET                        | 0.50       | 4.00 |         | 2.00     |
| PLAQUE 82MM                    | 71.60      | 1.00 |         | 71.60    |
| FRT DOOR JOINT SEAL            | 32.10      | 1.00 |         | 32.10    |

#### # SUPPLEMENTARY ITEMS

|                                 |          |
|---------------------------------|----------|
| Total Labour :                  | 5,613.00 |
| Total Parts :                   | 2,626.75 |
| Total Labour & Parts :          | 8,239.75 |
| Deduction for Excess :          | 500.00   |
| Total Repair Costs less Excess: | 7,739.75 |
| GST @7%:                        | 541.78   |
| Grand Total :                   | 8,281.53 |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 54847**  
Date Estimated : **19/03/2020**  
Prepared By : **Han Kwan Yong**

### - ESTIMATE REPAIR FOR -

**Huang HongLiang**  
**52 Bukit Batok Street 31**  
**#23-12**

**Singapore 659443**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

| REGN. NO.       | CHASSIS NO.              | REGN. DATE        | MODEL          | MILEAGE  |
|-----------------|--------------------------|-------------------|----------------|----------|
| <b>SJQ9878S</b> | <b>WBA2B32060V926372</b> | <b>14/05/2018</b> | <b>216d AT</b> | <b>0</b> |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|-------------|----------------|---------|------|
|-------------|----------------|---------|------|

| DESCRIPTION   | UNIT PRICE | QTY  | DISC. % | NETT |
|---------------|------------|------|---------|------|
| # RIVET / Nec | 0.50       | 4.00 |         | 2.00 |

### # SUPPLEMENTARY ITEMS

|                        |      |
|------------------------|------|
| Total Labour :         |      |
| Total Parts :          | 2.00 |
| Total Labour & Parts : | 2.00 |