

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 54847
Date Estimated : 19/03/2020
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Huang HongLiang
52 Bukit Batok Street 31
#23-12

Singapore 659443

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJQ9878S	WBA2B32060V926372	14/05/2018	216d AT	0

DESCRIPTION

VALUE

To replace front bumper, front right fender and front right door

2125 3,400.00

To respray front bumper, front right fender and front right door

2527 2,808.00

To carry out body cavity preservation (2X)

200 238.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 531.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

Sundries.

80 / ~~150.00~~

Total Labour 1: 7,398.00

DESCRIPTION

QTY

PRIC

VALUE

ALLOY RIM 7JX16 DOUBLE SPK 473 / COT

1 757.00

757.00

HUB CAP WITH CHROME EDGE X NN

1 29.40

29.40

FRT RH FENDER / 00

1 627.15

627.15

FRT RH DOOR / 00

1 1,136.90

1,136.90

FRT BUMPER PANEL PRIMED (PMA X R

1 897.25

897.25

GROMMET / REC X NN

2 0.80

1.60

FRT RH DOOR EXTERIOR CHANNEL X NN

1 99.80

99.80

RH SEAL A PILLAR X NN

1 48.35

48.35

PLAQUE 82MM / N

1 71.60

71.60

FRT DOOR JOINT SEAL / N

1 32.10

32.10

Total Parts : 3,701.15

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 54847**
Date Estimated : **19/03/2020**
Prepared By : **Han Kwan Yong**Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJQ9878S	WBA2B32060V926372	14/05/2018	216d AT	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No _____ Claim No. _____
 Date & Time 20/3/20, 1.00pm Excess S\$ _____
 Surveyor's Name SPK (LKK) Sign _____
 Surveyor's Tel _____ Authorised Yes / No
 Authorised Date _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
 Surveyor's E-mail _____
 No. of Working Days Recommend _____

00 - Not Auth (PMT)
 Excess - \$500
 P/P
 Ry Del spy



Labour 1	:	7,398.00
Parts	:	3,701.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	776.94
Grand Total	:	11,876.09

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **