

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Mar 2020		01 Apr 2020 17:45 Edit Adj Rpt	S\$1,456.54 Edit Estimates	S\$1,456.54 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:	-, Co. Reg. No.: -			
Main Claimant:	TOWER TRANSIT SINGAPORE PTE LTD , Co. Reg. No.: 201419417K			
Vehicle Reg. No.:	SBS3341Y	Date of Loss:	18/03/2020 13:00 - :59 [82 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM20D201381C02	Policy/Cover Note No.:	DMCVSNW00006672003	
Vehicle Reg. No. (Insured):	YM9025E	Policy No. (Claimant):	D-19094584MFBP/4	
		Excess:	S\$0.00	
Repairer:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot, 648170 Jurong West - Tel: 81688950			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/04/2020]			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

*SBS3341Y (SNM20D201381C02)
[YM9025E]
TP
TOWER TRANSIT SINGAPORE PTE LTD
Mar 18 2020 1:00PM
[-]
Tower Transit Singapore Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Assessment Reports			1 per page ▼	✓
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	19/03/20 08:50	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	19/03/20 08:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
2	19/03/20 08:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
3	19/03/20 08:50	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/20 14:40	General View	 Load JPG	✓
2	02/04/20 14:40	General View	 Load JPG	✓
3	02/04/20 14:40	General View	 Load JPG	✓
4	02/04/20 14:40	General View	 Load JPG	✓
5	02/04/20 14:40	General View	 Load JPG	✓
6	02/04/20 14:40	General View	 Load JPG	✓
7	02/04/20 14:40	General View	 Load JPG	✓
8	02/04/20 14:40	General View	 Load JPG	✓
9	02/04/20 14:40	General View	 Load JPG	✓
10	02/04/20 14:40	General View	 Load JPG	✓
11	02/04/20 14:40	General View	 Load JPG	✓
12	02/04/20 14:40	General View	 Load JPG	✓
13	02/04/20 14:40	General View	 Load JPG	✓
14	02/04/20 14:40	General View	 Load JPG	✓
15	02/04/20 14:40	General View	 Load JPG	✓
16	02/04/20 14:40	Reinspection Photo	 Load JPG	✓
17	02/04/20 14:40	Reinspection Photo	 Load JPG	✓
18	02/04/20 14:40	Reinspection Photo	 Load JPG	✓
19	02/04/20 14:40	Reinspection Photo	 Load JPG	✓
20	02/04/20 14:40	Reinspection Photo	 Load JPG	✓
21	02/04/20 14:40	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	19/03/20 08:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
2	19/03/20 08:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
3	19/03/20 08:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓

Linked Accident Report Documents

View [View in Browser](#) ▼

Assessment Reports				1 per page ▼	✔
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)		Thumbnail	Print
1	19/03/20 08:50	Accident Statement		Load HTM	
Photos/Images				3 per page ▼	✔
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)		Thumbnail	Print
1	19/03/20 08:50	Accident Photo		Load JPG	✔
2	19/03/20 08:50	Accident Photo		Load JPG	✔
3	19/03/20 08:50	Accident Photo		Load JPG	✔
Documentation				1 per page ▼	✔
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)		Thumbnail	Print
1	19/03/20 08:48	Accident Sketch Plan		Load JPG	✔
2	19/03/20 08:48	Accident Sketch Plan		Load JPG	✔
3	19/03/20 08:48	Accident Sketch Plan		Load JPG	✔

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20004278/ETD3S2**Date:** 14/04/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00006672003
Claimant Vehicle No :	SBS3341Y	Insured Vehicle No :	YM9025E
Date of Loss:	18/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201381C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS3341Y	Engine No:	D9189956
Make & Model:	VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)	Chassis No:	YV3S4P926DA160556
Reg. Date:	02/05/2013 (Man. Year: 2013)	Odometer:	427483 km
Colour:	Green		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5/5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	528.38	481.54	46.84	8.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	975.00	975.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,478.38	1,456.54	1,021.84	41.23
+ GST 7.00/7.00% (S\$)	173.49	101.96	71.53	41.23
Nett Amount (S\$)	2,651.87	1,558.50	1,093.37	41.23

INSPECTION

Date of Assignment:	01/04/2020		
Date Inspected:	20/03/2020	Inspected At:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot Singapore 648170
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Apr 2020)	
Parts:	N/A	VOLVO B9TL 9.4 D AUTO TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3341Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S MILLENN 1/4 GLASS	Broken	106.16 F	*106.16 FL
2	1		*O/S MIRROR ELECTRIC	Broken	330.22 F	*330.22 FL
3	2		*SIKAFLEX BLACK	Necessary	32.00 F	*32.00 FL
4	1		*REFLECTOR STICKER	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	528.38	528.38
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	46.84
Total Parts (\$)	528.38	481.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS.	New	1,950.00	975.00
Gross Labour Cost (\$\$)			1,950.00	975.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >