



HUA HONG PRIVATE LIMITED

250 SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: [65] 6661 9688 Fax: [65] 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

19 March 2020

QUOT202003-000025
HHTPCLAIMS20-41

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
3 ANSON RD, #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Attn: Motor Claims Department

ACCIDENT INVOLVING SLM123T & XE5209Y ON 17/03/2020 ALONG SUNGEI KADUT ST 1 AT ABOUT 1040 HOURS

Insured : TAN WEE TAT
Vehicle Registration No. : SLM123T
Vehicle Make : B.M.W.
Vehicle Model : 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Vehicle Chassis No. : WBAXG12080DX53228
Policy No. : MT/00704053
Date of Accident : 17/03/2020

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper / CR4		\$ 1,571.95 ✓
2	2	Rear Bumper Side Retainer (LH/RH) / PR	\$ 156.70	\$ 313.40 ✓
3	10	Rear Bumper Clips / Nec	\$ 5.00	\$ 50.00 ✓
4	1	Rear Bumper Towing Cover / MS		\$ 47.85 ✓
5	1	Rear Bumper Top Garnish / CR4		\$ 67.45 ✓
6	1	Rear Bumper Lower Garnish (Adapter) / CR4		\$ 109.35 ✓
7	1	Rear Bumper Reinforcement / CR4		\$ 775.95 ✓
8	2	Rear Bumper Reflector (LH/RH) ? X SVC	\$ 37.75	\$ 75.50 X
9	1	Rear Bumper Undercover ? / CR4		\$ 58.25 ✓
10	1	Rear Bumper Undercover (RH) ? / CR4		\$ 84.20 ✓
11	4	Rear Bumper Reverse Sensor / short	\$ 238.05	\$ 952.20 880
12	4	Rear Bumper Reverse Sensor Bracket / Nec	\$ 58.90	\$ 235.60 ✓
13	2	Rear Fender (LH/RH) / CR4	\$ 1,910.35	\$ 3,820.70 3,500
14	2	Rear Fender Innershield (LH/RH) ? X SVC	\$ 161.05	\$ 322.10 X
15	20	Rear Fender Innershield Clips ? X SVC	\$ 5.00	\$ 100.00 X
16	2	Rear Taillamp (LH/RH) / CR4	\$ 625.45	\$ 1,250.90 ✓
17	1	Rear Boot / CR4		\$ 1,650.65 ✓
18	2	Rear Boot Lamp (LH/RH) / CR4	\$ 369.40	\$ 738.80 ✓
19	1	Rear Boot Emblem / Nec		\$ 71.60 ✓
20	1	Rear Boot 520i Logo / Nec		\$ 64.45 ✓
21	1	Rear Boot Lock / Sum		\$ 425.35 ✓
22	1	Rear Boot Catch ? X SVC		\$ 56.05 X
23	2	Rear Boot Hinge (LH/RH) ? / BT	\$ 119.40	\$ 238.80 ✓
24	1	Rear Boot Trim ? / CR4		\$ 114.75 ✓
25	10	Rear Boot Trim Clips ? / Nec	\$ 5.00	\$ 50.00 ✓

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: [65] 6661 9688 Fax: [65] 6661 9699 Email: info@huhong.com.sg

Estimate Repair List

19 March 2020

QUOT202003-000025
HHTPCLAIMS20-41

ACCIDENT INVOLVING SLM123T & XE5209Y ON 17/03/2020 ALONG SUNGEI KADUT ST 1 AT ABOUT 1040 HOURS

Estimate Repair List for vehicle SLM123T - B.M.W. 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV

S/N	Quantity	Description	Unit Price S\$	Amount S\$
26	1	Rear Boot Weatherstrip / BH		\$ 66.40 ✓
27	2	Rear Boot No. Plate Lamp (LH/RH) / BR	\$ 27.45	\$ 54.90 ✓
28	1	Rear Boot Outer Holder / CR4		\$ 48.65 ✓
29	2	Rear Boot Stopper (LH/RH) / MEA NOC	\$ 31.10	\$ 62.20 ✓
30	2	Rear Boot Side Garnish (LH/RH) ? X SVC	\$ 41.05	\$ 82.10 X
31	2	Rear Boot Inner Trim (LH/RH) ? / CR4	\$ 171.70	\$ 343.40 ✓
32	1	Rear End Panel / PD		\$ 821.40 ✓
33	1	Rear End Panel Top Garnish / CR4		\$ 116.15 ✓
34	1	Rear Spare Wheel Well / PD		\$ 171.10 ✓
35	1	Rear Spare Wheel Floor Carpet ? X SVC		\$ 572.25 X
36	1	Rear Windscreen with Moulding X SVC		\$ 921.00 X
37	1	Rear Battery ? X SVC		\$ 740.30 X
38	1	Rear Fuse Box ? / CR4		\$ 250.35 ✓
39	1	Rear Door (RH) XR		\$ 1,783.40 X
40	1	Rear Door Black Tape (RH) ? X SVC		\$ 169.70 X
41	1	Rear Door Lock (RH) X SVC		\$ 289.20 X
42	1	Rear Fuel Cover XR		\$ 47.30 X
43	1	Rear Fuel Cover Base CR4		\$ 98.75 ✓
44	1	Rear Exhaust with Slicencer ? X SVC		\$ 1,224.25 X
45	1	Rear Exhaust Insulator ? X SVC		\$ 134.05 X
				\$ 21,242.70 14,332.60
				Less 5.0% \$ 1,062.08 -5%
				\$ 20,180.62 13,615.97
46	1	Sealant / Nec	NETT	\$ 40.00 ✓
47	1	Rear No. Plate / CR4	NETT	\$ 35.00 75
To Dismantle & Change Rear Bumper, Rear Boot, Rear Fender (LH/RH), Rear End Panel, Rear Door (RH), Rear Spare Wheel Well, Rear Reinforcement				\$ 2,200.00 1800
To Perform Wire Checking				\$ 20.00 ✓
To Dismantle & Refit Reverse Sensor				\$ 60.00 ✓
To Dismantle & Refit Rear Exhaust				\$ 150.00 ? 50
To Dismantle & Refit Rear Windscreen				\$ 100.00 ✓
To Remove & Refit Upholstery				\$ 150.00 100
To Remove & Refit Fuel Tank				\$ 180.00 80

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

19 March 2020

QUOT202003-000025
HHTPCLAIMS20-41

ACCIDENT INVOLVING SLM123T & XE5209Y ON 17/03/2020 ALONG SUNGEI KADUT ST 1 AT ABOUT 1040 HOURS

Estimate Repair List for vehicle SLM123T - B.M.W. 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To Dismantle & Refit Rear Door (RH) Mechanism to New Door		\$ 60.00
		To Do Diagnostic Test		\$ 250.00
		To Spray Rear Bumper, Rear Boot, Rear Fender (LH/RH), Rear Door (RH), Rear End Panel, Rear Spare Wheel Well, Rear Fuel Cover		\$ 2,000.00
				1,600
			29,118.91	\$ 25,425.82
		7% GST	\$ 1,779.79	50
		Total	\$ 27,205.41	4,010

Repair day - 12 days

*L/S Repair
After paint photo*

*Sun Pn (S/Kk)
20/03/2020*

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Authorised by Claims Dept



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Supplementary List

22 July 2020

QUOT202003-000025

HHTPCLAIMS20-41

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
3 ANSON RD, #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Attn: Motor Claims Department

ACCIDENT INVOLVING SLM123T & XE5209Y ON 17/03/2020 ALONG SUNGEI KADUT ST 1 AT ABOUT 1040 HOURS

Insured	:	TAN WEE TAT
Vehicle Registration No.	:	SLM123T
Vehicle Make	:	B.M.W.
Vehicle Model	:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Vehicle Chassis No.	:	WBAXG12080DX53228
Policy No.	:	MT/00704053
Date of Accident	:	17/03/2020

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Air Vent (RH) / CRU		\$ 56.80 ✓
2	2	Rear Boot Spring (LH/RH) / BT	\$ 556.75	\$ 1,113.50 ✓
3	1	Rear Luggage Indentation Trim / Def		\$ 171.70 ✓
4	1	Air Bag ECU / Nec		\$ 1,456.80 ✓
5	1	Rear Compartment Sponge / CRU		\$ 88.60 ✓
6	1	Rear Cover Pot / CRU		\$ 98.75 ✓
7	1	Rear Tools Cover / CRA		\$ 97.30 ✓
8	2	Front Headrest (LH/RH) / Jam	\$ 360.00	\$ 720.00 ✓
				\$ 3,803.45 3,803.45
				Less 5.0% \$ 190.16 -56
				\$ 3,613.29 3,613.29
				\$ 80.00 50
				\$ 3,693.29
				7% GST \$ 258.53
				Total \$ 3,951.82

To dismantle & refit new front headrest (LH/RH)

$$\begin{aligned}
 P &= 13,615.97 \\
 S/P &= 3,613.29 \\
 S/N &= 75 \\
 L &= 4,010 \\
 \hline
 &21,314.26 \\
 &- 20\% \\
 \hline
 &17,051.41
 \end{aligned}$$

45
\$17,000
12 days



Authorised by Claims Dept