



HUA HONG PRIVATE LIMITED

250 SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: [65] 6661 9688 Fax: [65] 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

19 March 2020

QUOT202003-000025
HHTPCLAIMS20-41

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
3 ANSON RD, #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Attn: Motor Claims Department

ACCIDENT INVOLVING SLM123T & XE5209Y ON 17/03/2020 ALONG SUNGEI KADUT ST 1 AT ABOUT 1040 HOURS

Insured : TAN WEE TAT
Vehicle Registration No. : SLM123T
Vehicle Make : B.M.W.
Vehicle Model : 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Vehicle Chassis No. : WBAXG12080DX53228
Policy No. : MT/00704053
Date of Accident : 17/03/2020

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper / CRU		\$ 1,571.95
2	2	Rear Bumper Side Retainer (LH/RH) / PR	\$ 156.70	\$ 313.40
3	10	Rear Bumper Clips / Nec	\$ 5.00	\$ 50.00
4	1	Rear Bumper Towing Cover / MIS		\$ 47.85
5	1	Rear Bumper Top Garnish / CRU		\$ 67.45
6	1	Rear Bumper Lower Garnish (Adapter) / CRU		\$ 109.35
7	1	Rear Bumper Reinforcement / CRU		\$ 775.95
8	2	Rear Bumper Reflector (LH/RH) ?	\$ 37.75	\$ 75.50
9	1	Rear Bumper Undercover ?		\$ 58.25
10	1	Rear Bumper Undercover (RH) ?		\$ 84.20
11	4	Rear Bumper Reverse Sensor / short	\$ 238.05	\$ 952.20
12	4	Rear Bumper Reverse Sensor Bracket / Nec	\$ 58.90	\$ 235.60
13	2	Rear Fender (LH/RH) / CRU	\$ 1,910.35	\$ 3,820.70
14	2	Rear Fender Innershield (LH/RH) ?	\$ 161.05	\$ 322.10
15	20	Rear Fender Innershield Clips ?	\$ 5.00	\$ 100.00
16	2	Rear Taillamp (LH/RH) / CRU	\$ 625.45	\$ 1,250.90
17	1	Rear Boot / CRU		\$ 1,650.65
18	2	Rear Boot Lamp (LH/RH) / CRU	\$ 369.40	\$ 738.80
19	1	Rear Boot Emblem / Nec		\$ 71.60
20	1	Rear Boot 520i Logo / Nec		\$ 64.45
21	1	Rear Boot Lock / Sum		\$ 425.35
22	1	Rear Boot Catch ?		\$ 56.05
23	2	Rear Boot Hinge (LH/RH) ?	\$ 119.40	\$ 238.80
24	1	Rear Boot Trim ?		\$ 114.75
25	10	Rear Boot Trim Clips ?	\$ 5.00	\$ 50.00

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: [65] 6661 9688 Fax: [65] 6661 9699 Email: info@huhong.com.sg

Estimate Repair List

19 March 2020

QUOT202003-000025
HHTPCLAIMS20-41

ACCIDENT INVOLVING SLM123T & XE5209Y ON 17/03/2020 ALONG SUNGEI KADUT ST 1 AT ABOUT 1040 HOURS

Estimate Repair List for vehicle SLM123T - B.M.W. 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV

S/N	Quantity	Description	Unit Price S\$	Amount S\$
26	1	Rear Boot Weatherstrip / BH		\$ 66.40
27	2	Rear Boot No. Plate Lamp (LH/RH) / BR	\$ 27.45	\$ 54.90
28	1	Rear Boot Outer Holder / CR4		\$ 48.65
29	2	Rear Boot Stopper (LH/RH) / MEA NOC	\$ 31.10	\$ 62.20
30	2	Rear Boot Side Garnish (LH/RH) ?	\$ 41.05	\$ 82.10
31	2	Rear Boot Inner Trim (LH/RH) ?	\$ 171.70	\$ 343.40
32	1	Rear End Panel / PD		\$ 821.40
33	1	Rear End Panel Top Garnish / CR4		\$ 116.15
34	1	Rear Spare Wheel Well / PD		\$ 171.10
35	1	Rear Spare Wheel Floor Carpet ?		\$ 572.25
36	1	Rear Windscreen with Moulding / NCC		\$ 921.00
37	1	Rear Battery ?		\$ 740.30
38	1	Rear Fuse Box ?		\$ 250.35
39	1	Rear Door (RH) XR		\$ 1,783.40
40	1	Rear Door Black Tape (RH) ?		\$ 169.70
41	1	Rear Door Lock (RH) X		\$ 289.20
42	1	Rear Fuel Cover XR		\$ 47.30
43	1	Rear Fuel Cover Base CR4 / CR1		\$ 98.75
44	1	Rear Exhaust with Slicencer ?		\$ 1,224.25
45	1	Rear Exhaust Insulator ?		\$ 134.05
				\$ 21,242.70
				Less 5.0%
				\$ 1,062.08
				\$ 20,180.62
46	1	Sealant /	NETT	\$ 40.00
47	1	Rear No. Plate /	NETT	\$ 35.00
To Dismantle & Change Rear Bumper, Rear Boot, Rear Fender (LH/RH), Rear End Panel, Rear Door (RH), Rear Spare Wheel Well, Rear Reinforcement				\$ 2,200.00 / 800
To Perform Wire Checking				\$ 20.00
To Dismantle & Refit Reverse Sensor				\$ 60.00
To Dismantle & Refit Rear Exhaust				\$ 150.00 ?
To Dismantle & Refit Rear Windscreen				\$ 100.00 /
To Remove & Refit Upholstery				\$ 150.00 / 100
To Remove & Refit Fuel Tank				\$ 180.00 80

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

19 March 2020

QUOT202003-000025
HHTPCLAIMS20-41

ACCIDENT INVOLVING SLM123T & XE5209Y ON 17/03/2020 ALONG SUNGEI KADUT ST 1 AT ABOUT 1040 HOURS

Estimate Repair List for vehicle SLM123T - B.M.W. 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To Dismantle & Refit Rear Door (RH) Mechanism to New Door		\$ 60.00 XΔ
		To Do Diagnostic Test		\$ 250.00 50
		To Spray Rear Bumper, Rear Boot, Rear Fender (LH/RH), Rear Door (RH), Rear End Panel, Rear Spare Wheel Well, Rear Fuel Cover		\$ 2,000.00 1,600
				\$ 25,425.62
		7% GST		\$ 1,779.79
		Total		\$ 27,205.41

[Signature]
24/3/2020
Repair day - 12 days

L/S Repair
After paint photo

Sun Pn (S/K)

20/03/2020

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[Signature]
Authorised by Claims Dept

