

Revol Carz Garage Pte Ltd

Blk 10 Ang Mo Kio Industrial Park 2a, Ang Mo Kio Autopoint #02-18

Singapore 568047

Tel: 65551171 Fax: 62679317

Final Repair Bill of SLQ4039G

Name : Revol Carz Garage Pte Ltd
Address : c/o 10 Ang Mo Kio Industrial Park 2A
#02-18, Ang Mo Kio AutoPoint Singapore 568047

Date : 25-Mar-20

Model : **MAZDA 2**

QTY	ITEM	AMT (\$\$)
<u>List Items</u>		
1 pc	Car boot	\$956.70
1 pc	Boot lock	\$212.30
1 pc	Boot logo	\$61.20
1 pc	Mazda 2 wording	\$58.30
1 pc	Boot switch	\$85.10
1 pc	Skyactiv emblem	\$68.00
1 pc	Rear bumper	\$892.80
2 pc	Rear bumper retainer	\$27.20
1 pc	Car plate light module	\$55.80
1 pc	Rear end panel top garnish	\$77.00
		<hr/>
		\$ 2,494.40
Discount 20%		<hr/>
		\$498.88
Total:		<hr/>
		\$1,995.52

<u>Special Nett Items</u>		
1 pc	Reverse camera	\$300.00
1 pc	Carplate with cover	\$40.00
1 pc	Reverse sensor 1 set	\$200.00
1 pc	Rear bumper clip (1 set)	\$30.00
		<hr/>
Total:		\$570.00

<u>S/N</u>	<u>Labour Charge</u>	
1	To remove and refit front electrical wiring, replaced damaged lamps and test for proper functioning	\$20.00
2	To remove and refit rear bumper sensor	\$40.00
3	To remove and refit inner trims, inner garnishes, to facilitate the repairs	\$60.00

4	To remove and replace the above damaged parts, repair exhaust, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$400.00
5	To spray paint on the replaced and repaired parts prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available	\$600.00
6	To remove and refit rear windscreen glass.	<u>\$100.00</u>
		\$1,220.00

Total : \$3,785.52

Dollars : Three Thousand Seven Hundred Eighty-Five and Fifty-Two Cents Only

