Weellend (\$

TOTAL

Lump Sum / LBJ: /5

# Rasul (LKKAuto)

Cheok Motor <cheokmotor@gmail.com> From:

Tuesday, 24 March, 2020 12:19 PM Sent:

To:

Re: Independent Survey - SDE6969S Rasul (LKKAuto) **Subject:** 

Attachments:

image001.jpg

Dear Rasul

We hereby confirm repairs amount of \$4,695.00 and 4 days of repairs.

Thank you.

Teo How Cheok

96784272

On Tue, 24 Mar 2020, 10:04 am Rasul (LKKAuto), <Rasul@lkkauto.com> wrote:

Hi Theresa,

Refer to attachment

Finalised amount is \$4,695 / 4 days of part by part repair


Kindly confirm

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	645E
Vehicle Details	· · · · · · · · · · · · · · · · · · ·
Vehicle No.:	SDE6969S
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Mar 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S350 BT L (R18 LED)
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	64286141552289
Chassis No.:	WDD2221322A056581
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$93,249.00
Original Registration Date:	05 Jun 2014
First Registration Date:	05 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$134,849.00
Intended PARF Rebate Details	。 1987年,1987年的東京大學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2024
PARF Rebate Amount:	\$94,394.00
Intended COE Rebate Details	A.E. A.E. A.
COE Expiry Date:	04 Jun 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,103.00
COE Rebate Amount:	\$28,598.00
Total Rebate Amount:	\$122,992.00

The information contained herein is correct as at 23 Mar 2020







Report No. T/20200225/2034

Police Station Of Origin: Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/02/2020 12:06		ade:	Vide Report No.: D/20200224/0172	Station Diary No.: 61	
Informant	's Particul	ars			
Name of Informant: LIM ENG CHEE			Address: APT BLK 714 CLEMENTI WEST STREET 2 #12-145 SINGAPORE 120714		
ID Type / ID No.: NRIC NO / S1436017D			Contact No.: Home/Office: Mobile: 96399991		
Nationality SINGAPO	: RE CITIZE	N	Email:		
Sex: Age: Date of Birth: Male 59 15/03/1960			Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation			Driving Licence Information: Class: 2B.2A.2.3.4	Date of Expiry:	

Type of Accident:	' Conveyed By Ambulance		Date/Time of Accident: 24/02/2020 21:10	Type of Location Straight Road	
JURONG TO	Traveling Toward Road 2 WN HALL ROAD Town Hall towards Boon La	ay Way Lamp Po	st 114		
Lamp Post No Weather:		Road Surface:		Road Speed Limit:	
Clear		Drizzling			
	7	Traffic Control:		Traffic Volume:	
Traffic Flow:		Traffic Light - Working		Light	
Traffic Flow: One Way	Т	Fraffic Light - Wo	rking	Light	

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
JTS2509	Motorcycle	YAMAHA		Black	Seriously Damaged	OAllianz Genera
SDE6969S	Car	MERCEDES BENZ	S350	Silver	Slightly Damaged	0 11 A





2 of 3

Report No. T/20200225/2034

Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999

Brief Details.

On 24/02/2020 at 2110hrs, I was driving my car a Silver Mercedes 350 with registration number SDE6969S at Lane 2 of Jurong Town Hall Road heading towards Boon Lay Way. It was a four lane road and traffic at that point was light.

CONTINUATION OF REPORT

As I was approaching the traffic light junction near to Genting Hotel ,Lamp post 114, I noticed that the light were Orange and I was preparing to stop. I approached the traffic light junction safely and it was Red. Not long after, I felt a hit at the back of the car.

There was a motorcycle with registration number JTS2509 did not manage to stop in time and hit the rear of my car. The driver lost control and fall to the roadside. I immediately went out of the car and went to assist him. I call 999 and 995 soon after. He said that his shoulder was in pain. A taxi driver came over from the rear and assist to call 995 for assistance.

The rear bumper of my car has scratches and the right rear light is broken. The motorcycle was then towed away. I do not have any in-vehicle camera. I did not exchange particulars with the motorcyclist. Traffic Police and ambulance came to scene and the motorcyclist was subsequently conveyed to Ng Teng Fong Hospital.





3 of 3

Report No. T/20200225/2034

Police Station Of Origin: Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

Authentication Stamp

NP168

CONTINUATION OF REPORT

# Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  D /  Sgt 3 NURAISHAH BINTE OSMAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/02/2020 12:06
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt MA JUNXIANG Contact No.: 65476251	Classification Of Case:



# HEOK MOTOR

Blk 241 Hougang St 22 #08-57

(S) 530241 HP: 9678 4272

EMAIL: cheokmtr@angnet.com

Reg. No. 52974061G

x Ohir Rest: 6969/03/20 · 传理 · 处理 · 汽車機件零售價漆等 · 保险值金代理及汽車賠償。 STOUT ROTA TO Still Used no - Spray Painting - Car Repairing - Insurance Commission Agent - Motor Insurance Claims - Value Parts, etc.

LKK Auto Consultants Pte Ltd Blk 51 Paya Ubi Industrial Park #02-25 Ubi Ave I Singapore 408933

Attn: Surveyor Mr Rasul rasul@lkkauto.com

Quotation for Repairs SDE6969S

LKK Auto Consultants her Men 3000

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Datet

Parts Supply:

15 pcs

rear lamp lh 1 pc rear bumper

1 pc low bumper cover garnish .. 1 pc bumper clips @\$7.00

\$ 1,030.00 Nett CA/ \$ 1,980.00 Nett de /

\$ 520.00 Nett de /

\$ 105.00 Nett ne /

\$ 3,635.00

Labour Charges:

Knocking rear panel/rear boot/remove and renew rear bumper..... \$ 580.00 Spray Painting rear boot/rear bumper/rear panel/lh fender etc ... \$ 780.00 600 Remove and install inner cover ..... \$ 80,00 60

Total:

\$ 5,075.00

Yours sincerel

Teo How Cheok

3638

LASUL 4p 90010068

4 days
Plf
16/03/2020
Resy be fre paint



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Aut	tomobile
--	----------

CHEOK MOTOR

Ref: CS/TP20004290/R1vf3e2

.......

	241 HOUGANG ST GAPORE 530241	REET 22 #08-57	Date: 26-03-2020		
			Code: TP519		
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.		Veh. Inspected	SDE 6969S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	16/03/2020	
2.		Vehicle Part	iculars & Condition	A STATE OF THE	
	Make & Model	MERCEDES BENZ S350 BT	c.c	2987	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	WDD2221322A056581	Colour	GREY	
	Odometer	159376	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
	1418 48 0 0 0	Condi	tions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	275/45 R18	PIRELLI	6 mm	
	L/H Front Tyre	275/45 R18	PIRELLI	6 mm	
	R/H Rear Tyre	275/45 R18	PIRELLI	6 mm	
	L/H Rear Tyre	275/45 R18	PIRELLI	6 mm	
		Descript	tion of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR PORTION.		
	DAMAGES SEE D	ETAILS.			
		Gener	al Information		
	Accident Date	24/02/2020	Inspection Date	16/03/2020	
	Survey held at	51 UBI AVE 1 #01-25 PAYA UI	BI IND PARK S' 408933		
	Repairer	CHEOK MOTOR			
ia.			Remarks		
		ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS, V			
b.		Estimate	e Days of Repair		
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDE 6969S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR LAMP LH (SN)	CRACKED	1,030.00	1,030.00
1	REAR BUMPER (SN)	DEFORMED	1,980.00	1,980.00
1	LOW BUMPER COVER GARNISH (SN)	DEFORMED	520.00	520.00
15	BUMPER CLIPS @\$7.00 (SN)	NECESSARY	105.00	105.00
			3,635.00	3,635.00
	LABOUR			
	KNOCKING REAR PANEL / REAR BOOT / REMOVE AND RENEW REAR BUMPER.		580.00	400.00
	SPRAY PAINTING REAR BOOT / REAR BUMPER / REAR PANEL / LH FENDER ETC.		780.00	600.00
	REMOVE AND INSTALL INNER COVER.		80.00	60.00
			1,440.00	1,060.00
	GRAND TOTAL		5,075.00	4,695.00

RECOMMENDED COST OF REPAIRS			4,695.00
RECOMMENDED COST OF REPAIRS	RESIDUES HORESTON FOR THE CONTRACTOR	REPRESENTATION OF THE PROPERTY	4,033.00

Report Ref No. CS/TP20004290/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

ADRIAN LING WAI PING

**Automotive Assessor** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.