

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/P 91082728

Fax : 64816131

AIG Asia Pacific Insurance Singapore Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Vehicle No : SJZ 9503 B
Make : Nissan Juke
Year : 2011

Not Authorized
L1 Pump & ?
Running After Repair
3-4 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy
1 pc	Rear tail-gate outer handle
1 pc	Rear bumper
1 pc	Rear bumper lower garnish
1 pc	Rear bumper reinforcement
1 pc	Rear n/s bumper side retainer

<i>R</i>	\$1,277.50	<i>X</i>
<i>R</i>	\$187.50	<i>X</i>
<i>BT</i>	\$755.10	<i>✓</i>
<i>Ref/Car</i>	\$625.60	<i>✓</i>
	\$550.70	<i>?</i>
<i>Di</i>	\$1.00	<i>✓</i>
	<u>\$3,397.40</u>	
Less 30 %	\$1,019.22	
List total	<u>\$2,378.18</u>	

Nett Item

1 pc	Rear tail-gate inner lock
1 pc	Rear n/s tail-lamp assy
1 pc	Rear emblem "Juke"
1 pc	Rear emblem "DIG-T"
1 pc	Rear emblem "X Tronic CVT"
1 pc	Rear n/s bumper reflector
1 pc	Rear n/s bumper center reflector

<i>R</i>	\$287.60	<i>X</i>
	\$520.10	<i>?</i>
<i>Re</i>	\$55.10	<i>✓</i>
<i>Re</i>	\$45.60	<i>✓</i>
<i>Re</i>	\$62.50	<i>✓</i>
<i>Re</i>	\$75.10	<i>X</i>
<i>Re</i>	\$205.60	<i>X</i>
	<u>\$1,251.60</u>	
Less 10 %	\$125.16	
Nett total	<u>\$1,126.44</u>	

S. Nett Item

1 pc	Rear reverse sensor
15 pcs	Clip
1 pc	Rear no plate

<i>Ref</i>	\$200.00	<i>✓</i>
\$2.00 <i>Re</i>	\$30.00	<i>✓</i>
<i>Re</i>	\$35.00	<i>X</i>
S Nett total	<u>\$265.00</u>	

balance c/f \$3,769.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJZ 9503 B

balance b/f \$3,769.62

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$900.00 3601

To putty & spray paint on accident affected portion.

\$800.00 4001

Check/reconnect wiring.

\$40.00 201

To spray anti rust on accident affected portion.

~ \$100.00 1

Remove/repair rear exhaust silencer

\$480.00 ?

Diagnostic check on lock system and to reset to factory specification

\$280.00 ?

Total \$6,369.62