

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/P 91082728

Fax : 64816131

AIG Asia Pacific Insurance Singapore Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Vehicle No : SJZ 9503 B
Make : Nissan Juke
Year : 2011

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Qty	Description	Acknowledged by Repairer Signature:	Unit Price	Amount
		Date:		

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	R		\$1,277.50	X
1 pc	Rear tail-gate outer handle	X		\$187.50	X
1 pc	Rear end panel	photo	482.00	\$755.60	✓
1 pc	Rear end panel inner garnish	photo		\$185.70	✓
1 pc	Rear n/s fender inner trim board	photo		\$655.30	X
1 pc	Rear bumper	678.90		\$755.10	✓
1 pc	Rear bumper lower garnish	548.20		\$625.60	✓
1 pc	Rear bumper reinforcement	photo	480.10	\$550.70	✓
1 pc	Rear bumper sponge	photo		\$145.70	✓
1 pc	Rear n/s bumper side retainer	photo		\$65.10	✓
1 pc	Rear exhaust silencer	photo	692.20	\$855.10	✓
				\$6,058.90	
				Less 30 %	\$1,817.67
				List total	\$4,241.23

Nett Item

1 pc	Rear tail-gate inner lock	photo		\$287.60	✓
1 pc	Rear n/s tail-lamp assy	photo	438.80	\$520.10	✓
1 pc	Rear emblem " Juke "			\$55.10	✓
1 pc	Rear emblem " DIG-T "			\$45.60	✓
1 pc	Rear emblem " X Tronic CVT "			\$62.50	✓
1 pc	Rear boot rubber	photo		\$155.10	508.20
1 pc	Rear n/s bumper reflector	photo		\$75.10	X
1 pc	Rear n/s bumper center cover	missing		\$175.10	✓
1 pc	Rear n/s end panel air vent	photo		\$125.20	✓
				\$1,501.40	
				Less 10 %	\$150.14
				Nett total	\$1,351.26
				balance c/f	\$5,592.49

SJZ 9503 B

balance b/f \$5,592.49

S. Nett Item

1 pc Rear reverse sensor
15 pcs Clip

	<i>nd</i>	\$200.00	<i>—</i>
\$2.00	<i>na</i>	\$30.00	<i>—</i>
		<u>\$230.00</u>	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 *600*

To putty & spray paint on accident affected portion.

\$1,200.00 *600*

Check/reconnect wiring.

\$40.00 *20*

To spray anti rust on accident affected portion.

\$100.00 *60*

Remove/renew rear exhaust silencer

\$150.00 *60*

Diagnostic check on lock system and to reset to factory specification

	<i>nn</i>	\$280.00	<i>X</i>
Total		<u>\$8,792.49</u>	