

22/03/2020

ASS. REC. BY:

REF: CS/SMO 20004296/UVd3ⁿ²

Special Instruction:

Surveyr: MARCUS

ASSIGNMENT (Office)

From (Person) Henry Irene James of SMO

Date/Time: 23/3/2020 @ 2:48pm

Estimated Cost: _____

Bill to: _____

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBJ 8909A

Insured: SJV 8681 Y

at Workshop m/s Fastech Auto

Tel: 67465405

of 1 keeki Bukit Ave 6 # 01-46 Autobay

Policy No: _____

Claim No: CMTD200/225/THE

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 19/03/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS mpj

H.O.D. Endorsement: _____

Date/Time: 2:44pm 23/3/2020

Person Contacted: Shi ying

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

GBJ 8909A - X

SJV 8681Y - X

23/3/20

Informed Thelma pending workshop est by email

25/3/20

Email preli revised to Thelma

RECEIVED 25 MAR 2020

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBJ8909A
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: GBJ8909A Yr Regn: 9.19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CM
 Make: Toyota hiace c.c. 2982
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 12214 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFHT027800249433
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15
 R: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 19/3/20 D.O.I. 20/3/20
 Survey held at _____

Bal. or Market Value: 60k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: 4 Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS L7A 23389
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
MS Rev
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
25/3/20 4/5 @ 4500 Conf. and w. Alan (Red 13,228.10, 75/10)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 6
 Resurvey No. of Trip: 2

2) 25/3 - typist

Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))

Survey Fee: _____
 Transportation: _____
) S + RS \$ _____
) Photos _____
) Others _____
 TOTAL 450

Report Format : TP
 Lump Sum / I.B.I: (\$ 45 \$ 4500/2)



Auto
Consultants
Pte Ltd

Company Registration No. 19960719

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: CMTD2001225/THE

Our ref: CS/SMO20004296/Uvd3

DATE: 25/3/2020

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. GBJ 8909A


We thank for your instruction on 20/3/2020

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/3/2020 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$17,728.10
Revised Estimate Amount	:S\$4,500.00 (LUMP SUM)
"Check" Items Amount	:S\$
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the n/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 25 March 2020 3:22 PM
To: 'Henry, Irene James'; SUR; 'Choo, Thelma'
Subject: RE: SOMP REF:CMTD2001225/THE//RE: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8909A DOA: 19.02.2020
Attachments: GBJ 8909A PRELI ADVISED.pdf

Dear Thelma,

Enclosed preliminary revised of vehicle GBJ 8909A
Date of survey: 20/3/2020
Number of days (estimated) : 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Monday, 23 March 2020 10:12 AM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>; Choo, Thelma <thelma.choo@sompo.com.sg>
Subject: RE: SOMP REF:CMTD2001225/THE//RE: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8909A DOA: 19.02.2020

Dear Thelma,

Please be informed that we have inspected the vehicle GBJ 8909A on 20/3/2020.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 20 March 2020 3:03 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>

Subject: RE: SOMP REF:CMTD2001225/THE//RE: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8908A DOA: 19.02.2020

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Friday, 20 March 2020 2:48 PM
To: Ong Shiyong <shiyong.ong@fastechauto.com.sg>; assignments@lkkauto.com; sur@lkkauto.com
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Nivitha (LKK Auto) <admin-d@lkkauto.com>
Subject: SOMP REF:CMTD2001225/THE//RE: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8908A DOA: 19.02.2020

Our Reference : CMTD2001225/THE

Without Prejudice
EMAIL ONLY

Date: 20.03.2020

Attention:

M/S FASTECH AUTO PTE LTD

ACCIDENT INVOLVING SJV 8681Y & GBJ 8908A ON 19.02.2020

Dear Sir/ Madam,

We refer to your Notice of Accident dated 20.03.20.

Please be informed that **Thelma Choo** the handler of this case who can be contacted at 6322 4681/
thelma.choo@sompo.com.sg .

As per earlier tele-conversation, we will proceed to assign **LKK AUTO CONSULTANTS PTE LTD** as joint "SJE".

Aside to **LKK AUTO**,

Kindly contact the undersigned for conduct of the motor survey.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ong Shiyong <shiyong.ong@fastechauto.com.sg>

Sent: Friday, 20 March, 2020 1:00 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>

Subject: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8908A DOA: 19.02.2020

Without Prejudice

Dear Sir/Madam

Your insured' s vehicle: SJV 8681Y.

Date of accident: 19/02/2020

Please arrange Pre-repair Inspection for my client' s vehicle no: GBJ 8908A.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS

AMENDMENT NO. 1 OF 2016 paragraph 2.3, please provide a list of at least 10 motor surveyors within 2 days of the notice.

Thank you.

Best Regards,
Shiyong
Fastech Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-46/48/50
Autobay Singapore 417883
Tel: 6746 5405
Fax: 6745 8520



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 23 March 2020 10:12 AM
To: 'Henry, Irene James'; SUR; Choo, Thelma
Subject: RE: SOMP REF:CMTD2001225/THE//RE: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8909A DOA: 19.02.2020

Dear Thelma,

Please be informed that we have inspected the vehicle GBJ 8909A on 20/3/2020.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 20 March 2020 3:03 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SOMP REF:CMTD2001225/THE//RE: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8908A DOA: 19.02.2020

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Friday, 20 March 2020 2:48 PM
To: Ong Shiyong <shiyong.ong@fastechauto.com.sg>; assignments@lkkauto.com; sur@lkkauto.com
Cc: Jason <jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Nivitha (LKK Auto) <admin-d@lkkauto.com>

Subject: SOMPO REF:CMTD2001225/THE//RE: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8908A DOA:
19.02.2020

Our Reference : CMTD2001225/THE

Without Prejudice
EMAIL ONLY

Date: 20.03.2020

Attention:

M/S FASTECH AUTO PTE LTD

ACCIDENT INVOLVING SJV 8681Y & GBJ 8908A ON 19.02.2020

Dear Sir/ Madam,

We refer to your Notice of Accident dated 20.03.20.

Please be informed that **Thelma Choo** the handler of this case who can be contacted at 6322 4681/
thelma.choo@sompo.com.sg .

As per earlier tele-conversation, we will proceed to assign **LKK AUTO CONSULTANTS PTE LTD** as joint "SJE".

Aside to **LKK AUTO**,

Kindly contact the undersigned for conduct of the motor survey.

Best Regards
Irene Henry
Claims Division
D: 6322 4618 | T: 6461 6555



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ong Shiyong <shiyong.ong@fastechauto.com.sg>
Sent: Friday, 20 March, 2020 1:00 PM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>
Subject: REQUEST FOR PRE-REPAIR INSPECTION FOR GBJ 8908A DOA: 19.02.2020

Without Prejudice

Dear Sir/Madam

Your insured' s vehicle: SJV 8681Y.

Date of accident: 19/02/2020

Please arrange Pre-repair Inspection for my client' s vehicle no: GBJ 8908A.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS

AMENDMENT NO. 1 OF 2016 paragraph 2.3, please provide a list of at least 10 motor surveyors within 2 days of the notice.

Thank you.

Best Regards,
Shiyong
Fastech Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-46/48/50
Autobay Singapore 417883
Tel: 6746 5405
Fax: 6745 8520



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2018 Mercedes-Benz CLA180 Urban At \$115,800.



Agent Unit, Under Warranty,
 Showroom Condition, Low
 Depreciation,
 Speedo Motoring



Browse by Category

« Back (1 2 3 4) Next »

Sort by Date Posted 20

66 vehicles

hiace

Advanced Search

Make	Model	Price	Depreciation	Year	Eng Cap	Mileage	Veh Type
Search Selection							
hiace		Any	Any	2019	Any	Any	Any
	Toyota Hiace 3.0M	\$63,000	\$6,670 /yr	30-Aug-2019	2,982 cc	2,100 km	Van
Fuel Type: Diesel							
You Sit Inside You Still Can Smell The New Car Smell! 3.0M With 5 Doors Is Definitely Helpful With Your Goods Delivery Since You Can Open The Van From Both Sides!							
Posted: 23-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace							
	Toyota Hiace 2.8A DX	\$65,800	\$6,960 /yr	03-Sep-2019	2,754 cc	-	Van
Fuel Type: Diesel							
Brand New! GST Inclusive! No Hidden Cost! Immediate Registration! The Most Reliable Large Van! Auto/Diesel! Drive With Class 3A! New Euro 6 LED Facelift! 3 Years Warranty Or 100,000km! 3x Free Servicing! Hassle Free And Low Maintenance For Your Everyday Drive! Lo...							
Net Link Partners Pte Ltd							
Posted: 22-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace							
	Toyota Hiace 3.0M	\$64,800	\$6,680 /yr	05-Dec-2019	2,982 cc	15 km	Van
Fuel Type: Diesel							
New Agent Unit! No Admin Fee. GST/ARF/COE All In! Toyota Hiace 5 Doors Diesel. Borneo Motors 3 Years Or 100k Km Warranty! With Free 8 x Times Servicing! Doorstep Discussion Welcome.Trade In Available To Offset Your Previous Vehicle! What You Need, We Can He...							
Car (S) Pte Ltd							
Posted: 21-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace							
	Toyota Hiace 2.8A DX	\$64,800	\$6,630 /yr	30-Dec-2019	2,754 cc	18 km	Van
Fuel Type: Diesel							
Logistic, Delivery Or Other Usage Of Van Company Can Consider This Newly Register HiAce Van, This Is Consider Nearly Brand New Condition, Price Open For Discussion, Loan Can Be Arrange 100% Loan, We Also Have In House Loan. Call Me Now.							
ABWIN Bus Pte Ltd							
Posted: 21-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace							
	Projector Headlamp						
Brand New hiace Euro 6 projector headlamp for sale							
More info about this product							
	Toyota Hiace Commuter 2.8A	\$82,800	\$9,110 /yr	23-Apr-2019	2,754 cc	-	Bus
Fuel Type: Diesel							
Loan, Flexible Loan Available.							

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 914W

Vehicle Details

Vehicle No.: GBJ8909A
Vehicle to be Exported: No
Intended Deregistration Date: 23 Mar 2020
Vehicle Make: TOYOTA
Vehicle Model: HIACE VAN TURBO 5DR MT
Primary Colour: Silver
Manufacturing Year: 2019
Engine No.: 1KD2866946
Chassis No.: JTFHT02P800249433
Maximum Power Output: -
Open Market Value: \$28,138.00
Original Registration Date: 27 Sep 2019
First Registration Date: 27 Sep 2019
Transfer Count: 0
Actual ARF Paid: \$1,407.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Sep 2029
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$24,599.00
COE Rebate Amount: \$23,389.00
Total Rebate Amount: \$23,389.00

The information contained herein is correct as at 23 Mar 2020

OK

FASTECH AUTO PTE LTD
 BLK 1 KAKI BUKIT AVE 6
 #01-46,48,50 AUTO BAY
 SINGAPORE 417883

Not Authorized
 Make
 1/5 @ 4500
 6 days.

VEHICLE No: GBJ 8909A

1PC	REAR FENDER N/S	1889.70
1PC	REAR FENDER OUTER RAILING N/S	
1PC	REAR FENDER MUDFLAP N/S	185.50
1PC	REAR FENDER AIR VENT N/S	
1PC	REAR FENDER INNER HOUSING PANEL N/S	
1PC	TAILLAMP N/S	388.50
1PC	TAILLAMP HOUSING PANEL N/S	399.40
1PC	TAILLAMP LOWER GARNISH N/S	
1PC	REAR BUMPER	681.10
1PC	REAR BUMPER SIDE HOLDER N/S	115.00
1SET	REAR BUMPER CLIPS	
1PC	REAR END PANEL N/S	412.20
1PC	REAR SHOCK ABSORBER N/S	
1PC	REAR WHEEL HUB BEARING N/S	
1PC	REAR AXLE BEAM	
1PC	TAILGATE	
1PC	TAILGATE REAR LOGO	
1PC	REAR WHEEL HUB CAP N/S	

Body no	\$2,880.20	←
1 1	\$366.50	X
reflex	\$245.30	←
one	\$166.50	←
2	\$1,220.30	X
one	\$480.50	←
3 of 5 no	\$605.10	←
no	\$98.50	←
no	\$688.20	✓
one	\$188.20	←
two	\$50.00	✓
Body no	\$755.30	←
1 1	\$299.20	X
1 1	\$688.90	X
1 1	\$1,712.30	X
2	\$2,150.00	X
1 1	\$68.10	X
2	\$225.10	
	\$12,888.10	
	20	

(257)

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REFIX REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX TAILGATE MECHANISM	1 1	\$120.00 X
TO DISMANTLE & REFIX INNER TRIM, WOODEN BOARD, FOR FACILITATE REPAIR REAR INNER PANEL		\$380.00 200
TO SPRAY RUST PROOFING		\$100.00 80
TO CONDUCT WHEEL ALIGNMENT	1 1	\$100.00 X
TO DISMANTLE & REFIX REAR UNDER CARRIAGE	1 1	\$380.00 X
LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,800.00 / 200
TO PUTTY & SPRAY PAINTING		\$1,800.00 800
TOTAL		\$17,728.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

1. 4386.4
 257
 3289.80
 5649.8
 4219



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20004296/Uvd3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 26-03-2020	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJV 8681Y	Veh. Inspected	GBJ 8909A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2001225/THE	Excess (\$)	0.00
Assign From	HENRY IRENE JAMES	Assign Date	20/03/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTFHT02P800249433	Colour	SILVER
Odometer	12214	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/03/2020	Inspection Date	20/03/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 8909A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER N/S	BADLY DENTED	2,880.20	1,889.70
1	REAR FENDER OUTER RAILING N/S	NOT NECESSARY	366.50	-
1	REAR FENDER MUDFLAP N/S	DEFORMED / TORN	245.30	185.50
1	REAR FENDER AIR VENT N/S	CRACKED	166.50	166.50
1	REAR FENDER INNER HOUSING PANEL N/S	TO REPAIR SEE LABOUR	1,220.30	-
1	TAILLAMP N/S	CRACKED	480.50	388.50
1	TAILLAMP HOUSING PANEL N/S	BADLY DENTED	605.10	399.40
1	TAILLAMP LOWER GARNISH N/S	DISTORTED	98.50	98.50
1	REAR BUMPER	DISTORTED	688.20	681.10
1	REAR BUMPER SIDE HOLDER N/S	CRACKED	188.20	115.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL N/S	BADLY DENTED	755.30	412.20
1	REAR SHOCK ABSORBER N/S	NOT NECESSARY	299.20	-
1	REAR WHEEL HUB BEARING N/S	NOT NECESSARY	688.90	-
1	REAR AXLE BEAM	NOT NECESSARY	1,712.30	-
1	TAILGATE	TO REPAIR SEE LABOUR	2,150.00	-
1	TAILGATE REAR LOGO	NOT NECESSARY	68.10	-
1	REAR WHEEL HUB CAP N/S	TO REPAIR SEE LABOUR	225.10	-
	LESS 25% DISCOUNT		-	-1,096.60
			12,888.20	3,289.80
LABOUR				
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REFIX REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX INNER TRIM,WOODEN BOARD, FOR FACILITATE REPAIR REAR INNER PANEL.		380.00	200.00
	TO SPRAY RUST PROOFING.		100.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR UNDER CARRIAGE.	NOT NECESSARY	380.00	-

Report Ref No. CS/SMO20004296/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER INNER HOUSING PANEL N/S, TAILGATE AND REAR WHEEL HUB CAP N/S. TO PUTTY & SPRAY PAINTING.		1,800.00	1,200.00
			1,800.00	800.00
			4,840.00	2,360.00
GRAND TOTAL			17,728.20	5,649.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CS/SMO20004296/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.