



AIG Singapore
78 Shenton Way
Singapore 079120

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

Vehicle number SKQ4273H
Make / Model MAZDA / 6
Chassis number JM6GJ1031F0146916
Accident date 13/3/20
Reference 2003-31

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER	de 1378.40 379.80
2	REAR BUMPER RETAINER	7 144.80 x 7 7
1	REAR BUMPER REINFORCEMENT	7 532.10 460
2	REAR BUMPER REFLECTOR	8 162.50 482.60
1	END PANEL	7 565.40 180.10
1	END PANEL TOP GARNISH	7 323.40 de 180.10
1	REAR LH TAILLAMP	7 791.10
1	REAR RH TAILLAMP	7 791.10
1	BOOTLID	R 1394.10
1	BOOTLID WEATHERSTRIP	7 190.60
1	BOOTLID EMBLEM LOGO	7 63.70
1	BOOTLID EMBLEM -MAZDA	7 46.40
1	BOOTLID EMBLEM- 6	7 39.10
1	BOOTLID LAMP LH	7 436.00
1	BOOTLID LAMP RH	7 436.00
1	BOOTLID LOCK STRIKER	7 118.50
1	BOOTLID INNER TRIM	7 212.60
1	BOOTLID OUTER CHROME GARNISH	7 391.40
1	SPARE TYRE TOP BOARD	7 486.75
1	REAR EXHAUST SILENCER	R 1008.60
2	REAR EXHAUST MOUTING	x 40.00
		2314.40
		20% 1851.52
		9552.55
	Less 20%	1910.51
	Subtotal	7642.04
	Balance C/F	
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	REAR NUMBER PLATE	7 80.00
1 SET	REAR BUMPER CLIP	7 30.00
1 SET	REAR REVERSE SENSOR	200 1W 400.00
1 SET	BOOTLID INNER TRIM CLIP	7 30.00
1	JOINT SEALANT	7 120.00
		230
	Subtotal	660.00
	Balance C/F	8302.04

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F		8302.04
1	CHECK REAR WIRING AND LIGHTING SYSTEM	60.00 30'
2	REMOVE, REFIT REAR LINING TRIM AND GARNISH	150.00 60
3	REMOVE AND RNEW REAR REVERSE SENSOR	120.00 30
4	REMOVE AND RENEW REAR EXHAUST SILENCER	120.00 2h 1
5	TRNASFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 x 2h 1
6	PANEL BEATING AND RENEW DAMGAR PARTS ON AFFECTED AR	1000.00 600
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 600
8	APPLY ANTI RUST ON AFFECTED AREAS	100.00 30
Subtotal		2950.00
Grand total		11252.04

1350

1851.52
230
1350

3431.52.
1/5/2700 *
5 days.

Taughlin 97495749
'WP'
19/3/20 @ 1pm
Lump sum
Payable after repair
5 days
Taughlin & Khanlou

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: