

AIG Singapore  
78 Shenton Way  
Singapore 079120

**TeamWork Garage Pte Ltd**  
53 Ubi Avenue 1 #01-23/24 Spore 408934  
Paya Ubi Industrial Park  
Tel : 6844 2475  
E-mail : claims@teamworkgarage.com  
ROC number : 201015366H

## REPAIR PERFORMA INVOICE

|                |                   |
|----------------|-------------------|
| Vehicle number | SKQ4273H          |
| Make / Model   | MAZDA / 6         |
| Chassis number | JM6GJ1031F0146916 |
| Accident date  | 13/3/20           |
| Reference      | 2003-31           |

| Qty                                           | Particulars                  | Unit Price - SGD \$ |
|-----------------------------------------------|------------------------------|---------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u>         |                              |                     |
| 1                                             | REAR BUMPER                  | de 1378.40          |
| 2                                             | REAR BUMPER RETAINER         | 7 144.80            |
| 1                                             | REAR BUMPER REINFORCEMENT    | 7 532.10            |
| 2                                             | REAR BUMPER REFLECTOR        | x 162.50            |
| 1                                             | END PANEL                    | 7 565.40            |
| 1                                             | END PANEL TOP GARNISH        | 7 323.40            |
| 1                                             | REAR LH TAILLAMP             | x 791.10            |
| 1                                             | REAR RH TAILLAMP             | x 791.10            |
| 1                                             | BOOTLID                      | Ry 1394.10          |
| 1                                             | BOOTLID WEATHERSTRIP         | 7 190.60            |
| 1                                             | BOOTLID EMBLEM LOGO          | new 63.70           |
| 1                                             | BOOTLID EMBLEM -MAZDA        | new 46.40           |
| 1                                             | BOOTLID EMBLEM- 6            | new 39.10           |
| 1                                             | BOOTLID LAMP LH              | x 436.00            |
| 1                                             | BOOTLID LAMP RH              | x 436.00            |
| 1                                             | BOOTLID LOCK STRIKER         | x 118.50            |
| 1                                             | BOOTLID INNER TRIM           | x 212.60            |
| 1                                             | BOOTLID OUTER CHROME GARNISH | x 391.40            |
| 1                                             | SPARE TYRE TOP BOARD         | x 486.75            |
| 1                                             | REAR EXHAUST SILENCER        | Ry 1008.60          |
| 2                                             | REAR EXHAUST MOUTING         | x 40.00             |
|                                               |                              | 9552.55             |
| Less 20%                                      |                              | 1910.51             |
| Subtotal                                      |                              | 7642.04             |
| Balance C/F                                   |                              |                     |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |                              |                     |
| 1                                             | REAR NUMBER PLATE            | x 80.00             |
| 1 SET                                         | REAR BUMPER CLIP             | new 30.00           |
| 1 SET                                         | REAR REVERSE SENSOR          | 200 new 400.00      |
| 1 SET                                         | BOOTLID INNER TRIM CLIP      | x 30.00             |
| 1                                             | JOINT SEALANT                | x 120.00            |
| Subtotal                                      |                              | 660.00              |
| Balance C/F                                   |                              | 8302.04             |

LABOUR AND MISCELLANEOUS CHARGES

|   | Balance B/F                                         | 8302.04     |
|---|-----------------------------------------------------|-------------|
| 1 | CHECK REAR WIRING AND LIGHTING SYSTEM               | 60.00 30'   |
| 2 | REMOVE, REFIT REAR LINING TRIM AND GARNISH          | 150.00 60   |
| 3 | REMOVE AND RNEW REAR REVERSE SENSOR                 | 120.00 30   |
| 4 | REMOVE AND RENEW REAR EXHAUST SILENCER              | 120.00 X    |
| 5 | TRNASFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW  | 200.00 X    |
| 6 | PANEL BEATING AND RENEW DAMGAR PARTS ON AFFECTED AR | 1000.00 600 |
| 7 | SPRAY PAINTING ON AFFECTED AREAS                    | 1200.00 600 |
| 8 | APPLY ANTI RUST ON AFFECTED AREAS                   | 100.00 30   |
|   | Subtotal                                            | 2950.00     |
|   | Grand total                                         | 11252.04    |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495744  
'WP'

19/3/20 @ 1pm

Amptm

Reopen after repair

5 days

Tanpin @ Khandaan