

12/03/2020

ASS. REC. BY:

REF: CS/AIG 2000-4301/At d3⁷²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Ted Eric Weihong

of AIG

Date/Time: 20/3/2020 @ 1.49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCA 212

Insured:

SC2 578C

at Workshop m/s

JEC Auto

Tel:

of

1, Ikerai Bukit Ave 6 # 02-11 Andokay

Policy No:

Claim No:

579980540059

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/03/2020

CA / REV / REP. / REV 24 HRS

23/03/2020

H.O.D. Endorsement:

Date/Time:

1.57pm 20/3/2020

Person Contacted:

Ah xian

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate	LT
	SCA 212 - NA/EGT 2000-4240/13		D.O.A: 18/03/2020
	SC2 578C - NA/EGT 2000-4240/13		D.O.A: 18/03/2020
	Lump Sum \$2300 (Red: 7533.49: 16%)		
	3 days		

250

11

261

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2020 10:56
Date Of Accident	18/03/2020 18:55
Exact Location Of Accident	HOUGANG AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCA21Z
Insured/Policyholder	
Name Of Registered Owner	SOH PEK KOON(SU BIJUN)
NRIC No	SXXXX420G
Email Address	JOEY.SOH.21@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90478891
Alternative Phone No	OTHERS-90478891

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ20-001061
Cover Note Number	

Driver

Name of Driver	SOH PEK KOON(SU BIJUN)
NRIC No	SXXXX420G
Date Of Birth	03/11/1980
Occupation	INDOOR
Date Of Driving Pass	08/07/2002
Driving Experience	17 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90478891
Fax Number	
Contact Number	OTHERS-90478891
Email Address	JOEY.SOH.21@GMAIL.COM

Address	24A RICHARDS AVE
Postcode	546436
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG HOUGANG AVE 2 TWDS HOUGANG AVE 8 ON THE 2ND LANE OF A3-LANES RD. INFR. OF MY VEH STOP AND I FOLLOWED SUIT. SUDDENLY I FELT THE IMPACT FROM MY REAR. WHEN I CAME OUT FROM MY VEH, I WAS INVOLVED IN A CHAIN COLLISION OF 3 VEHICLES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCZ578C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KUAH LEONG KOK
NRIC/Passport Number	SXXXX135J
Contact Number	96709027
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMM9035T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YEO NAI HOO
NRIC/Passport Number	SXXXX609D
Contact Number	98300524
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

19/3/2020
11:25AM

GIARMC SketchPlanForm_V3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

19/03/20

SCA21Z.

TPA163
revised

Toyota Harrier '98 6CC
ZSU60008732

Rear Bumper Deflated	1481.50 ✓
Rear Bumper Lips. New	5230
Rear Bumper Side Holder x 02 ^{New}	101.2 x 2 = 202.40 ✓
Rear Bumper Corner Guards Deflated	419.65 ✓
Rear Bumper Sponge Deflated	160.20 ✓
Rear Bumper Reflector 102 ^{New}	96.8 x 2 = 193.60 x
Reverse Sensor Pkg	280 (SN) 200 (SN)
Rear End Panel Repair	881.65 x
Rear End Panel Top Grmsh. ^{New}	381.60 x
Tailgate Repair	1975.25 x
Tailgate Lock	597.35 x
Tailgate Weatherstripe ^{New}	341.65 x
Tailgate Lock Sensor (keyless) ^{New}	230.50 x
Tailgate Glass Moulding ^{New}	199.62 x

SCA 212.

Tailgate glass Sealant ^{MP} on 60(SN) +

Harrier Wording. NEL 68.50 ✓

2362.25 SN: 200
1771.68

Panel Beating ~~800~~ 400

Spray Painting. ~~800~~ 400

Wiring. ~~50~~ 30

To undersoil 00 x

To remove reverse sensor ~~100~~ 50

To remove upholstery ~~150~~ 40

To remove tailgate glass 180 x 920

To transfer tailgate fittings. 150 x.

9833.47

total 2891.68

H/S 2.3K

03 Days

SCA21Z.

TRAIL
Denise.

Toyota Harrier 1986CC
ZSU600087153

Rear Bumper Deformed	1481.50 ✓
Rear Bumper Lips. New	5230
Rear Bumper Side Holder x 02 ^{New}	101.2 x 2 = 202.40 ✓
Rear Bumper Lower Garish Deformed	419.65 ✓
Rear Bumper Sponge. Dehd	160.20 ✓
Rear Bumper Reflector x 02 ^{HP} _{new}	96.8 x 2 = 193.60 x
Reverse Sensor Dandy	280 (SW) 200 (SW)
Rear End Panel Repair	881.65 x.
Rear End Panel Top Garish. ^{HP} _{new}	381.60 x.
Tailgate Repair	1975.25 +
Tailgate Lock	597.35 +
Tailgate Weatherstripe. } ^{HP} _{new}	341.65 x.
Tailgate Lock Sensor (Keyless) ^{HP} _{new}	230.50 x
Tailgate Glass Moulding ^{HP} _{new}	199.62 x

SCA 212

Tailgate Glass Sealant. ^{NP} on 60(SN) +

Harrier Wording. ^{NEC} 68.50 ✓

2362.25 SN: 200
1771.68

Panel Bunting ~~800~~ 400

Spring Painting. ~~800~~ 400

Wiring. ~~50~~ 30

To undersail 100 x

To remove reverse sensor ~~100~~ 50

To remove upholstery ~~150~~ 40

To remove tailgate glass 180 x 920

To transfer tailgate fittings. 150 x.

total 2891.68

9853.47

L/S 2.3K

0.3 Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20004301/ATD3N2
Date: 03/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100166305
Claimant Vehicle No: SCA21Z Insured Vehicle No: SCZ578C
Date of Loss: 18/03/2020 Nature of Claim: TP Claim No: 5799805400SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCA21Z
Make & Model: TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD Engine No: 3ZRB863679
(A)
Reg. Date: 17/03/2017 (Man. Year: 2016) Chassis No: ZSU600087153
Colour: Maroon Odometer: 37022 km
Engine Capacity: 1986 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R18 Rear Tyre Size: 235/55R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread's depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,523.47	1,971.69	5,551.78	73.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	920.00	1,410.00	60.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,853.47	2,891.69	6,961.78	70.65
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	9,853.47	2,300.00	7,553.47	76.66

INSPECTION

Date of Assignment: 20/03/2020
Date Inspected: 23/03/2020 Inspected At: Jec Automotive (HQ)
1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,481.50 F	*1,481.50 FL
2	1		*REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	202.40 F	*202.40 FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	419.65 F	*419.65 FL
5	1		*REAR BUMPER SPONGE	Deformed	160.20 F	*160.20 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	193.60 F	*- FL
7	1		*REAR END PANEL	Repair	881.65 F	*- FL
8	1		*REAR END PANEL TOP GARNISH	Not Necessary	381.60 F	*- FL
9	1		*TAILGATE	Repair	1,975.25 F	*- FL
10	1		*TAILGATE LOCK	Not Necessary	597.35 F	*- FL
11	1		*TAILGATE WEATHERSTRIPE	Not Necessary	341.65 F	*- FL
12	1		*TAILGATE LOCK SENSOR (MEYLESS)	Not Necessary	230.50 F	*- FL
13	1		*TAILGATE GLASS MOULDING	Not Necessary	199.62 F	*- FL
14	1		*HARRIER WORDING	Necessary	68.50 F	*68.50 FL
15	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
16	1		*TAILGATE GLASS SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	7,523.47	2,562.25
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	590.56
Total Parts (S\$)	7,523.47	1,971.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	100.00	0.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	40.00
7	TO REMOVE TAILGATE GLASS	New	180.00	0.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	0.00
Gross Labour Cost (S\$)			2,330.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >