

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD # 05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L


Hp 96699986

INVOICE

Ms. Rashinah Binte Abdul Rashid
Apt Blk 480 Sembawang
Drive #02-461
Singapore 750480

Invoice No : PA/20020002/tpw
Our Ref : PA/FBN6926/1119/tpw
Date : 31 January 2020

Claim Type	Third Party	Date of Accident	: 13 May 2019
Vehicle No.	FBN 6926 S	Date of Inspection	: 20 November 2019
No	Description		Amount (S\$)
1	Survey fees inclusive of Transportation and Photographs (65) copies		\$365.00
		Total	<u>\$365.00</u>
Singapore Dollar: Three Hundred And Sixty Five Only			
All payments made payable to : Prudent Adjustors Services			


Prudent Adjustors Services

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L

VEHICLE APPRAISAL REPORT

Ms. Rashinah Binte Abdul Rashid
Apt Blk 480 Sembawang
Drive #02-461
Singapore 750480

Our Ref : PA/FBN6926/1119/tpw
Date : 31 January 2020

REFERENCE PARTICULARS

Your Reference No : Not Advised
Date of Accident : 13 May 2019

Date of Assignment : 20 November 2019
Date of Inspection : 20 November 2019
Date of Re-inspn. : 09 December 2019

PARTICULARS OF VEHICLE

Reg. No : FBN 6926 S
Make : Piaggio
Model : Vespa GTS 150 ABS
Year : 23 November 2018

Odometer : No Key
Color : Black
Chassis No. : ZAPMA320000001549
Engine No : Blocked

TYRE / CONDITION

<u>Location</u>	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Michelin	120/70 R12	4 mm
Rear	Michelin	130/70 R12	5 mm

DAMAGE PROFILE

The Scooters sustained severe damage at all sides. Chassis frame badly distorted and damaged beyond repair. The Scooters was not able to restore to road worthy condition.

ASSESSMENT SUMMARY

The Scooters was rendered not safe to repair. **Hence recommended as Total Loss.**

Market value of the Scooter at time of loss was approximately \$12,500

LTA rebate as on 20/11/2019 was \$2,391.00 Nett value was \$10,109.00.00 approximately.

No wreck offer by repairer nor any salvage value

Except LTA rebate at deregistration.

Survey conducted at: Ong Motor Trading

Enclosed (65) photographs depicting damage to the scooters.

The survey was conducted on a **WITHOUT PREJUDICE BASIS.**


Prudent Adjustors Services
Bok Jee Tan







PRUDENT ADJ



PRUDENT ADJ







PRUDENT ADJ.




PRUDENT ADJ.












PRUDENT ADJ




PRUDENT ADJ
















Re-Survey






Re-Survey





Re-Survey






Re-Survey





Re-Survey





Re-Survey






Re-Survey





Re-Survey





Re-Survey

