



# AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047  
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre  
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Car Plate No. GBE 4655J

Date of Accident : 17-03-2020

Model Toyota Dyna

*Not Withheld* Time of Accident : 17:15

*Ways @ 3109.72*  
*Resurvey After Paint*

Venue : Sembawang Rd  
 Chong Pang

No	Qty	Parts Description	Estimated Parts Price
1	1	Front right door panel assy <i>1380</i>	\$ <i>Pr</i> 1,652.00 ✓
2	1	Front right door inner board	\$ <i>Sm</i> 312.00 ✗
3	1	Front right door lock mechanism	\$ <i>N</i> 205.00 ✗
4	1	Front right door lock catch	\$ <i>N</i> 68.00 ✓
5	1	Front right door glass	\$ <i>Sm</i> 650.00 ✗
6	1	Front right door glass moulding	\$ <i>Sm</i> 185.00 ✗
7	1	Front right door outer handle	\$ <i>Sm</i> 176.00 ✗
8	1	Front right regulator with motor assy	\$ <i>N</i> 478.00 ✗
9	1	Front right door checker linkage	\$ <i>Sm</i> 167.00 ✗
10	2	Front right door hinge	\$ <i>Pr/Dit</i> <i>N</i> 195.00 ✓
11	1	Front right door signal lamp	\$ <i>Pr</i> 95.00 ✓
		<i>if head lamp R.H. Cur ✓</i>	\$ 4,183.00
		Less 25%	\$ 1,045.75
			\$ 3,137.25

Special Nett Items

1	10	Front right door inner board clips	\$ <i>nn</i> 30.00 ✗
2	1	Front right door company sticker	<i>net</i> \$ 180.00 <i>Pr</i>
			\$ 210.00

**Total parts**

**\$ 3,347.25**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



## AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047  
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre  
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Car Plate No. GBE 4655J

Model Toyota Dyna

Date of Accident : 17-03-2020

Time of Accident : 17:15

Venue : Sembawang Rd  
 Chong Pang

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 1,200.00 <sup>400</sup>
2	To putty and spray painting front right portion.	\$ 1,200.00 <sup>500</sup>
3	To check wiring and focus front headlamp.	\$ 200 50.00
4	To apply anti rust proofing to front right affected area.	\$ 300 120.00
5	To transfer front right door glass to new door.	\$ 600 80.00
6	To remove and install front right door lock mechanism.	\$ 80.00
7	To check door central locking for function.	\$ <i>nn</i> 80.00 X
8	Towing service.	<i>nn</i> \$ 100.00 X
<b>Total labour :</b>		<b>\$ 2,910.00</b>
<b>Total parts :</b>		<b>\$ 3,347.25</b>
<b>Total labour :</b>		<b>\$ 2,910.00</b>
<b>Total repair cost :</b>		<b>\$ 6,257.25</b>
		7,823.43



**AH CHANG MOTOR SERVICE CENTRE**

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047  
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre  
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Car Plate No. GBE 4655J

Date of Accident : 17-03-2020

Model Toyota Dyna

Time of Accident : 17:15

Venue : Sembawang Rd  
 Chong Pang

No	Qty	Parts Description	Estimated Parts Price
----	-----	-------------------	-----------------------

Supplementary Items

87.555w

- 1 1 Door outer wheather moulding 175.10
- 2 1 Front bumper assy
- 3 1 RH head lamp

\$ 210.00 506w

\$ 952.00 X

\$ 872.90 ✓

\$ 2,034.90

258

Special Nett Items

- 1 RH door decal ( lower )

NEC

\$ 40.00 25/2

\$ 40.00

Total \$ 2,074.90