



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD	Ref : CS/AWA20004306/Ksd3s2
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914	Date : 08-05-2020
	Code : AWA



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 8034J	Veh. Inspected	GBE 4655J
Policy No.	AVCPSB0093151901	Coverage (\$)	0.00
Claim No.	NSV2000123/KW	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	20/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KDY2318022183	Colour	SILVER
Odometer	177019	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	CONDOR	6 mm
L/H Front Tyre	195 R15X8	CONDOR	6 mm
R/H Rear Tyre	155 R12X8(D)	NEXEN	7/7 mm
L/H Rear Tyre	155 R12X8(D)	NEXEN	7/7 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DMAGES SEE DETAILS.
--	--

5. General Information

Accident Date	17/03/2020	Inspection Date	23/03/2020
Survey held at	AH CHANG MOTOR SERVICE CENTRE BLK 10 ANG MO KIO IND PARK 2A AMK AUTOPOINT #03-16 SINGAPORE 568047		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-------------------------------------	-----------------------