

MK Vehicle Engineering Pte Ltd

48 Toh Guan Road East #04-124/125 Enterprise Hub Singapore 608586

Tel : 6763 6363 Fax : 6763 0919

Email: repair@mkvehicle.com.sg

Telefax

Estimate : Accident Repairs
Workshop : MK Vehicle Engineering
Contact No : 6763 6363
Fax No : 6763 0919
Reference : MK/TP/0001/2020/TG
Date : 23-Mar-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SBW 8283 C

FWD SINGAPORE PTE. LTD

6 Temasek Boulevard #18-01

Suntec Tower Four

Singapore

Attn: Motor Claims Dept

Tel: Fax 6820 8888

Owner's Name : Ms. Li Fang
Address : 4 Choa Chu Kang Grove
#03-07
Singapore 688239
Telephone : (HP)+65 97307808
Type of Claim : Third Party Claims
Policy No. : D19MTPV01007596
Vehicle No : **SKT 3214 U**
Model Code : Jetta GP 1.4 TSI 90 A/T HL 1634G5
Model / Year : 29/5/2015
Engine No : CAXE94927
Chassis No : WVVZZZ16ZFM001863
Mileage :
Date In :
Estimated By : Troy Goh
Accident Date : 12-Mar-20
Place of Accident : Jurong Town Hall R Slip Rd Towards AYE City

MK Vehicle Engineering Pte Ltd

48 Toh Guan Road East #04-124/125 Enterprise Hub Singapore 608586
Tel : 6763 6363 Fax : 6763 0919

Telefax

Estimated Labour Charges for Accident Vehicle SKT 3214 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	S/N \$ 150.00 /	
2	To respray rear bumper.	\$ 300.00 200	<u>410</u>
3	To carry out diagnostic checks.	S/N \$ 60.00 /	
TOTAL LABOUR CHARGES		: \$ 510.00	

MK Vehicle Engineering Pte Ltd

48 Toh Guan Road East #04-124/125 Enterprise Hub Singapore 608586

Tel : 6763 6363 Fax : 6763 0919

Telefax

Material List for Accident Vehicle Regn No. SKT 3214 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>de /</i>	\$ 1,650.00	1212
2	REAR BUMPER SPONGE ⁷ X SVC	\$ 225.00	540
3	REAR BUMPER SPOILER <i>cut /</i>	\$ 855.00	1752 10%
4	REAR BUMPER CARRIER ⁷ X SVC	\$ 795.00	1576.80
5	REAR BUMPER CENTRE RETAINER ⁷ X SVC	\$ 105.00	
6	REAR BUMPER RETAINER LH / RH X SVC	2 \$ 240.00	
7	REAR LIGHT REFLECTOR - LH / RH X SVC	2 \$ 240.00	
8	SUNDRIES <i>u /</i>	\$ 20 50.00	20
TOTAL SPARE PARTS		\$ 4,160.00	
TOTAL LABOUR CHARGES		\$ 510.00	
GRAND TOTAL		<u>\$ 4,670.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

1576.80
410.00
+ 20.00
2006.80

MK Vehicle Engineering Pte Ltd

48 Toh Guan Road East #04-124/125 Enterprise Hub Singapore 608586
Tel : 6763 6363 Fax : 6763 0919

Telefax

Name : Rasul - Hp 90010068
Surveyed Date : 24/03/2020 @ 1500hrs
Authorised Date :
Excess Cost : 3 days
Liability : P/P
Remarks : Resurvey before paint

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

Yours faithfully,
MK Vehicle Engineering Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: