

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

19th March 2020

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TPALH.
Vic

ZWR800425526

Accident date: 19TH MARCH 2020

Estimated repair cost for vehicle no: SMR7873C TOYOTA NOAH 1.8 ' 2020

S/n	Qty	Items	U/price	Amount	
				\$1,774.20	✓
1	1	Rear Boot Lid <i>Dented</i>		\$40.00	✓
2	1	Rear Boot Lid HYBIRD logo <i>new</i>		\$385.10	✓
3	1	Rear Boot Lid lock <i>Damaged</i>		\$315.00	✓
4	1	Rear boot lid center moulding <i>cracked</i>		\$39.00	✓
5	6	Rear boot lid center moulding clips <i>new</i>	\$6.50	\$285.00	✓
6	1	Rear Boot Lid weatherstrip <i>ht</i>		\$55.90	✓
7	1	Rear boot lid emble logo <i>new</i>		\$50.00	x
8	1	Rear Boot Lid Number Plate <i>2 new</i>		\$117.00	x
9	2	Rear Boot Lid Number Plate Lamp <i>2 new</i>	\$58.50	\$265.00	x
10	1	Rear boot lid inner rubber <i>Repeated</i>		\$552.10	✓
11	1	Rear Boot Lid Inner Trim board <i>cracked</i>		\$310.40	x
12	2	boot lid side reflector <i>2 new</i>	\$155.20	\$1,250.40	x
13	2	Rear tail lamp <i>2 new</i>	\$625.20	\$510.80	x
14	2	tail lamp lower panel <i>2 new</i>	\$255.40	\$1,455.00	770.
15	1	Rear Bumper <i>Delivered</i>		\$68.00	36
16	1	Rear bumper towing cover <i>Missing</i>		\$190.40	x
17	2	Rear bumper side reflector <i>new</i>	\$95.20	\$50.00	30
18	8	Rear bumper clips <i>new</i>		\$350.00	200 (SN)
19	1	Rear Bumper reverse sensor <i>Damaged</i>		\$425.00	95
20	1	Antenna electrical key <i>cracked</i>		\$783.20	✓
21	1	end panel <i>Dented</i>		\$258.20	✓
22	1	end panel top garnish <i>Delivered</i>		\$1,225.20	x
23	1	Rear spare tire panel <i>Repair</i>		\$265.30	x
24	1	Rear spare tire panel top sponge <i>new</i>		\$485.20	✓
25	1	Rear spare tire panel top cover <i>cracked</i>		\$250.00	x
26	1	Rear spare tire panel sealant <i>new</i>		\$1,310.80	✓
27	2	rear fender side inner trim <i>cracked</i>	\$655.40	\$215.30	✓
28	1	Rear windscreen seal <i>new</i>			

Subtotal :- \$13,281.50

7214.70

S.N. 200

5411.02

Labour charges

To remove & re-fix cushion

~~\$120.00~~ 60

to remove & Refix rear windscreen

~~\$120.00~~ ✓

Gum

~~\$50.00~~ ✓

to remove & Refix rear reverse sensor

~~\$120.00~~ 50

To Check Wiring System

1970 ~~\$80.00~~ 30

Tuff Kote

~~\$120.00~~ 60

Panel beating

~~\$900.00~~ 800

Spray painting

~~\$900.00~~ 800.

Subtotal :- \$2,410.00

Total :- \$15,691.50

total : 7581.02

L/S: 6K.

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: