

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20004339/AEA3Q2

**Date:** 23/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800051775

**Claimant**  
**Vehicle No :** SJL9490C **Insured Vehicle No :** SLZ6744T

Date of Loss: 18/03/2020 Nature of Claim: TP Claim No: 9096770103SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                       |             |                   |
|-----------------------------|---------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJL9490C</b>                       |             |                   |
| Make & Model:               | MAZDA 3, 1.5 HATCHBACK DELUXE EU6 (A) | Engine No:  | P520465636        |
| Reg. Date:                  | 12/10/2017 (Man. Year: 2017)          | Chassis No: | JM6BN24A8J0175739 |
| Colour:                     | Black                                 | Odometer:   | 63140 km          |
| Engine Capacity:            | 1496 cc                               |             |                   |
| Market Value/New Car Price: | N/A                                   |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>     |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 225/50 R17  | Rear Tyre Size:  | 225/50 R17  |
| Front Left Side:  | Dunlop 6 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 4,779.56          | 3,915.48          | 864.08            | 18.08         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 2,080.00          | 430.00            | 1,650.00          | 79.33         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>6,859.56</b>   | <b>4,345.48</b>   | <b>2,514.08</b>   | <b>36.65</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>3,400.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 6,859.56          | 3,400.00          | 3,459.56          | 50.43         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 480.17            | 238.00            | 242.17            | 50.43         |
| <b>Nett Amount (S\$)</b>                        | <b>7,339.73</b>   | <b>3,638.00</b>   | <b>3,701.73</b>   | <b>50.43</b>  |
| <b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b> |                   | 300.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>3,945.45</b>   |                   |               |

### INSPECTION

Date of Assignment: 20/03/2020

Date Inspected: 20/03/2020 Inspected At:

Mg Solution (HQ)  
25 Kaki Bukit Road 4 #04-01  
Singapore 41800

Estimated Period of Repair: 3.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                     | Deformed      | 1,080.00 FL | *1,080.00 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE RETAINER       | N/S Necessary | 129.00 FL   | *64.50 FL    |
| 3   | 1   |          | *FRONT BUMPER REINFORCEMENT       | Not Necessary | 630.00 FL   | *- FL        |
| 4   | 1   |          | *FRONT BUMPER REINFORCEMENT COVER | Not Necessary | 155.60 FL   | *- FL        |
| 5   | 1   |          | *FRONT BUMPER DAYLIGHT LH         | Not Necessary | 230.00 FL   | *- FL        |
| 6   | 1   |          | *FRONT BUMPER DAYLIGHT HOUSING LH | Cut           | 120.00 FL   | *120.00 FL   |
| 7   | 1   |          | *HEADLAMP (LED) LH                | Cracked       | 3,598.60 FL | *3,598.60 FL |
| 8   | 1   |          | *SET FRONT BUMPER CLIPS           | Necessary     | 25.00 FS    | *25.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>5,968.20</b> | <b>4,888.10</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 1,188.64        | 972.62          |
| <b>Total Parts (\$)</b>                                  | <b>4,779.56</b> | <b>3,915.48</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                | Lab.Type | Repairer's      | Amount        |
|--------------------------------|--|----------|-----------------|---------------|
| <u>Labour Items</u>            |  |          |                 |               |
| 1                              | PANEL BEATING ,REMOVAL AND REPLACING PARTS | New      | 1,000.00        | 200.00        |
| 2                              | TO SPRAY PAINT AFFECTED AREA               | New      | 1,000.00        | 200.00        |
| 3                              | WIRING CHECK                               | New      | 80.00           | 30.00         |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>2,080.00</b> | <b>430.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >