

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33157

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0300/2020/KK
Date : 18-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days - ok - jb -11 Jul 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Seetoh Wei-Min
Address : 48 Kismis Green
Singapore 596273
Telephone : HP +65 84483872
Type of Claim : Own Damage Claims
Policy No. : 1800082455
Vehicle No : **SKR 4845 C**
Model Code : Audi Q2 1.0 TFSI S TRONIC
Model / Year : Jul-18
Engine No : CHZ 474495
Chassis No : WAUZZZGA2JA095833
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Mar-20
Place of Accident : Holland Road (Towards Botanic Garden)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 4845 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's commendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00	\$ 500.00
3	To respray front bumper and bonnet.	\$	2,200.00	\$ 1,100.00
3a	Added labour - see attached	\$	4,200.00	\$ 2,650.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 9,752.00	\$ 4,802.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 4845 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 1,763.00	\$ 1,410.40
2	FRONT BUMPER FIXING PARTS	\$ 326.00	
3	FRONT BUMPER GRILLE - CENTER	\$ 186.00	
4	FRONT BUMPER AIR GUIDE GRILLE - LH/RH 2	\$ 318.00	
5	FRONT BUMPER END CAP - LH/RH 2	\$ 64.00	
6	FRONT BUMPER SPOILER	\$ 282.00	
7	FRONT BUMPER CLOSING ELEMENT	\$ 147.00	
8	WHEEL SPOILER - LH / RH 2	\$ 64.00	
9	RADIATOR GRILLE	\$ 1,328.00	\$ 1,062.40
10	RADIATOR GRILLE STRIKER PLATE	\$ 117.00	
11	FRONT BUMPER CARRIER	\$ 646.00	\$ 516.80
12	FRONT BUMPER FOAM FILLE RPIECE	\$ 73.00	
13	FRONT BUMPER COVER	\$ 95.00	\$ 75.36
14	CAUTION SIGN STICKER NEC	\$ 13.00	\$ 10.24
15	AIRCON STICKER NEC	\$ 7.00	\$ 5.36
16	SIGNAL HORN - RH HIGH TONE	\$ 178.00	
17	SPRING SHACKLE - RH	\$ 30.00	
18	BONNET	\$ 2,629.00	
19	BONNET ATTACHMENT PARTS	\$ 155.00	
20	BONNET IMPACT PROTECTION - CENTRE	\$ 28.00	
SUB TOTAL SPARE PARTS		\$ 8,449.00	\$ 3,080.56

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 4845 C

S/N	Parts Description	<u>Damage Parts & Prices</u>		
			S/NETT	Remarks
		C/F		\$ 3,080.56
21	BONNET IMPACT PROTECTION - LH	\$	29.00	
22	BONNET IMPACT PROTECTION - RH	\$	28.00	
23	BONNET RELEASE ELEMENT	\$	54.00	
24	BONNET BOWDEN CABLE - CENTRE	\$	54.00	
25	HEADLIGHT MOUNTING	\$	112.00	\$ 89.20
26	LED HEADLIGHT - RH	\$	4,627.00	
27	LIFT CYLINDER - RH	\$	134.00	
28	RADIATOR AIR GUIDE - LH / RH	2 \$	58.00	\$ 22.72
29	RADIATOR AIR GUIDE - UPPER CENTRE	\$	21.00	\$ 16.16
30	FRONT WHEEL COVER - LH/RH	2 \$	606.00	\$ 484.00
31	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
32	Added parts - see attached	\$	1,024.00	\$ 817.60
33	SUNDRIES	\$	300.00	\$ 9.60
TOTAL SPARE PARTS CHARGES		:	\$ 15,556.00	\$ 4,579.84
TOTAL LABOUR CHARGES		:	\$ 9,752.00	\$ 4,802.00
GRAND TOTAL		:	\$ 25,308.00	\$ 9,381.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0300/2020/KK 16-Jun-20 Glory Tan 1 OF 1 SKR 4845 C Audi Q2 1.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Lock carrier	\$ 936.00	\$ 748.80
2	Liquid coolant	\$ 88.00	\$ 68.80
			\$ 817.60
<u>Labours</u>			
1	To remove and reinstall aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	s/n 1400	\$ 1,400.00
2	To renew front lock carrier and align to position.	\$ 2,800.00	\$ 1,250.00
	TOTAL	\$ 5,224.00	\$ 3,467.60

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant