

ASS. REC. BY:

REF: CS3/AIG 20004355/RIS f30 Special Instruction:

PRS.

Surveyor: Rasu ASSIGNMENT (Office)

Minimum

From (Person): Eric Tso Wai Hong of AIG Date/Time: 21.3.2020 12.41p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 3125B Insured: SLG 8709H

at Workshop m/s TT Motorsport Tel: 8811121

of 4B Ton Guan Road East #01-103

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13.3.2020

(Client's Record) _____ 24.3.2020

CA / REV / REP. / REV 24 HRS 1/1 H.O.D. Endorsement: _____

Date/Time: 23.3.2020 1.19p.m Person Contacted: Kem Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SLB 3125 B - X
	SLG 8709 H - X
30/03/20 @ 10:27 am	

ASS. REC. BY: PRM

REF:

621E

ASSIGNMENT

PRS

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 3125B

at Workshop m/s TT MOTORSPORT

of 48, TDH LUMAN RD EAST #01-103

Insured: ALH

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 80K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 3125B Yr Regn: 2016 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA HARRIER 2.0 E.L c.c. 1986

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 6863 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZSU600065404

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R17

R: _____

PS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/03/2020

Survey held at TT MOTORSPORT

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	no G2D 8911121
	Range & no. of days - (23K - 25K) / 2 days
	RECEIVED 30 MAR 2020

Date/Time, File Pass to? 30/03/20

1) Fast

Date/Time, File Return to? _____

2) _____

Rep. Format: PRS

Lump Sum / F.B.I.: ()

: Preli. Report
 : Final Report



Days Of Repair: 20

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	<u>180</u>
Transportation:	_____
\$ + RS. SI	_____
Photos	_____
Others	<u>11</u>
TOTAL	<u>191</u>

FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG8709H AND SLB3125B ON 13/03/2020

From: Teo, Ericweihong
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Hor, Yinrul, Subramaniam, Divyashni, Abu Kassim, Noor Mariesa, Lim, Kok-Chong
Sent: Saturday, 21 March, 2020 12:41:03 AM
Attachments:  

Hi LKK,

Kindly assist on attached PRI.
Thank you.

Regards,
Eric Teo Wei Hong
AIG
Claim Adjuster II,
Singapore- Auto Express & FNOL
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.
Tel 8001206556 | Ext: 1002213
Ericweihong.Teo@aig.com | www.aig.com

From: Teo, Ericweihong
Sent: Saturday, March 21, 2020 12:32 AM
To: 'kavitha@apl.com.sg' <kavitha@apl.com.sg>
Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Teo, Ericweihong <Ericweihong.Teo@aig.com>
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG8709H AND SLB3125B ON 13/03/2020

Without Prejudice

Your Reference : AP/2020/002638
Our Reference : 9628286890SG003

Dear Sir/Madam,

We refer to your email below. We disagree with the list of your nominated surveyors.
Pursuant to Appendix C of Pre-Action Protocol for NIMA cases, citation 2.9. We will proceed to appoint our appointed surveyor for the pre-repair inspection.

Kindly provide us with details of repairer's contact number and address.

Regards,
Eric Teo Wei Hong
AIG
Claim Adjuster II,
Singapore- Auto Express & FNOL
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.
Tel 8001206556 | Ext: 1002213
Ericweihong.Teo@aig.com | www.aig.com

From: Teo, Ericweihong
Sent: Wednesday, March 18, 2020 1:20 PM
To: kavitha@apl.com.sg
Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG8709H AND SLB3125B ON 13/03/2020

Without Prejudice

Your Reference : AP/2020/002638

Our Reference : 9628286890SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,
Eric Teo Wei Hong
AIG
Claim Adjuster II,
Singapore – Auto Express & FNOL

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel 8001206556 | Ext: 1002213
Ericweihong.Teo@aig.com | www.aig.com

From: Kavitha <kavitha@apl.com.sg>
Sent: Wednesday, March 18, 2020 11:15 AM
To: ClaimsDocManagement <ClaimsDocManagement@aig.com>
Cc: Charles Hoon <charles@apl.com.sg>; Nur Ardiilah Ramli <ardiilah@apl.com.sg>; admin@ttmotorsport.sg
Subject: [EXTERNAL] Our ref: AP/2020/002638 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 13 MARCH 2020 AT ABOUT 08:30HRS INVOLVING MOTOR VEHICLES NO(S). SLB3125B AND SLG8709H AND SGG8426H AND SLM6571T ALONG MARINA COASTAL EXPRESSWAY

This message is from an external sender; be cautious with links and attachments.

Attn: Motor Claims Department

Dear Sirs,

Please find attached, our letter of even date

Please note our new office address as of 1st June 2019.

*151 Chin Swee Road,
#10-03/05 Manhattan House,*

*Singapore 169876
Tel no.: 6955 8899
Office mobile no.: 9171 4767
Fax no.: 6900 9899*

**Regards,
Kavitha
Secretary to Mr Charles Hoon**

AV Law Practice LLC

151 Chin Swee Road #10-03/05 Manhattan House, Singapore 169876

T: 6955 8899 F: 6900 9899 E: kavitha@apl.com.sg

Singapore UEN No.: 201939937D

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

AP Law Practice LLC
(UEN No. 201939937D)

151 Chin Swee Road
#10-03/05 Manhattan House
Singapore 169876

T: +65 6955 8899
F: +65 6900 9899
E: enquiry@aplp.com.sg

We do not accept service of Court documents by fax

Our ref: AP/2020/002638

POON CHOY WAN
1 Jalan Kathi
Singapore 468646

By Certificate of Posting

AIG Asia Pacific Insurance Pte Ltd
Insurer of SLG8709H
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claim Department
(your ref: to be advised)

By Post & Email:
ClaimsDocManagement@aig.com

Date: 18 March 2020

Dear Sirs,

CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 13 MARCH 2020 AT ABOUT 08:30HRS INVOLVING MOTOR VEHICLES NO(S). SLB3125B AND SLG8709H AND SGG8426H AND SLM6571T ALONG MARINA COASTAL EXPRESSWAY

We refer to the above matter.

We act for ONG MEE KONG , the owner of SLB3125B.

We are instructed by our clients to notify you of a road traffic accident on 13 MARCH 2020 at about 08:30hrs along MARINA COASTAL EXPRESSWAY involving our clients' vehicle and your vehicle bearing registration number SLG8709H . A copy of client's Singapore accident statement is enclosed.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of our clients' vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair their vehicle without further reference to you.

Please revert to us via email: kavitha@aplp.com.sg

Yours faithfully,


Charles Hoon
enc.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	621E
Vehicle Details	
Vehicle No.:	SLB3125B
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	3ZRB683999
Chassis No.:	ZSU600065404
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$27,713.00
Original Registration Date:	01 Apr 2016
First Registration Date:	01 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$25,799.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2026
PARF Rebate Amount:	\$19,349.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$27,988.00
Total Rebate Amount:	\$47,337.00

The information contained herein is correct as at 24 Mar 2020

OK

80,000
47,337

32,663



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)




Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad |
 Advertiser Login |
 Ways of Selling

2015 High Spec Vellfire! Depre @ \$15k Only!



1 Owner Low Mileage! Month End Promo! Free 1 Year Engine And GearBox Warranty!
AutoPrestige Gallery StarAd



PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.



Browse by Category |
 Save Search |
 Print |
 « Back (1 2) Next » |
 Sort by Date Posted |
 20 results/page

36 vehicles | **Search** | [Advanced Search](#) | |

|
 |
 |
 |
 |
 |
 |
 |

Search Selection	Toyota Harrier	Any	Any	2016	Any	Any	Any	Available
------------------	----------------	-----	-----	------	-----	-----	-----	-----------




Toyota Harrier 2.0A Elegance Panoramic **\$85,800** **\$11,340 /yr** **14-Jul-2016** **1,986 cc** **50,344 km** **SUV** **Available**

1 Owner, Low Mileage, Accident Free, Good Condition, Well Maintain.

★ Posted: 24-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier


DIRECT OWNER



Toyota Harrier 2.0A Premium Panoramic **\$95,800** **\$12,280 /yr** **29-Aug-2016** **1,986 cc** **61,000 km** **SUV** **Available**

One Non Smoker Previous Owner. Beautiful Original Pearl White. Vehicle In Showroom Condition. 100% Accident Free. High ARF Value. Various Loan Schemes Available To Suit Your Budget. Call For A No Obligation Discussion On Test Drive Or Financial Matters.

★ Posted: 23-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier




Toyota Harrier 2.0A Premium Panoramic **\$84,800** **\$12,070 /yr** **27-Jan-2016** **1,986 cc** **-** **SUV** **Available**

Elegant White SUV, Premium Model With Panoramic Moonroof And Electric Tailgate, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

★ Posted: 22-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier




Toyota Harrier 2.0A Elegance **\$78,800** **\$11,430 /yr** **25-Jan-2016** **1,986 cc** **43,123 km** **SUV** **Available**

1 x Retiree Owner Only, Low Interest Rate At 2.28%. No Cranky Sound Seeing Is Believing. Original Paint Work Since Day 1. Popular Harrier SUV Equipped With 2L Engine Providing Adequate Daily Power! Spacious Cabin For 5 Adults To Lounge In Comfort! Comes With...

★ Posted: 21-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier


PREMIUM AD



Lee Sheng Auto Pte Ltd - Specialist for Toyota Car repair, servicing & maintenance

Lee Sheng Motor Works is a one-stop repair centre offering vehicle servicing, repairs, accident claims and spray painting.

More info about this shop



Toyota Harrier 2.0A Premium Panoramic **\$82,888** **\$11,410 /yr** **04-Feb-2016** **1,986 cc** **60,000 km** **SUV** **Available**

Owned This Car With 95% Loan As Indicated, One Single Under Uterlise Unit, Extremely Low Mileage Clocked, Night City Driving Makes Pleasant With It's Full Panamonic Roof, World Wide Recognised SUV, Combinations Of Sporty And Luxury Art Piece, Various Financial PL...

★ Posted: 21-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier

PREMIUM AD



Toyota Harrier 2.0A Elegance Panoramic **\$85,800** **\$11,030 /yr** **14-Oct-2016** **1,986 cc** **37,586 km** **SUV** **Available**

100% Loan Available, 1 Owner, Accident Free! Well Maintained By Owner. Powerful And Smooth Transmission. Most Popular Japanese SUV In The Market. Well Kept And Spacious Interior With Exterior Decorated Features. Fuel Efficient And Perfect Car For Your Daily Usa...

taxis

★ Posted: 21-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier

|
 |
 |
 ta Harrier 2.0A Elegance **\$87,800** **\$10,570 /yr** **25-Nov-2016** **1,986 cc** **54,000 km** **SUV** **Available**



100% Loan Approval, \$950 Monthly Installment, \$11k Yearly Depreciation, New Paintwork, New Rims, Low Mileage, Excellent Maintained Condition, No Repairs Needed And Comes With 6 Months Warranty.

☆ Posted: 15-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium Panoramic | **\$88,800** | **\$11,560 /yr** | **13-Jul-2016** | **1,986 cc** | **46,890 km** | **SUV** | **Available**

We Do Immediate Transfer Of Ownership For Peace Of Mind, Low Interest Rate, Easy In House Finance Available, 1 Owner, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured! Ready For Viewing In Our Aircon Showroom Now!

Dickson Automobile

☆ Posted: 14-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium | **\$93,800** | **\$11,600 /yr** | **02-Dec-2016** | **1,986 cc** | **34,719 km** | **SUV** | **Available**

Popular Harrier SUV Equipped With 2L Engine Providing Adequate Daily Power! Spacious Cabin For 5 Adults To Lounge In Comfort! Panoramic Roof Give You A Sense Of Spaciousness In The Cabin! Large Boot Coupled With Knockdown Rear Seats Provide Ample Load...

Select By Performance Premium Selection

☆ Posted: 14-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Elegance Panoramic | **\$83,000** | **\$12,080 /yr** | **22-Jan-2016** | **1,986 cc** | **89,000 km** | **SUV** | **Available**

90% Loan Of The Car Price Available, Call For Details.

☆ Posted: 14-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium Panoramic | **\$86,800** | **\$11,040 /yr** | **10-Aug-2016** | **1,986 cc** | **58,800 km** | **SUV** | **Available**

Genuine Mileage. Internal Transfer Count. Showroom Condition. Shelter Parked. Still Under Warranty. Full Servicing Record. STA/VICOM Welcome. Highest Trade-In. Std Bank Loan, Balloon Loan, In House Loan. 100% Loan Available. Test Drive Today At Balestier Office.

☆ Posted: 12-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier



Toyota Harrier 2.0A Premium Panoramic | **\$98,800** | **\$13,130 /yr** | **27-Jul-2016** | **1,986 cc** | **68,000 km** | **SUV** | **Available**

Hurry! 1.98% Special Interest Rate, 1 Year Warranty Cover Engine And Gearbox, Can Arrange For STA Evaluation, High Trade In Up To \$2K More And Flexible Loan Available, Please Call/Whatsapp Our Sales Consultant For Viewing Appointment.

Accendore Autolution Pte Ltd

☆ Posted: 12-Mar-2020 Tags: 2016 Toyota Harrier, Toyota Harrier, Toyota, Harrier

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sport cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & insurance. Find buy used Toyota Harrier, Toyota Harrier Singapore, used Toyota Harrier Singapore, used Toyota Harrier, used vehicles Singapore or even buy used Toyota Harrier Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow **sgCarMart.com**



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2020 sgCarMart. All rights reserved.

SHORTLISTED HISTORY
Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2020 11:44
Date Of Accident	13/03/2020 08:30
Exact Location Of Accident	MCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB3125B
Insured/Policyholder	
Name Of Registered Owner	ONG MEE KONG
NRIC No	SXXXX621E
Email Address	JOYCEONGMK@LIVE.COM
Mobile Phone No	(LOCAL) +65-91856676
Alternative Phone No	OFFICE-91856676

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP309553
Cover Note Number	

Driver

Name of Driver	ONG MEE KONG
NRIC No	SXXXX621E
Date Of Birth	03/12/1965
Occupation	INDOOR
Date Of Driving Pass	07/10/1996
Driving Experience	23 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91856676
Fax Number	
Contact Number	OFFICE-91856676
Email Address	JOYCEONGMK@LIVE.COM

Address	72 CEYLON ROAD
Postcode	429655
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JEREVEN POON GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN FOR ACCIDENT DETAILS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG8709H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2


Vehicle Registration Number SLM6571T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SGG8426H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driving on 2nd lane.
Car in front Jam break.
I jam break too.
Car behind hit me from the back, push my car to
hit the car in front of me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form	X1		
CERTIFICATE NUMBER	: MP309553		
Type of Coverage	: Comprehensive	Own Damage Excess	: SGD750.00
Sum Insured	: Market Value	Windscreen Excess	: SGD100.00
1. Index Mark and Registration Number of Vehicle		SLB3125B	
Chassis Number of Vehicle		ZSU600065404	
2. Name of Policyholder	ONG, MEE KONG		
3. Effective date of the Commencement of Insurance for the purposes of the Act	01 Apr 2019		
4. Date of Expiry of Insurance	31 Mar 2020		
5. Persons or Classes of Persons entitled to drive*			
01. ONG, MEE KONG		02. N/A	
03. N/A		04. N/A	
05. N/A		06. N/A	
(b)	Any other person who is driving on the Policyholder's order or with his/her permission.		
	*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
6. Limitations as to use*	Use only for social domestic and pleasure purposes and for the Policyholder's business or profession. The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.		
	*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		
	Please note that the Own Damage Excess will be halved if claims related repairs are done at HL Assurance Approved Workshops listed in the attached.		
	This Certificate is not transferable to a new owner of the Motor Vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to HL Assurance Pte. Ltd. Within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).		
Hire Purchase Company	: MAYBANK SINGAPORE LIMITED		

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

HL ASSURANCE PTE. LTD.

Authorized Signature

Issue on: 08 Mar 2019

HL Assurance Pte. Ltd. A Member of the Hong Leong Group

11 Keppel Road, #11-01 ABI Plaza, Singapore 089057 Tel: 65 6702 0202 Fax: 65 6221 3782 UIN/GSI Regn No. 20129558W www.hlas.com.sg

20160308



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form X1

CERTIFICATE NUMBER : MP309553

Type of Coverage	: Comprehensive	Own Damage Excess	: SGD750.00
Sum Insured	: Market Value	Windscreen Excess	: SGD100.00

- | | |
|--|---------------|
| 1. Index Mark and Registration Number of Vehicle | SLB3125B |
| Chassis Number of Vehicle | ZSU600065404 |
| 2. Name of Policyholder | ONG, MEE KONG |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 01 Apr 2019 |
| 4. Date of Expiry of Insurance | 31 Mar 2020 |
| 5. Persons or Classes of Persons entitled to drive* | |
| 01. ONG, MEE KONG | 02. N/A |
| 03. N/A | 04. N/A |
| 05. N/A | 06. N/A |

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business or profession. The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Please note that the Own Damage Excess will be halved if claims related repairs are done at HL Assurance Approved Workshops listed in the attached.

This Certificate is not transferable to a new owner of the Motor Vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to HL Assurance Pte. Ltd. Within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

Hire Purchase Company : MAYBANK SINGAPORE LIMITED

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

HL ASSURANCE PTE. LTD.

Authorized Signature

Issue on: 06 Mar 2019

HL Assurance Pte. Ltd. A member of the Hong Leong Group

11 Keppel Road, #11-01 ABI Plaza, Singapore 089057 Tel: 65 6702 0202 Fax: 65 6221 3782 UEN/GST Regn No. 201229558W

www.hlas.com.sg

20160308

(6) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched (7) Deformed
 (8) Stalled (9) Backed (10) Broken (11) Necessary (12) Missing (13) Turn
 (14) Unconfirmed (15) Not Working

AS-USE ONLY
 (1) Replace (✓) (2) Repair (X) (3) Check (✓)
 (4) Not Consistent (NC)

MOTOR CAR (Frt)

Front Portion

SLB 3125B

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	bt	/	
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	de	/	
1005	992341	Frt Bumper Clips	ne	/	10
1006	991325	Frt Bumper Bracket	ne	/	2
1007	991462	Frt Bumper Side Retainer	ne	/	2
1008	991433	Frt Bumper Reinforcement	bt	/	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	cm	/	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	cut	/	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler	de	/	
1016	991438	Frt Bumper Sensor	nr	/	
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	cm	/	
1022	991328	Frt Grille Emblem	ne	/	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	R		
1026	992025	Frt Support Panel Top Garnish Cover	de	/	
1027	992416	Horn			
1028	991277	Frt Brace Panel	bt	/	
1029	995153	Frt LH Headlamp Assy	cm	/	
1030	991821	Frt RH Headlamp Assy	ca	/	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	bt	/	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	bt	/	
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber	ne	/	
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand Chrome	cm	/	
1042	990119	Air Con Condenser	bt	/	
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator	bt	/	
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992738	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery	cut	/	
1068	990224	Battery Cover			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	de	/	
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	bt	/	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	de	/	
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	bt	/	
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	de	/	
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		side garnish front	de	/	2

30/3/2020

Condition (CON)

(0)Item (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
 (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
 (12)Missing (13)Tom (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Duplicate (2) Inconsistent (3) Not Consistent (NC)

Vehicle No: **SLB 3125 B**

Rear-Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	bt	/	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	de	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	nc	/	10
1147	992976	Rear Bumper Bracket	nc	/	2
1148	993068	Rear Bumper Side Retainer	nc	/	2
1149	993045	Rear Bumper Reinforcement	bt	/	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	ca	/	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	br	/	1
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	rw	/	2
1159	993327	Rear End Panel	bt	/	
1160	993339	Rear End Panel Top Garnish	de	/	
1161	993333	Rear End Panel Inner Trim	de	/	
1162	990333	Boot Compartment Inner Trim	de	/	
1163	993851	Rear LH Taillamp	ca	/	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	ca	/	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	bt	/	
1182	991328	Tailgate Emblem	nc	/	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding	ca	/	
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	ca	/	2
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	nc	/	
1196	994607	Tailgate Glass Sealant	nc	/	
1197	994629	Tailgate Lock	bt	/	
1198	994651	Tailgate Rubber	nc	/	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

1201 994613 Tailgate inner Board de /

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	de	/	
1203	994328	Spare Tyre Panel		R	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw	ca	/	
1206	993787	Spare Tyre Cover	de	/	
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	bt	/	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member		R	
1217	993165	Rear RH Chassis Member		R	
1218	993436	Rear LH Fender		R	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	de	/	
1222	993415	Rear LH Fender Inner Garnish	de	/	
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender		R	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	de	/	
1232	993415	Rear RH Fender Inner Garnish	de	/	
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
99362	990247	Sticker			
		FRT DOOR RH		R	
		TOOL BOX TRAY	de	/	
		SPARE TYRE SPONGE	ca	/	

[Handwritten signature]
 30/3/2020

20 days

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Mar 2020 Edit Reg		21 Mar 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: POON CHOY WAN , ID: S1200379Z									
Main Claimant: ONG MEE KONG									
Vehicle Reg. No.:	SLB3125B	Date of Loss:	13/03/2020 08:00 - :59 [47 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9628286890SG	Policy/Cover Note No.:	1800017833 (Comprehensive) Coverage: 22/02/2020 - 21/02/2021						
Vehicle Reg. No. (Insured):	SLG8709H	Policy No. (Claimant):							
Excess:									
Repairer:	Tt Motorsport Pte Ltd (TT MOTORSPORT PTE LTD) 48 TOH GUAN ROAD EAST #01-103 ENTERPRISE HUB, 608586 Jurong East - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/04/2020]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG (24/03/2020): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									














































Claim Documents















































*SLB3125B (9628286890SG)
[SLG8709H]
TP
ONG MEE KONG
Mar 13 2020 8:00AM
[POON CHOY WAN]
Tt Motorsport Pte Ltd














































Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Photos/Images												
3 per page <input type="checkbox"/>												
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
2	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
3	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
4	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
5	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
6	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
7	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
8	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
9	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
10	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
11	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
12	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
13	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
14	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
15	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
16	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
17	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
18	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
19	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
20	30/03/20 11:01	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
21	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
22	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
23	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
24	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
25	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
26	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
27	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
28	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
29	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
30	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
31	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
32	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
33	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
34	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
35	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
36	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
37	30/03/20 11:05	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/03/20 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
39	30/03/20 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
40	30/03/20 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
41	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
42	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
43	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
44	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
45	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
46	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
47	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
48	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
49	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
50	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
51	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
52	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
53	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
54	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
55	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
56	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
57	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
58	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
59	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
60	30/03/20 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
61	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
62	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
63	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
64	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
65	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
66	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
67	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
68	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
69	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
70	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
71	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
72	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
73	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
74	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
75	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
76	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
77	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
78	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
79	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
80	30/03/20 11:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
81	30/03/20 11:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
82	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	30/03/20 11:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	30/03/20 11:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	30/03/20 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
147	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
150	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
151	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
152	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
153	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
154	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
155	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
156	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
157	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
158	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
159	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
160	30/03/20 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
161	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
162	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
163	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
164	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
165	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
166	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
167	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
168	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
169	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
170	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
171	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
172	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
173	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
174	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
175	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
176	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
177	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
178	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
179	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
180	30/03/20 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
181	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
182	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
183	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
184	30/03/20 11:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
185	30/03/20 11:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
186	30/03/20 11:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
187	30/03/20 11:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
189	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
190	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
191	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
192	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
193	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
194	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
195	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
196	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
197	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
198	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
199	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
200	30/03/20 11:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
201	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
202	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
203	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
204	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
205	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
206	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
207	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
208	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
209	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
210	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
211	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
212	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
213	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
214	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
215	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
216	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
217	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
218	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
219	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
220	30/03/20 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
221	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
222	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
223	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
224	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
225	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
226	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
227	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
228	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
229	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
230	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
231	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
232	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
233	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
234	30/03/20 11:55	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
235	30/03/20 11:55	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
236	30/03/20 11:55	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
237	30/03/20 11:55	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
238	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
239	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
240	30/03/20 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
241	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
242	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
243	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
244	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
245	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
246	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
247	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
248	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
249	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
250	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
251	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
252	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
253	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
254	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
255	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
256	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
257	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
258	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
259	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
260	30/03/20 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
261	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
262	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
263	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
264	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
265	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
266	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
267	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
268	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
269	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
270	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
271	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
272	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
273	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
274	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
275	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
276	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
277	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
278	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
279	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
280	30/03/20 12:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
281	30/03/20 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
282	30/03/20 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
283	30/03/20 12:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
284	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
285	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
286	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
287	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
288	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
289	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
290	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
291	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
292	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
293	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
294	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
295	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
296	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
297	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
298	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
299	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
300	30/03/20 12:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
301	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
302	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
303	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
304	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
305	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
306	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
307	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
308	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
309	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
310	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
311	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
312	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
313	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
314	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
315	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
316	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
317	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
318	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
319	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
320	30/03/20 12:21	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
321	30/03/20 12:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
322	30/03/20 12:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
323	30/03/20 12:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
324	30/03/20 12:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
325	30/03/20 12:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/03/20 12:01	TP GIA REPORT	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/03/20 09:28	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004355/R1SF3E2

Date: 31/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800017833
 Claimant Vehicle No: SLB3125B Insured Vehicle No: SLG8709H
 Date of Loss: 13/03/2020 Nature of Claim: TP Claim No: 9628286890SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB3125B**
 Make & Model: TOYOTA HARRIER, 2.0 Elegance (A) Engine No: 3ZRB683999
 Reg. Date: 01/04/2016 (Man. Year: 2015) Chassis No: ZSU600065404
 Colour: White Odometer: 68663 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/03/2020
 Date Inspected: 23/03/2020 Inspected At: Tt Motorsport Pte Ltd (TT MOTORSPORT PTE LTD)
 48 TOH GUAN ROAD EAST #01-103
 ENTERPRISE HUB
 Singapore 608586

Estimated Period of Repair: 20.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT BUMPER	Deformed	0.00 F	*- F
3	10		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*FRT BUMPER BRACKET	Necessary	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
8	1		*FRT BUMPER GRILLE	Cut	0.00 F	*- F
9	1		*FRT BUMPER LOWER SPOILER	Distorted	0.00 F	*- F
10	1		*FRT BUMPER SENSOR	Not Working	0.00 F	*- F
11	1		*FRT GRILLE	Cracked	0.00 F	*- F
12	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
13	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
14	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Deformed	0.00 F	*- F
15	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
16	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
17	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
18	1		*BONNET	Bent	0.00 F	*- F
19	1		*BONNET LOCK	Bent	0.00 F	*- F
20	1		*BONNET RUBBER	Necessary	0.00 F	*- F
21	1		*BONNET CHROME	Cracked	0.00 F	*- F
22	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
23	1		*RADIATOR	Bent	0.00 F	*- F
24	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F
25	1		*FRT LH FENDER	Bent	0.00 F	*- F
26	1		*FRT LH FENDER INNER SHIELD	Deformed	0.00 F	*- F
27	1		*FRT RH FENDER	Bent	0.00 F	*- F
28	1		*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*- F
29	2		*SIDE GARNISH FRONT	Deformed	0.00 F	*- F
30	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
31	1		*REAR BUMPER	Deformed	0.00 F	*- F
32	10		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
33	2		*REAR BUMPER BRACKET	Necessary	0.00 F	*- F
34	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
35	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
36	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
37	1		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
38	2		*REVERSE SENSOR	Not Working	0.00 F	*- F
39	1		*REAR END PANEL	Bent	0.00 F	*- F
40	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
41	1		*REAR END PANEL INNER TRIM	Deformed	0.00 F	*- F
42	1		*BOOT COMPARTMENT INNER TRIM	Deformed	0.00 F	*- F
43	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
44	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
45	1		*TAILGATE	Bent	0.00 F	*- F
46	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
47	1		*TAILGATE MOULDING	Cracked	0.00 F	*- F
48	2		*TAILGATE LAMP	Cracked	0.00 F	*- F
49	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
51	1		*TAILGATE LOCK	Bent	0.00 F	*- F
52	1		*TAILGATE RUBBER	Necessary	0.00 F	*- F
53	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*- F
54	1		*SPARE TYRE BOARD	Deformed	0.00 F	*- F
55	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
56	1		*SPARE TYRE COVER	Deformed	0.00 F	*- F
57	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
58	1		*REAR LH CHASSIS MEMBER	Repair	0.00 F	*- F
59	1		*REAR RH CHASSIS MEMBER	Repair	0.00 F	*- F
60	1		*REAR LH FENDER	Repair	0.00 F	*- F
61	1		*REAR LH FENDER INNER TRIM	Deformed	0.00 F	*- F
62	1		*REAR LH FENDER INNER GARNISH	Deformed	0.00 F	*- F
63	1		*REAR RH FENDER	Repair	0.00 F	*- F
64	1		*REAR RH FENDER INNER TRIM	Deformed	0.00 F	*- F
65	1		*REAR RH FENDER INNER GARNISH	Deformed	0.00 F	*- F
66	1		*FRT DOOR RH	Repair	0.00 F	*- F
67	1		*TOOL BOX TRAY	Deformed	0.00 F	*- F
68	1		*SPARE TYRE SPONGE	Cracked	0.00 F	*- F
69	1		*BATTERY	Cut	0.00 F	*- F
70	1		*SPARE TYRE LOCK SCREW	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >